

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Abu Kassim, Noor Mariesa

Date: 03 Sep 2021

**Preliminary Advice**

Vehicle No	: GBF635M	Accident Date	: 26/08/2021
Make	: TOYOTA HIACE	Policy No.	: 0999993603
Assignment Date	: 01/09/2021	Excess	: S\$1,000.00
Date of Inspection	: 02/09/2021	Est. Duration of Repair	: 12
Inspection At	: KIM SENG TECK MOTOR WORKS (HQ) 3021A UBI RD 1 #01-42 SINGAPORE 408715		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,678.90
Revised Amount	:S\$	8,868.90
Check Items (Estimated)	:S\$	425.00
Total	:S\$	9,293.90

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	45,000.00
COE / PARF Rebate	:S\$	14,706.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,294.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check items) stated are subject to part prices and labour cost.