

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	30 Aug 2021 13:34	Clm Veh Model Changed		[] Merimen Administrator
2	30 Aug 2021 13:34	Clm Created	Reg No: GBF635M. Policy No: 999993603. Acct Date: 2021/08/26. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP0U218U0002	[I] Merimen Administrator
3	30 Aug 2021 19:30	Clm Registration Modified	Acct Time:14:30:00->14:00:00. Pol No:999993603->0999993603.	[I] Hor, Yinrul
4	01 Sep 2021 16:46	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
5	01 Sep 2021 16:46	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
6	01 Sep 2021 16:46	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
7	01 Sep 2021 16:46	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/09/10	[A] LEE SU THING
8	01 Sep 2021 16:46	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] LEE SU THING
9	01 Sep 2021 16:46	Clm Registration Modified	Rep:1137->200188.	[A] LEE SU THING
10	01 Sep 2021 16:46	Clm Veh Model Changed	(206621) TOYOTA HIACE 1.8 D SUPER GL DARK PRIME (A).	[A] LEE SU THING
11	01 Sep 2021 16:47	Adj Adjuster Assigned	[None] -> XING GUO QIANG	[A] LEE SU THING
12	02 Sep 2021 09:50	Clm Registration Modified	Init.Est.:->5,000 - 6,000.	[I] Low, Xianyu
13	02 Sep 2021 14:47	Clm Registration Modified	Excess: -> 1000.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Abu Kassim, Noor Mariesa
14	03 Sep 2021 13:06	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
15	03 Sep 2021 13:06	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
16	03 Sep 2021 13:06	Clm Dtl Modified	JPJ Reg. Date: -> 2016/06/10.	[A] Elaine Kuan Hwa Meen
17	03 Sep 2021 13:06	Clm Details Notified		[A] Elaine Kuan Hwa Meen
18	03 Sep 2021 14:02	Ins Email Updated	[DAVPOYRAZ@GMAIL.COM] -> [KSTTEAM@SINGNET.COM.SG]	[A] Tan Hui Zhen
19	03 Sep 2021 14:06	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/09/10	[A] Tan Hui Zhen
20	03 Sep 2021 14:07	Adj Mandate Request	Cur.Reg:9293.90:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] Tan Hui Zhen
21	03 Sep 2021 18:39	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/09/10. Mandate Remarks: Authorise repair. Cost plus 10% for parts. Radiator - damage photos?. Bumper retainers 1 pc only LH, RH side not damage. Part by part repair with invoice and parts replacement photos. Item 11, 12,	[I] Koh, Victor-CK
22	03 Sep 2021 18:39	Adj Mandate Set	Approved:9293.90:Authorise repair. Cost plus 10% for parts. Radiator - damage photos?. Bumper retainers 1 pc only LH, RH side not damage. Part by part repair with invoice and parts replacement photos. Item 11, 12, 14, 15 under s/nett item.	[I] Koh, Victor-CK

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2722278	03 Sep 2021 13:06:27	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants	LKK Auto Consultants	GBF635M		11.00

				Pte Ltd	Pte Ltd (HQ)			
--	--	--	--	---------	--------------	--	--	--