

PANG SCOOTER SERVICE

Bik 1006 Bukit Merah Lane 2 #01-06 Singapore 159762
 Tel : 6271 4618 Fax : 6273 2632

ESTIMATE REPAIR

BIKE NO.: JPK 3064

DOA: 24/02/2021

MAKE/MODEL: YAMAHA LC135

S/No	DESCRIPTION	AMOUNT
1	HEADLIGHT ASSY LKK Auto Consultants hence notify	\$185.00
2	METER ASSY the Repairer of the following:	\$320.00
3	SIGNAL LIGHT ASSY • To resurvey before/after spray painting	\$165.00
4	HANDLER BAR • To display damaged part(s) during resurvey	\$98.00
5	HANDLER BRACKET • Parts prices are subject to confirmation	\$85.00
6	COWLING STAY • Third party survey is on a "Without Prejudice" basis	\$65.00
7	STEERING CON • No illegal modification(s) is allowed	\$110.00
8	UNDLER BRACKET • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	\$195.00
9	FORK ASSY X 2 Acknowledged by Repairer	\$380.00
10	FRONT FENDER Signature:	\$85.00
11	FRONT WHEEL SHAFT Date:	\$45.00
12	FRONT WHEEL RIM	\$398.00
13	FRONT BRAKE DISC	\$185.00
14	FRONT HANDLER COVER UPPER	\$95.00
15	REAR HANDLER COVER UPPER	\$85.00
16	TOP FRONT PANEL	\$195.00
17	PANEL COVER	\$110.00
18	PANEL INNER (1)	\$80.00
19	MIRROR	\$45.00
20	BRAKE LEVER	\$110.00
21	METER GEAR METER GLASS	\$85.00
22	L/H LEG SHIELD	\$185.00
23	R/H LEG SHIELD	\$185.00
24	L/H FRONT BODY LOWER	\$45.00
25	R/H FRONT BODY LOWER	\$45.00
26	L/H AIR GUIDE	\$25.00
27	R/H AIR GUIDE	\$25.00
28	PRESS BODY \$780	\$450.00
29	RADIATOR	\$380.00
30	COOLANT	\$35.00
31	TOW	\$80.00
32	LABOUR	\$500.00
33	→ WIND SHIELD \$68	\$68
	→ REAR BOX \$580	\$580
	→ FRONT BOX RACK \$180	\$180
	→ Exhaust Assy \$495	\$495
	Total:	\$5,656.00

5369
 4832.10
 780

 45612.10
 7 days

mis ✓
 crn ✓
 crn ✓
 bt ✓
 bt ✓
 jt ✓
 ne ✓
 bt ✓
 bt ✓
 crn ✓
 bt ✓
 bt ✓
 us ✓
 de ✓
 acb ✓
 de ✓
 de ✓
 mis ✓
 bt ✓
 us ✓
 us ✓
 de ✓
 de ✓
 de ✓
 400 SN
 bt ✓
 ne ✓
 ✓ SN
 300 SN

→ WIND SHIELD ~~\$68~~ mis ✓
 → REAR BOX ~~\$580~~ mis ✓
 → FRONT BOX RACK ~~\$180~~ bt ✓
 → Exhaust Assy ~~\$495~~ bt ✓