



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



CITROËN

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
UNITED OVERSEAS INSURANCE LTD 3 Anson Road #28-01 Springleaf Tower Singapore 079909	Cust No/Name /Ec Tech Engineering Pte. Ltd. Reg No/Reg Date GBL2255G*AD / 24/02/2021 Date In/Mileage 26/08/2021/ 16349 Chassis No VR7EFYHZRLJ959139 Engine No 10Q4DR0027739 Make/Model CITCV/K9 BERLINGO L2 1.5 BLUEHDI 13 Colour/Trim VLM / GY
Contact No	

Hui Zher
\$3870

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000057	Credit	27/08/2021/ 15:45	DS	218 / Mars Ler	17650			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	SUNDRY							30 50.00
	COMPANY STICKER	neu						+ 300.00
S	MIPNT88088							✓ 250.00
	LALAMOVE STICKER	Not insured						320 1280.00
	-TBA							x 1280.00
S	MIPNT88088							1600 3840.00
	DIAGNOSTIC / SCANNING							
S	MIPNT88088							
	TO TRANSFER DOOR AND RHF SLIDING DOOR MECHANISM AND COMPONENT PARTS							
S	MIPNT88088							
	TO REMOVE AND RE-INSTALL TRIMMING AND CAPERTING TO GIVE							
	WAY FACILATATE RENEWEL RHR OUTER QUARTER PANEL							
S	MIPNT88088							
	TO REPLACE RHF DOOR PANEL, RHS SLIDING DOOR PANEL, ETC							
	-TO CUT & RE-WELD RHR OUTER QUARTER PANEL							
	- TO REPAIR RHS SIDE SILL							
	STRAIGHTEN, REFORM, ALIGN ON RHS ACCIDENT AFFECTED AREAS							100 300.00
S	MIPNT88088							165 2750.00
	TO APPLY SEALANT KIT ON NEW PANEL							
S	MIPNT98088							✓ 1462.00
	SPRAY PAINTING ON RH SIDE ACCIDENT AFFECTED AREAS							+ 93.00
M	C9820423180	RHF DOOR PANEL ASSY	vented		1.00	1462.00	0.00	+ 79.00
M	C9817683180	RH DOOR WEATHERSTRIP	3mm		1.00	93.00	0.00	✓ 336.00
M	C9820661280	RH DOOR WEATHERSTRIP			1.00	79.00	0.00	✓ 10.00
M	C98176962XT	RHF PROTECTOR PANEL	cut		1.00	336.00	0.00	+ 1590.00
M	C9819277380	RHF DOOR ADHESIVE TA	neu		1.00	10.00	0.00	x 98.00
M	C9820425580	RH SLINDING SIDE DOO	neu		1.00	1590.00	0.00	✓ 112.00
M	C9832997080	RH SIDE SILL SEAL	neu		1.00	98.00	0.00	+ 1747.00
M	C98176951XT	RH SLIDE DOOR PROTEC	cut		1.00	112.00	0.00	
M	C9827669480	RIGHT REAR WING	Repair		1.00	1747.00	0.00	
Z	NOTES							
	ACCIDENT ON 13/08/2021 ALONG PAYA LEBAR RD							
	OWNER CLAIMING THIRD PARTY							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



CITROËN

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
UNITED OVERSEAS INSURANCE LTD 3 Anson Road #28-01 Springleaf Tower Singapore 079909	Cust No/Name /Ec Tech Engineering Pte. Ltd. Reg No/Reg Date GBL2255G*AD / 24/02/2021 Date In/Mileage 26/08/2021/ 16349 Chassis No VR7EFYHZRLJ959139 Engine No 10Q4DR0027739 Make/Model CITCV/K9 BERLINGO L2 1.5 BLUEHDI 13 Colour/Trim VLM / GY
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000057	Credit	27/08/2021/ 15:45	DS	218 / Mars Ler	17650
Description of Goods / Services	Qty	Unit Price	Disc%	Amount	

REQUIRED REPLACEMENT VEHICLE
TP # SFR3218D TP INS : AXA

Estimate

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lij
P/P 02/09/21

OSPays
Excess \$500
Not Refunded

Confirm & accepted by

Parts	5,527.00
Labour	0.00
Standard Menu	0.00
Specialist Job	10,000.00
Others(Lub,etc)	0.00
Sundry	50.00
Total(w/o GST)	15,577.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.