

REPAIR PERFORMANCE INVOICE

Vehicle number	EZ2525T
Make / Model	VOLVO S90
Chassis number	LVYP510ADLP079893
Accident date	30/8/21
Reference	2108-24

ALLIED WORLD

5 Days.
Unjam repair
After repair photos.
Gano Qian
02/9/2021

Qty	Particulars	Unit Price - SGD \$
PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER	2942.50
2	REAR BUMPER PDC SENSOR	363.00
1	REAR BUMPER TOW COVER	68.20
1	REAR BUMPER RE-IN-FORCEMENT	1133.00
1	REAR END PANEL	1199.00
1	REAR END PANEL TOP GARNISH	167.20
1	REAR BUMPER RETAINER	49.50
2	REAR BUMPER LOWER GARNISH	539.00
1	REAR BOOTLID	2898.50
1	REAR BOOTLID WEATHERSTRIP	451.00
1	REAR BOOTLID LOCK	269.50
1	REAR BOOTLID "AUTO CLOSE" MODULE	1226.50
1	REAR BOOTLID LOCK STRIKER	27.50
2	REAR BOOTLID HINGE	250.80
1	REAR BOOTLID LAMP LH	212.30
1	REAR BOOTLID LAMP RH	212.30
1	REAR BOOTLID VOLVO EMBLEM	74.80
1	REAR BOOTLID T5 EMBLEM	66.00
1	REAR EXHAUST SILENCER	1067.00
2	REAR EXHAUST TIPS	253.00
2	REAR EXHAUST MOUNTING	35.20
		13505.80
	Less 20%	2701.16
		10804.46
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1	REVERSE CAMERA	500.00
1 SET	REAR BUMPER CLIP	50.00
2	REAR AFTERMARKET TAIL LAMP	4000.00
1 SET	END PANEL TOP GARNISH CLIP	50.00
1	REAR NUMBER PLATE (3D)	180.00
	Subtotal	4720.00
LABOUR AND MISCELLANEOUS CHARGES		
	Balance B/F	15524.64
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00
2	REMOVE, REPLACE AND REFIT PDC SENSOR	150.00
3	LABOUR FOR RESET OF (AUTO CLOSE MODULE)	200.00
4	REMOVE, REPLACE AND REFIT REVERSE CAMERA	250.00
5	REMOVE, REPLACE AND REFIT BOOTLID	200.00
6	REMOVE, REPLACE AND REFIT TRIMS AND GARNISHES	200.00
7	PANEL BEATING ON AFFECTED AREAS	1500.00
8	SPRAY PAINTING ON AFFECTED AREAS	1500.00
9	APPLY ANTI RUST ON AFFECTED AREAS	150.00
	Subtotal	4210.00
	Grand total	19734.64