



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2302440

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 18/04/2023
Reference CC6/CTI21009214/Kya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMG 53G
Insured Veh. YQ 486X
Claim No. SNM21D204885/C02
Policy No. DMCVSNW00038312101
Accident Date 27/08/2021
Inspection Date 31/08/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21009214/Kya3q2 Date: 18/04/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YQ 486X	Veh. Inspected	SMG 53G	
Policy No.	DMCVSNW00038312101	Coverage (\$)	0.00	
Claim No.	SNM21D204885/C02	Excess (\$)	0.00	
Assign From		Assign Date	31/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	PORSCHE CAYENNE (A)	c.c	3598	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	WP1ZZZ9PZ8LA27607	Colour	MATT GREY	
Odometer	63559 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/35 R21	MICHELIN	9 mm	
L/H Front Tyre	295/35 R21	MICHELIN	9 mm	
R/H Rear Tyre	295/35 R21	MICHELIN	9 mm	
L/H Rear Tyre	295/35 R21	MICHELIN	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/08/2021	Inspection Date	31/08/2021	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 53G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BUCKLED	1,920.00	1,920.00
1	REAR BUMPER (LOWER)	DENTED / DISTORTED	1,780.00	1,780.00
1	REAR BUMPER LOWER LIP	CRACKED	1,100.00	1,100.00
1	CHROME PROTECTOR	DENTED	680.00	680.00
1	REAR BUMPER REINFORCEMENT	BUCKLED	1,550.00	1,440.00
1	REAR BUMPER INNER PARTS	CRACKED	180.00	180.00
1	REAR BUMPER INNER SPONGE	CRACKED	220.00	220.00
2	TOWING COVER @\$125.00	MTG DISTORTED	250.00	250.00
2	EXHAUST CHROME COVER @\$295.00	N/S DENTED	590.00	295.00
6	REVERSE SENSOR @\$390.00	CRACKED / SHORTED	2,340.00	780.00
1	TAILGATE	BENT	4,240.00	4,240.00
1	REAR W/S MOULDING	NECESSARY	740.00	740.00
1	"CAYENNE" EMBLEM	NECESSARY	220.00	220.00
	LESS 10% DISCOUNT		-1,581.00	-1,384.50
			14,229.00	12,460.50
<u>SPECIAL NETT ITEMS</u>				
1	REAR W/S GLASS SEALANT (SN)	NECESSARY	100.00	40.00
1	REAR NUMBER PLATE WITH BOX (SN)	SERVICEABLE	50.00	-
			150.00	40.00
<u>LABOUR</u>				
	TO REMOVE & RENEW REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		150.00	120.00
	TO REMOVE ROOF LINING,FRONT AND REAR SEATS,TRIM BOARD AND CARPET.	NOT NECESSARY	180.00	-
	TO PUTTY AND SPRAY REPLACED PARTS.		700.00	560.00
	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS.		800.00	500.00

Report Ref No. CC6/CTI21009214/Kya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO WRAP TAILGATE AND REAR BUMPER.		1,200.00	1,200.00
			3,030.00	2,380.00
GRAND TOTAL			17,409.00	14,880.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,900.00

Report Ref No. CC6/CTI21009214/Kya3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 53G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 53G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 53G

RE-INSPECTION

