

ASS. REC. BY:

REF:

072 / 210092141ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

12pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. 07/28 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMG 53G Yr Regn: 07 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Porsche Cayenne c.c 3598Colour: Mat Grey A/C: Insured / Std / NI / NASp. Reading: 63558 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WP12229P782A27607Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 2P5/35R 21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 27/8/21 D.O.I. 31/8/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/10/21, 8:11, 900 Cash

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation: _____ \$ + RS. _____ \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : YQ486X
Accident Date : 27-Aug-2021

Our Ref : 021122 (CHINA) / SHIJIE

MANJIT SINGH GILL
11 LEEDON HEIGHTS
#22-31
Singapore 267955

No. : 06439

Date : 30-Aug-2021

PAGE : 1

*Not Authorized
11,900/-
Returning After Pain*

ESTIMATED COST OF REPAIR FOR PORSCHE CAYENNE SMG53G

=====

1 pc	Rear bumper	Bu	1,920.00	—
1 pc	Rear bumper (lower)	nd / dit	1,780.00	—
1 pc	Rear bumper lower lip	cm	1,100.00	✓
1 pc	Chrome protector	nd	680.00	—
1 pc	Rear bumper reinforcement 1440	Bu	1,550.00	✓
1 pc	Rear bumper inner parts	cm	180.00	✓
1 pc	Rear bumper inner sponge	cm	220.00	✓
2 pcs	Towing cover	nd	250.00	✓
2 pcs	Exhaust chrome cover	n/s nd	590.00	✓
2 & 6 pcs	Reverse sensor	cm / shom	2,340.00	✓
1 pc	Tailgate	nd	4,240.00	—
1 pc	Rear w/s moulding	nd	740.00	—
1 pc	"Cayenne" emblem	nd	220.00	—

15,810.00

Less 10% : 1,581.00

1 pc Rear w/s glass sealant
1 pc Rear number plate with box

14,229.00 40sn
nd 100.00 sn
nd 50.00 sn X

To remove & renew rear windscreen
glass and conduct water leak test.

150.00 1201

To remove roof lining, front and
rear seats, trim board and carpet

nd 180.00 X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Con't Page 2 ...

Acknowledged by Repairer

Signature:

Date:

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : YQ486X

Page : 2

To putty and spray replaced parts

700.00

560/

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

800.00

500/

To wrap tailgate and rear bumper

(Bill) 1,200.00

✓

Total : S\$17,409.00

=====

Singapore Dollars Seventeen Thousand Four Hundred
and Nine Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey damaged parts during resurvey
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: