

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : YQ486X
Accident Date : 27-Aug-2021

Our Ref : 021122 (CHINA) / SHIJIE

MANJIT SINGH GILL
11 LEEDON HEIGHTS
#22-31
Singapore 267955

No. : 06439

Date : 30-Aug-2021

PAGE : 1

*Not Authorized
11 Days &
Returning After Pain*

ESTIMATED COST OF REPAIR FOR PORSCHE CAYENNE SMG53G

5 days

1 pc	Rear bumper		<i>Bu</i>	1,920.00	—
1 pc	Rear bumper (lower)		<i>nd/dit</i>	1,780.00	—
1 pc	Rear bumper lower lip			1,100.00	?
1 pc	Chrome protector		<i>nd</i>	680.00	—
1 pc	Rear bumper reinforcement			1,550.00	?
1 pc	Rear bumper inner parts			180.00	?
1 pc	Rear bumper inner sponge			220.00	?
2 pcs	Towing cover	@ S\$125.00	<i>in</i>	250.00	x
2 pcs	Exhaust chrome cover	<i>n/s nd</i> @ S\$295.00		590.00	lt
2 & pcs	Reverse sensor	@ S\$390.00		2,340.00	?
1 pc	Tailgate		<i>in</i>	4,240.00	—
1 pc	Rear w/s moulding		<i>in</i>	740.00	—
1 pc	"Cayenne" emblem		<i>in</i>	220.00	—
				15,810.00	
Less 10% :				1,581.00	

1 pc Rear w/s glass sealant
1 pc Rear number plate with box

*14,229.00 40sn
100.00 sn
50.00 sn x*

To remove & renew rear windscreen
glass and conduct water leak test.

150.00 12cl

To remove roof lining, front and
rear seats, trim board and carpet

180.00 ?

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Con't Page 2 ...

Acknowledged by Repairer

Signature:

Date:

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : YQ486X

Page : 2

To putty and spray replaced parts

700.00

500/

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

800.00

500/

To wrap tailgate and rear bumper

(Bill) 1,200.00 ?

Total : S\$17,409.00
=====

Singapore Dollars Seventeen Thousand Four Hundred
and Nine Only

JKK Auto Consultants hence notify
the Reparer of the following:

- To remove damaged parts during survey
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is not a "Warranted Price"
- No illegal modifications are allowed
- Supplemental items must be reviewed and
is subject to final approval from Insurance Company

Acknowledged by Reparer
Signature
Date