

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

Insured by : **AIG Asia Pacific Insurance Pte Ltd**
78, Shenton Way, #11-16,
Singapore 079120

Estimate bill : TT 35 / 21 / TP / WT

Insured by : **Motor Claims Department**
Tel : 6419 3000
Fax : 6225 6772

Registration No : SJA8572P
Make model : MB E200 (211)

Fileage : Date : 16 / 09 / 2021

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : GBK3458L AND SJA8572P
LONG ANG MO KIO AVENUE 1 ON 30 AUGUST 2021 AT ABOUT 1040HRS.**

c	Front bumper	1280	\$	mycm	1,349.00	✓
cs	Front bumper chrome moulding	(Each \$162.00)	\$	me	324.00	✓
c	Front license plate garnish		\$	pu	311.00	✓
cs	Front bumper side bracket	(Each \$81.00)	\$	pu	162.00	✓
c	Front bumper sponge (Centre)		\$	pu	108.00	✓
c	Front bumper sponge (Side)	(Each \$81.00)	\$	pu	162.00	✓
c	Front bumper frame (Centre)		\$	pu	54.00	✓
cs	Front bumper frame (Side)	(Each \$81.00)	\$	cm	162.00	✓
cs	Front seat head rest	(Each \$1,198.00)	\$	pu	2,396.00	✓
	Sub A total :		\$		5,028.00	
	Less 10% discount :		\$		502.80	
	A total :		\$		4,525.20	

Special net items :

Front license smart plate
Front license smart platw casing
B total :

\$ 35.00
\$ 35.00

Remove and transfer front bumper necessary attachment spart part items.

Remove and refit front bumper, front bumper chrome mouldings, front license plate garnish, front bumper side brackets, front bumper sponge (Centre), front bumper sponges (Side), front bumper frame (Centre), front bumper frames (Side).

\$ 400.00

Total amount for Page 1:

\$ 4,960.20

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:
Page 1 of 5

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

AIG Asia Pacific Insurance Pte Ltd

78, Shenton Way, #11-16,
Singapore 079120

Estimate bill : TT 35 / 21 / TP / WT

Registration No : SJA8572P

Motor Claims Department

6419 3000
6225 6772

Make model : MB E200 (211)

e :

Date : 16 / 09 / 2021

**TRUCK ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : GBK3458L AND SJA8572P
AT ANG MO KIO AVENUE 1 ON 30 AUGUST 2021 AT ABOUT 1040HRS.**

Remove and refit front head lamps. <i>rm</i>	\$	<i>100/</i> 200.00	<i>2ed</i>
To check & refit front head lamp wiring harness.	\$	<i>na</i> 120.00	<i>X</i>
Tuff kote front damaged portion.	\$	<i>na</i> 150.00	<i>X</i>
Putty / primer application, spray painting front bumper, front bumper license plate garnish, .	\$	400.00	<i>2401</i>
Total amount for Page : 2	\$	870.00	

Tropical Tech Automobile Services


(Authorised Signature)
William Tan



Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

AIG Asia Pacific Insurance Pte Ltd
78, Shenton Way, #11-16,
Singapore 079120

Estimate bill : TT 35 / 21 / TP / WT

Registration No : SJA8572P

Attn : **Motor Claims Department**
Tel : 6419 3000
Fax : 6225 6772

Make model : MB E200 (211)

Mileage :

Date : 16 / 09 / 2021

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : GBK3458L AND SJA8572P
ALONG ANG MO KIO AVENUE 1 ON 30 AUGUST 2021 AT ABOUT 1040HRS.**

1pc	Rear boot		\$	R	1,899.00	✓
1pc	Rear boot 3rd brake lamp		\$	CM	373.00	✓
1pc	Rear boot emblem		\$	na	49.00	—
3pcs	Rear boot emblem grommet	(Each \$6.00)	\$	na	18.00	—
1pc	Rear boot 'E200' designation		\$	na	119.00	—
1pc	Rear boot 'Kompressor' designation		\$	na	168.00	✓
1pc	Rear boot lock		\$	na	446.00	✓
2pcs	Rear tail lamp	(Each \$540.00)	\$	SM	1,080.00	X
8pcs	Rear tail lamp garnish clip	(Each \$9.00)	\$	na	72.00	X
1pc	Rear bumper	1680	\$	BU 1CM	1,808.00	✓
1pc	Rear bumper chrome moulding (Centre)	185	\$	na	284.00	—
2pcs	Rear bumper chrome moulding (Side)	e 150	\$	na	410.00	—
1set	Rear bumper parktronic sensor kit		\$	na	280.00	✓
2pcs	Rear bumper lower bracket	(Each \$30.00)	\$	CM	60.00	✓
2pcs	Rear bumper side bracket	(Each \$135.00)	\$	na	270.00	X
1pc	Rear bumper frame (Centre)	280	\$	CM	351.00	✓
1pc	Rear bumper reinforcement	582	\$	na	769.00	✓
1pc	Rear tail pipe bracket		\$	na	95.00	X
Sub total :			\$		8,551.00	
Less 10% discount:			\$		855.10	
C total :			\$		7,695.90	
Total amount of Page 3 :			\$		7,695.90	

Tropical Tech Automobile Services


(Authorised Signature)
William Tan



Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

AIG Asia Pacific Insurance Pte Ltd

78, Shenton Way, #11-16,
Singapore 079120

Estimate blll : TT 35 / 21 / TP / WT

Registration No : SJA8572P

Make model : MB E200 (211)

Attn : **Motor Claims Department**

Tel : 6419 3000

Fax : 6225 6772

Mileage :

Date : 16 / 09 / 2021

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : GBK3458L AND SJA8572P
ALONG ANG MO KIO AVENUE 1 ON 30 AUGUST 2021 AT ABOUT 1040HRS.**

Special net items :

1pc	Rear license smart plate	
1pc	Rear license smart platw casing	
	B total :	\$ 35.00 X
		\$ 35.00

Remove and transfer rear boot necessary attachment spare part items.

Remove and transfer rear bumper necessary attachment spare part items.

Remove & refit rear boot, rear boot 3rd brake lamp, rear boot lock, rear tail lamps,
rear tail lamp garnish clip, rear bumper, rear bumper chrome moulding (Centre),
rear bumper chrome mouldings (Side), rear bumper parktronic sensor kits, rear
bumper lower brackets, rear bumper side brackets, rear bumper frame (Centre), rear
bumper reinforcement, rear tail pipe bracket.

Panel / beating rear end panel, heat / weld / beating / pull / straighten / align rear
chassis frame by Chassis Alignment Jack.

Under coating on rear damaged portion.

Putty / primer application, spray painting rear boot, rear boot license plate garnish,
rear end panel, rear bumper, rear bumper parktronic sensors.

Total amount of Page 4 :

\$	800.00	4001
\$	300.00	X
\$	1,000.00	4801
\$	2,135.00	

Tropical Tech Automobile Services


(Authorised Signature)
William Tan



Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M / s : **AIG Asia Pacific Insurance Pte Ltd**
78, Shenton Way, #11-16,
Singapore 079120

Supplementary bill : TT 35 / 21 / TP / WT

Registration No : SJA8572P

Attn : **Motor Claims Department**
Tel : 6419 3000
Fax : 6225 6772

Make model : MB E200 (211)

Mileage :

Date : 20 / 09 / 2021

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : GBK3458L AND SJA8572P
ALONG ANG MO KIO AVENUE 1 ON 30 AUGUST 2021 AT ABOUT 1040HRS.**

1pc	Front LH head lamp	\$	<i>mycm</i> 540.00	✓
1pc	Radiator	\$	<i>sn</i> 1,079.00	X
	Sub A total :	\$	1,619.00	
	Less 10% discount :	\$	161.90	
	A total :	\$	1,457.10	
Special net items :				
1bte	MB coolant	\$	<i>nn</i> 27.00	X
	B total :	\$	27.00	
Total amount for Page 1:		\$	1,484.10	

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

AIG Asia Pacific Insurance Pte Ltd

78, Shenton Way, #11-16,
Singapore 079120

Supplementary bill : TT 35 / 21 / TP / WT

Registration No : SJA8572P

Motor Claims Department

6419 3000
6225 6772

Make model : MB E200 (211)

e :

Date : 20 / 09 / 2021

**FIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : GBK3458L AND SJA8572P
G ANG MO KIO AVENUE 1 ON 30 AUGUST 2021 AT ABOUT 1040HRS.**

Rear tail lamp garnish (RH)	\$	CM 52.00	✓
Rear bumper towing cover	\$	Re 108.00	X
Sub total :	\$	160.00	
Less 10% discount:	\$	16.00	
C total :	\$	144.00	
Balance brought forward from Page 1 :	\$	1,484.10	
Grand final amount :	\$	<u>1,628.10</u>	

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

