

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SBU 1001 G**
 Model : Toyota Altis
 Year : 2015
 Chassis No : MR053REH104545390

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bootlid	1	\$ 1,093.00	\$ 781.10 1,093.00
2	Bootlid logo	1	\$ 85.50	\$ 68.00 85.50
3	Bootlid emblem 'COROLLA'	1	\$ 68.00	\$ 32.00 68.00
4	Bootlid emblem 'ALTIS'	1	\$ 65.37	\$ 55.00 65.37
5	Bootlid outer chrome garnish	1	\$ 415.60	\$ 202.50 415.60
6	Bootlid lamp LH BR, RH CUT	2	\$ 328.00 485.30	\$ 656.00 970.60
7	Bootlid inner lock	1	\$ 298.70	\$ 298.70
8	Bootlid inner lock striker	1	\$ 65.00	\$ 65.00
9	Bootlid inner trim board	1	\$ 352.80	\$ 352.80
10	Bootlid weatherstrip	1	\$ 298.60	\$ 298.60
11	Bootlid antenna sensor	1	\$ 218.40	\$ 218.40
12	Rear bumper	1	\$ 885.90	\$ 639.80 885.90
13	Rear bumper side retainer	2	\$ 65.00 110.20	\$ 130.00 236.40
14	Rear bumper inner sponge	1	\$ 141.80	\$ 141.80
15	Rear bumper reinforcement	1	\$ 487.30	\$ 398.70 487.30
16	Rear bumper side bracket	2	\$ 85.60	\$ 171.20
17	Rear bumper reflector	2	\$ 93.60	\$ 187.20
18	Rear end panel	1	\$ 762.10	\$ 645.30 762.10
19	Rear end panel top garnish	1	\$ 268.00	\$ 185.99 268.00
20	Rear fender inner trim board	2	\$ 458.00	\$ 916.00
21	Taillamp RH 1	2	\$ 411.00 594.60	\$ 411.00 1,189.20
22	Taillamp lower bracket RH 1	2	\$ 82.00	\$ 82.00 164.00
Parts Sub Total :				\$ 4292.29 9,340.67
25% Discount :				\$ 1073.07 2,335.17
PARTS TOTAL :				\$ 3219.22 7,005.50

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Bootlid sealant	1	\$ 100.00	\$ 100.00 40.00
3	Bootlid outer chrome garnish clips	1	\$ 50.00	\$ 50.00 20.00
4	Bootlid lamp seal	2	\$ 60.00	\$ 120.00 60.00
5	Bootlid lamp clips	2	\$ 50.00	\$ 100.00 20.00
6	Bootlid inner trim board clips	1	\$ 50.00	\$ 50.00
7	Rear bumper clips	1	\$ 50.00	\$ 50.00 30.00
8	Rear bumper reverse sensor	2	\$ 250.00	\$ 500.00 200.00
9	Rear end panel sealant	1	\$ 100.00	\$ 100.00 40.00
10	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00 30.00
11	Rear fender inner trim board clips	2	\$ 50.00	\$ 100.00
12	Taillamp seal RH	2	\$ 60.00	\$ 120.00 30.00
13	Taillamp clips	1 2	\$ 50.00	\$ 100.00 20.00
SPECIAL NETT TOTAL :				\$ 1,520.00

490.00

Nos.	LABOUR	S\$
1	R&R bootlid component	\$ 150.00 80.00
2	R&R rear bumper reverse sensor	\$ 100.00 60.00
3	Diagnostic & reset fault code	\$ 300.00
4	Upholstery	\$ 300.00
5	Check wiring	\$ 100.00 50.00
6	Panel beating	\$ 1,400.00 800.00
7	Rust proofing	\$ 200.00
8	Spray painting	\$ 1,400.00 600.00
LABOUR TOTAL :		\$ 3,950.00

Survey 1/9/2021 1130hrs
 Re survey 1/9/2021 1145 hrs
 Lump sum repair
 Repair Days 6
 Train
 Train

PARTS TOTAL : \$ 7,005.50
 SPECIAL NETT TOTAL : \$ 1,520.00
 LABOUR TOTAL : \$ 3,950.00
 GRAND TOTAL : \$ 12,475.50

Parts 3219.22
 SN 490.00
 Labour 1590.00
 5299.22
 @ 20% 1059.84
 4239.37

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LS 4200/v Train
 27/9/2021