

1 KAKI BUKIT AVE 6 #02-56

SINGAPORE 417883

TEL : 96273323 FAX 68442641

CO.REG NO: 53049097-L

KURUBALAN S/O MANICKAM RENGARAJU

DATE : 04/10/2021

BLK 15, FARRER PARK ROAD, #08-37

SINGAPORE 210015

TP Msia (Independent)

Xiao Chen

ACCIDENT DATE : 19/08/2021

MODEL : NISSAN SUNNY 1.6 EX (A)

CHASSIS NO : JN1CFAN16Z0101683

ESIMATE COST OF REPAIR BILL TO NISSAN CAR NO : SGJS1166

1 PC REAR BOOTLID	Distorted	S\$655.80	Nett ✓
1 PC REAR BOOTLID CHROME HANDLE	crackd	331.20	NETT ✓
5 PC REAR BOOTLID EMBLEM	new	238.00	NETT ✓
1 PC REAR BOOTLID LOWER CHROME MOULDING	ut	187.00	NETT ✓
2 PC REAR BOOTLID HINGE	Bent	196.40	NETT ✓
1 PC REAR BOOTLID TRIMBOARD	Deformed.	365.50	Nett ✓
1 PC REAR BOOTLID LOCK	Damaged	68.70	NETT ✓
1 PC REAR BOOTLID RUBBER	ut	68.50	NETT ✓
2 PC REAR BOOTLID HINGE SPRING	He m	196.40	NETT x.
1 PC REAR BOOTLID OUTER LOCK	Tamed	126.80	NETT ✓
2 PC REAR TAILLAMP	Smashed	435.60	NETT ✓
2 PC REAR TAILLAMP BRACKET	crackd	68.60	NETT ✓
2 PC REAR TAILLAMP INNER PANEL	Dented	216.80	NETT ✓
1 PC REAR END PANEL	Distorted	455.80	Nett ✓
1 PC REAR END PANEL TOP GARNISH	Deformed	123.70	NETT ✓
1 PC REAR END PANEL LOWER GARNISH	to m	65.50	NETT ✓
1 PC REAR SPARE WHEEL PANEL	Reps	676.20	Nett x.

TK MOTOR WORKSHOP
1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL : 96273323 FAX 68442641
CO.REG NO: 53049097-L

ESTIMATE COST OF REPAIR BILL TO NISSAN CAR NO : SGJ5116G

1 PC REAR SPARE WHEEL TOP COVER GARNISH <i>torn</i>	S\$636.90 <i>Nett</i> ✓
2 PC REAR FENDER INNER TRIM BOARD <i>torn</i>	572.20 NETT ✓
4 PC REAR END PANEL GARNISH CLIP <i>new</i>	15.20 S/NETT ✓
1 PC REAR END PANEL LOCK <i>new</i>	56.80 NETT X
1 PC REAR BUMPER <i>Distorted</i>	541.80 <i>Nett</i> ✓
2 PC REAR BUMPER BRACKET <i>Distorted</i>	173.60 <i>Nett</i> ✓
1 PC REAR BUMPER CHROME MOULDING <i>Distorted</i>	168.80 NETT ✓
8 PC REAR BUMPER CLIP <i>new</i>	28.00 S/ NETT ✓
2 PC REAR BUMPER SIDE RETAINER <i>Distorted</i>	66.40 NETT ✓
1 SET REVERSE SENSOR <i>Distorted</i>	200.00 S/NETT ✓
2 PC REAR BUMPER SIDECLIP <i>new</i>	25.60 S/NETT ✓
1 PC REAR BUMPER SPONGE <i>Cracked</i>	233.80 NETT ✓ <i>133.80 (Nett)</i>
2 PC REAR FENDER <i>LH Reps, RH Buckled</i>	1,789.60 <i>894.80 Nett</i>
1 PC PETROL COVER <i>new</i>	65.20 NETT X
2 PC REAR BUMPER MUDFLAP <i>new</i>	85.60 NETT X
2 PC REAR CHASSIS CROSSMEMBER <i>Reps</i>	2,263.20 NETT X
1 PC REAR NO. PLATE (EMBOSS) <i>Best</i>	26.00 S/NETT ✓
1 PC REAR NO. PLATE COVER <i>Delaminated</i>	26.00 S/NETT ✓
2 PC REAR NO. PLATE LAMP <i>new</i>	76.80 NETT X
1 PC REAR WINDSCREEN MOULDING	130.10 NETT ✓
1 PC REAR WINDSCREEN SEALANT <i>new</i>	45.00 S/NETT ✓
1 PC REAR WINDSCREEN INNER SEAL	26.00 S/NETT ✓

Nett: 6923.30

S.N: 391.80.

Less 10%: 6230.97

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56

SINGAPORE 417883

TEL : 96273323 FAX 68442641

CO.REG NO: 53049097-L

ESTIMATE COST OF REPAIR BILL TO NISSAN CAR NO : SGJ5116G

LABOUR CHARGE

TO WIRING

~~S\$50.00~~ 30

TO SPRAY PAINTING

~~1,600.00~~ 1400

TO REMOVE AND REFIX REAR INTERIOR UPHOLSTERY & CUSHION

~~150.00~~ 80

TO REMOVE AND REFIX PETROL TANK

80.00 ✓

TO REMOVE AND REFIX REAR WINDSCREEN

~~150.00~~ 120

TO APPLY UNDERCOATING ON THE REPAIRED AND

REPLACED PANEL FOR RUST PROTECTION

~~150.00~~ 120

TO MEASURE, DRILL THE REPLACED BUMPER, POSITION & REINSTALL REVERSE

SENSOR, CONTROL UNIT, CHECK & TEST FOR FUNCTIONING

~~80.00~~ 50

LABOUR CHARGE FOR PANEL BEATING WELDING & REMOVING ALL DAMAGE

PARTS & REPLACING OF THE NEW PARTS ETC

~~1,400.00~~ 1300

3180

TOTAL S\$15,303.30

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 9802.77

(P/P).

10 Days.