

Our Job Ref No : 305484604  
Date : 01/09/21

**COMFORTDELGRO**  
**ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
89 Loyang Drive Singapore 608099

**FINALIZATION FORM**

To : LKK  
Attn : THEVAN  
Vehicle Reg No. : SHA2499G

Fax :

27/08/2021


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

2. The repair job shall bill to: NTUC PC3260S
2. The finalized amount shall be:
- (a) Spare Parts after List discount \_\_\_\_\_
- (b) Labour Charges \_\_\_\_\_
- Total for Part-By-Part Repair Cost** \_\_\_\_\_
- (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: \_\_\_\_\_  
**Final Lumpsum Repair cost** \$2,150.00

3. Estimated normal period for repairs: 3 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature : \_\_\_\_\_  
Name : CHIANG  
Tel : 62148314  
Fax : 65468156

Signature :   
Name : Thevan  
Date : 8/9/21

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_  
\_\_\_\_\_

# REPAIR ESTIMATE\*

VEHICLE NO SHA2499G

MAKE 17.03.2016 REG.

MODEL I-40

DATE 27.08.2021

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	FRONT BUMPER COVER			\$1,052.20	Xm/Net
1	HEAD LAMP LH			\$1,800.00	X Suc
10	BUMPER CLIP			\$22.00	/rec
1	FRONT BUMPER GRILLE LH			\$93.60	X Suc
1	FRONT BUMPER BRACKET TOP LH			\$22.80	/LH
1	FRONT FENDER SHIELD LH			\$174.90	X Suc
1	FRONT WHEEL COVER LH			\$217.20	/cut
1	FRONT FENDER RH			\$663.00	/DLS
	<b>SUB TOTAL</b>			<b>\$4,045.70</b>	
	<b>20.00%</b>			<b>\$809.14</b>	
				<b>\$3,236.56</b>	
1	FRONT FENDER ADVERTISEMENT			\$100.00	
				\$100.00	/rec
	<b>Labour Charge</b>				
	Panel Beating			\$560.00	470
	Spray painting			\$600.00	500
	Reset front wheel alignment			\$60.00	/
	Check Lighting			\$60.00	30
	<b>TOTAL LABOUR</b>			<b>\$1,280.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$4,616.56</b>	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

Thuan Lkh

30/8/21 1700

82235769

thuan@lkh auto. com

3 days w/p

L/S after repair photos

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: