Our Job Ref No 305484912						COMFORTDELGRO				
Date		) " ((4) (14) (4) (4)	02/09/21	2/09/21		ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 858949				
FINAL	.IZATI(	ON FORM				Fav 6546	8154			
To	Marifestante anni distributo de responsa com la riva ingriga		LKK	LKK		Fax				
Attn	Mr		THEVAN	THEVAN						
Vehic	le Reg	No. SH	C1094L	CTPL	-	-	28/08/2021			
The s	urvey a	and estimates	of the repairs of t	he above-mentio	med vehicle are	as follows -				
1.	The n	epair job shall	bill to	NTUC		***	SKG1017D			
2.	The f	inalized amou	nt shall be:							
	(a) Spare Parts after I		after List discoun	ist discount						
	(b) Labour Charges									
		Total for Pa	rt-By-Part Repai	r Cost		•	\$0.00			
	(c.)	Total for Lur	sum Repair (if applicable) for Lumpsum repair cost after Less:		20%					
		rinai Lump	sum Repair cos	i			\$2,950.00			
<b>4</b> . <b>5</b> .	Estimated normal period for repairs:  3 working days.  We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days  Thank you for your assistance.  We confirm the estimates and									
	Signature :			<u> </u>	_ Sigr _ Nan	Signature:  Name: 7/4/2				
	Fax	: 6546					0 4 6			
For	Officia	I Use Only			_					
					15					
	Item		,	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks			
1. F	Rental I	Rate P/Day			YES					
2. Loss of Income Paid					NO					
Survey Fees										
		arch Fee	\$7.	49 / \$2.00						
0	Medical Fees (on behalf of driver, if applicable)     Overrun									
-										

Remarks:

## Sheet2

## COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC1094L

Make

:HYUNDAI

Model : 1-40

Date: 30/08/2021

Insurance: NTUC

MVA: MS. LOKE YY

		MVA: MS. LUKE YY			
Qty	Parts Description / Labour	Туре	Unit Price	Amount	
	1 FRONT BUMPER COVER			\$1,052.20	MAS
1	OFRT BUMPER CLIPS			\$22.00	
	1 FRT BUMPER BRACKET TOP RH			\$44.80	/
	1 FRT BUMPER GRILLE RH			\$187.20	
	1 FRT FENDER RH			\$663.00	DT
	1 FRT FENDER SHIELD RH	• /	/	\$174.90	1
	1 HEADLAMP RH	/	13C)	\$1,800.00	
	1 FRT BUMPER REINFORCEMENT	(		\$588.40	
	1 FRT BUMPER SIDE BRACKET RH			\$24.60	<i>;</i>
	1 HEADLMAP SUPPORT PANEL ASSY			\$907.40	
					. 1
	GUD TOTAL				
	SUB TOTAL	1		\$5,464.50	
	LESS 20%	1		\$1,092.90	
	DISCOUNTED TOTAL			\$4,371.60	
				<b>\$</b> -	Nett
	Labour Charge				
	PANEL BEATING			\$900.00	<60
	SPRAY PAINTING CHARGE			\$850.00	1
	TUFF KOTE			\$60.00	
	WIRING CHARGE			\$60.00	1
	TOTAL LABOUR	1		\$1,870.00	
				\$1,070.00	1
	ESTIMATE TOTAL	-		\$6,241.60	]
	I	1	1		1

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Theyan Ltile St.
82235769

Theyan @ Ltile auto lom

L/S after repair photos
2018/21 1615

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Date: