

Our Job Ref No 305484709

Date 01/09/21

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax 6546 8156

FINALIZATION FORM

To LKK
Attn : THEVAN
: SHA 807P


Fax :


DOA: 27/08/2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SLC8271L
###
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$423.60
 - (b) Labour Charges ### \$630.00
 - Total for Part-By-Part Repair Cost** \$1,053.60
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 2 working days
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature : 
Name : THEVAN
Date : 7/9/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49 / 2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 30.08.2021

Time: 15:17:35

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305484709
 REGN NO : SHA 807P
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 24.09.2019
 DATE/TIME IN : 30.08.2021 14:30
 ACCIDENT DATE : 27.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION


0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	Xr
0002 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10	22.00	20.00	17.60	/ncc
0003 04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	X Svc
0004 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	/OT
0005 28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1 N	50.00	10.00	45.00	/scr

SUB-TOTAL : 841.12

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30

SUB-TOTAL : 780.00

thavon Lkh 
 30/8/21 1630
 2 days up
 thavon@lkhauto.com
 82235769
 P/p bfor paint pictures

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: