

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0719/2021/JT
DATE : 1-Sep-21
WIP : 42281

Denise

\$39514.76 .

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/9/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAN SZE TONG
ADDRESS : 8 ANG MO KIO AVENUE 2
#10-03
SINGAPORE 567695
TELEPHONE : HP +65 96806828
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800073045-03
VEHICLE NO : **SDZ 612 A**
MODEL CODE : A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 26/6/2018
ENGINE NO : CVK 058801
CHASSIS NO : WAUZZZF40JA146757
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Sep-21
PLACE OF ACCIDENT : SCHOOL OF THE ARTS
ROUNDAABOUT ENTRANCE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDZ 612 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$	480.00 ✓	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00 250 ✓	✓
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM TO CARRY OUT VACUUM AND REGAS	S/N \$	1,400.00 ?	✓
4	TO RENEW FRONT WINDSCREEN.	S/N \$	✓ 480.00 ✓	✓
5	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.	S/N \$	✓ 400.00 ✓	✓
6	TO RENEW FRONT WINDSCREEN SENSOR FOIL AND RESET SYSTEM.	S/N \$	✓ 300.00 ✓	✓
SUB - TOTAL LABOUR CHARGES		:	\$ 3,410.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDZ 612 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N \$ 200.00	150 ✓
8	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,400.00	✓ ✓
9	TO REMOVE AND TRANSFER RHS FRONT DOOR 'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 350.00	280 ✓
10	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER, RHS FRONT DOOR AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT RHS FRONT DOOR AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3750 8,050.00	2500 inclusive of fender top support (Rgn)
11	TO RESPRAY FRONT BUMPER, BONNET, HINGES, RHS FRONT FENDER, RHS FRONT FENDER TOP SUPPORT, RHS FRONT DOOR, RHS WING MIRROR COVER AND RHS A-PTILAR	✓ 2475 \$ 6,000.00	4x550 = 2200 Fender Top Support : 275
12	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	\$ 520.00	✓ 2475
SUB - TOTAL LABOUR CHARGES		\$ 17,520.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDZ 612 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$	280.00	X
14	TO CARRY OUT FIRST MESASUREMENT ON CAR-O-LINER.	S/N \$	800.00	✓
15	TO PLACE THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N \$	2,400.00	✓
16	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	✓
TOTAL LABOUR CHARGES		:	\$ 24,794.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDZ 612 A

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Distorted</i>	1	\$ 1,787.00	✓	1429.6
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	TBC	X	
3	FRONT BUMPER SECURING STRIP <i>missing</i>	2	\$ 71.00	✓	56.32
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>deformed</i>	1	\$ 210.00	X	
5	FRONT BUMPER AIR GUIDE - RH	1	\$ 63.00	✓	50.08
6	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Dehnd.</i>	1	\$ 365.00	✓	292
7	FRONT BUMPER GUIDE SECTION - RH <i>Distorted</i>	1	\$ 38.00	✓	29.84
8	HORN - RH <i>3 new</i>	1	\$ 126.00	+	
9	HORN BRACKET - RH	1	\$ 29.00	+	613.2
10	FRONT FENDER - RH <i>Distorted</i>	1	\$ 767.00	✓	
11	FRONT FENDER ATTACHMENT PARTS <i>new new bent</i>	1	\$ 202.00	X	57.52
12	FRONT FENDER CLOSING ELEMENT	1	\$ 72.00	✓	27.92
13	FRONT FENDER TOP BRACKET - FRONT RH <i>Bent</i>	1	\$ 35.00	✓	39.2
14	FRONT FENDER DEFORMATION BRACKET - RH <i>Bent</i>	1	\$ 49.00	✓	15.84
15	RIVET <i>rh</i>	6	\$ 20.00	✓	25.12
16	FRONT FENDER TOP BRACKET - REAR RH <i>Bent</i>	1	\$ 32.00	✓	94.4
17	FRONT FENDER BRACE - RH <i>Bent</i>	1	\$ 118.00	✓	192.8
18	FRONT WHEEL HOUSING LINER - RH <i>Dehnd</i>	1	\$ 241.00	✓	
19	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new new</i>	1	TBC	X	58.4
20	FRONT WHEEL SPOILER <i>Deformed</i>	1	\$ 73.00	✓	
SUB TOTAL SPARE PARTS			\$ 4,298.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1 SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDZ 612 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL SPOILER TRIM - RH <i>del</i>	1	\$ 36.00	28.56
22	FRONT FENDER STONE CHIP GUARD - RH <i>m</i>	1	\$ 51.00	40.32
23	FRONT FENDER TOP COVER - RH <i>del</i>	1	\$ 31.00	24.64
24	FRONT HEADLIGHT CORNER COVER - RH <i>del</i>	1	\$ 23.00	17.92
25	BONNET <i>Dented</i>	1	\$ 3,246.00	2596.8
26	BONNET ATTACHMENT PARTS <i>neu</i>	1	\$ 412.00	
* 27	BONNET HINGE - LH / RH <i>neu</i>	2	\$ 610.00	65.68
28	BONNET IMPACT PROTECTOR - LH / RH / CENTER <i>neu</i>	1	\$ 65.68 84.00	
29	BONNET STRIKER <i>neu</i>	1	\$ 50.00	
30	BONNET LOCK	1	\$ 214.00	6154.4
31	HEADLIGHT - RH <i>cracked</i>	1	\$ 6154.4 7,693.00	
32	HEADLIGHT LIFT CYLINDER - RH <i>neu</i>	1	\$ 210.00	
33	HEADLIGHT LIFT CYLINDER HOSE <i>neu</i>	1	\$ 93.00	
34	LOCK CARRIER <i>cracked</i>	1	\$ 812.8 1,016.00	
35	COOLANT <i>nec</i>	6	\$ 212.64 266.00	
36	FRONT FENDER CONNECTING PLATE - RH <i>neu</i>	2	\$ 217.00	
37	WATER RESERVOIR <i>neu</i>	1	\$ 251.00	
38	FRONT WINDSCREEN <i>cracked</i>	1	\$ 900 147.00	900
39	FRONT WINDSCREEN FOIL <i>neu</i>	1	\$ 109.6 1,125.00	109.2
40	FRONT WINDSCREEN RETAINING SPRING	1	\$ 137.00	16.56
SUB-TOTAL SPARE PARTS			\$ 15,912.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDZ 612 A

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	FRONT WINDSCREEN SPRING CLIP <i>new</i>	1 S	21.00	16.56
42	PRIMER <i>new</i>	1 S	20.00	15.76
43	FRONT DOOR - RH <i>Dented</i>	1 S	3,192.00	2553.6
44	FRONT DOOR OUTER SEAL - R <i>new</i>	1 S	205.00	164
45	BONDING AGENT <i>new</i>	1 S	49.00	?
46	CLEANING SOLUTION <i>new</i>	1 S	68.00	?
47	APPLICATOR <i>new</i>	1 S	8.00	?
48	BUNGS <i>new</i>	1 S	4.00	+
49	FRONT DOOR ATTACHMENT PARTS <i>new</i>	1	TBC	+
50	FRONT DOOR CATCH - RH <i>new</i>	1 S	105.00	?
51	TYRE PRESSURE STICKER <i>new</i>	1 S	38.00	29.84
52	FRONT WINDOR REGULATOR - RH <i>new</i>	1 S	282.00	+
53	FRONT WINDOR REGULATOR MOTOR - RH <i>new</i>	1 S	313.00	+
54	REAR VIEW MIRROR <i>new</i>	1 S	1,079.00	+
55	REAR VIEW MIRROR TOP COVER <i>new</i>	1 S	32.00	?
56	FRONT MIRROR MOUNTING - RH <i>new</i>	1 S	897.00	?
57	FRONT RIM - RH <i>new</i>	1 S	1,690.00	1352
58	FRONT SUB FRAME <i>new</i>	1 S	1,891.00	?
59	FRONT WISHBOON LINK - RH <i>Bent</i>	1 S	539.00	430.8
60	FRONT SUSPENTION GUIDE - RH <i>Bent</i>	1 S	943.00	754.4
SUB-TOTAL SPARE PARTS		:	\$	11,376.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDZ 612 A

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
photo 61	FRONT UPPER ARM - RH Best	2	\$ 1,024.00	✓	818.4	
* 62	FRONT WHEEL BEARING HOUSING - RH damaged	1	\$ 968.00	✓	774	
photo 63	FRONT SWIVEL JOINT - RH Best	1	\$ 193.00	✓	154.4	
* 64	FRONT WHEEL HUB - RH damaged	1	\$ 479.00	✓	383.2	
photo 65	FRONT WHEEL BEARING - RH 2nd	1	\$ 246.00	✓	196.8	
66	FRONT SUSPENSION FORKS - RH Best nn	1	\$ 264.00	✓		
67	FRONT COUPLING ROD - RH Best nn	1	\$ 127.00	✓		
68	FRONT ANTI ROLL BAR {never	1	\$ 433.00	X		
69	FRONT DRIVE SHAFT - RH {never	1	\$ 2,650.00	X		
photo 70	FRONT SHOCK ABSORBER - RH Best	1	\$ 301.00	✓	240.40	
71	FRONT STEERING RACK never	1	\$ 6,787.00	+		
72	FRONT TRACK ROD - RH Best	1	\$ 99.00	?	78.88	
73	FRONT TIE ROD END - RH Best	1	\$ 197.00	?	157.2	
74	FRONT LOWER NOISE INSULATION never	1	\$ 572.00	+		
75	FRONT DOOR WINDOW CHROME SLOT SEAL - RH never	1	\$ 307.00	+		
76	ACRYLIC SEALANT {never	S/N	\$ 180.00	X		
77	GRAVITY WAX {never	S/N	\$ 140.00	X		
78	METAL FILER POWER {never	S/N	\$ 280.00	X		
79	STONE CHIPS {never	S/N	\$ 180.00	X		
80	FRONT WINDSCREEN SEALANT Na	S/N	\$ 200.00	✓	200	
81	SUNDRIES never		\$ 500.00	?	362.96	
TOTAL SPARE PARTS			:	\$ 47,713.00		
TOTAL LABOUR CHARGES			:	\$ 24,794.00		
GRAND TOTAL			:	\$ 72,507.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian Lj
: 02/09/21

: AM Authorised, 12 Days inclusive of car-o-liner measurement.
: *[Signature]*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT