

ASS. REC. BY:

REF: 021

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OO / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Optima

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6-8 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMN 3682J Yr Regn: 08, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____ : Wagon

Make: Toy Noah c.c. 1797

Colour: Black AC: Insured / Std / NI / NA

Sp. Reading: 145368 T/Radio: Insured / Std / NI / NA

Eng No: _____

C.No: ZWR 80 0389578

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Sunwide

Front _____ Rear _____

R/Sal. 7 mm R/Sal. 7 mm

L/Sal. 7 mm L/Sal. 7 mm

D.O.A. 18/21 D.O.I. 1/9/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>GIA not ready</u>

Date/Time, File Pass to? : Prell. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:	_____
Transportation:	_____
\$ - RS. \$	_____
Fuel:	_____
Others:	_____
TOTAL:	_____

Report Format :
Lump Sum / I.B.I. (\$ _____)

*Not Authored
Resurvey B4 paint*

Date: 31.08.2021
Vehicle No: SMN3682J
Model: TOYOTA NOAH HYBRID 1.8X CVT
Chassis: ZWR800389578
Reg.Year: 2019

Third Party Insurer: CHN TAIPING
Third Party Veh No: CB692R
Date of Accident: 31.08.2021
Estimator: VICTOR
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	TAILGATE	1		<i>Ry</i> \$1,988.80
2	TAILGATE CHROME MOULDING	1		<i>CM</i> \$832.00
3	REAR TAILGATE "HYBRID" EMBLEM	1		<i>Me</i> \$85.80
4	REAR TAILGATE INNER TRIM	1		<i>Bu/Di</i> \$570.00
5	REAR TAILGATE INNER LOCK	1		<i>Tr</i> \$495.20
6	REAR WEATHERSTRIP	1		\$280.60
7	REAR WINDSCREEN	1		<i>Shotten</i> \$1,290.00
8	REAR WINDSCREEN MOULDING	1		<i>Me</i> \$116.00
9	TAILLAMP LH	1		\$912.00
10	TAILLAMP RH	1		<i>Pe</i> \$912.00
11	REAR BUMPER	1		<i>Ry</i> \$823.00
12	REAR BUMPER SIDE BRACKET LH	1		<i>Sm</i> \$156.70
13	REAR BUMPER SIDE BRACKET RH	1		<i>Sm</i> \$156.70
14	REAR BUMPER REFLECTOR LH	1		<i>Pe</i> \$38.40
15	REAR BUMPER REFLECTOR RH	1		<i>Sm</i> \$124.80
16	REAR TAIL LAMP LOWER GARNISH PANEL LH	1		\$197.80
17	REAR TAIL LAMP LOWER GARNISH PANEL RH	1		<i>Pe</i> \$197.80
18	REAR TAIL LAMP LOWER GARNISH PANEL BRACKET LH	1		\$115.20
19	REAR TAIL LAMP LOWER GARNISH PANEL BRACKET RH	1		<i>Sm</i> \$115.20
20	END PANEL	1		\$914.60
21	END PANEL TOP COVER	1		\$207.30
22	REAR SPARE TYRE PANEL	1		<i>Me</i> \$698.00
23	REAR SPARE TYRE PANEL TOP BOARD	1		\$830.00
24	REAR SPARE TYRE INNER TRIM	1		\$630.00
25	REAR QUARTER PANEL INNER TRIM LH	1		\$482.00
26	REAR QUARTER PANEL INNER TRIM RH	1		\$482.00
27	REAR TOP INNER TRIM LH	1		<i>Tr</i> \$342.00
28	REAR TOP INNER TRIM RH	1		\$342.00
29	REAR TOP INNER TRIM CENTER	1		<i>Sm</i> \$427.00
SUB TOTAL				\$14,762.90
LESS 25%				-\$3,690.73
PARTS TOTAL				\$11,072.18

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE INNER TRIM CLIPS	1		<i>Me</i> \$120.00

Head office

6 Kung Chong Road Singapore 150143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1003

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 31.08.2021
Vehicle No: SMN3682J
Model: TOYOTA NOAH HYBRID 1.8X CVT
Chassis: ZWRS00389578
Reg.Year: 2019

Third Party Insurer: CHN TAIPING
Third Party Veh No: CB692R
Date of Accident: 31.08.2021
Estimator: VICTOR
Surveyor:

2	REAR WINDSCREEN SEALANT	1	Me	\$100.00	405n
3	END PANEL JOINT SEALANT	1		\$80.00	7
4	REVERSE SENSOR	1	Not	\$300.00	2001n
5	REAR BUMPER CLIPS	1	Me	\$50.00	✓
6	END PANEL TOP COVER CLIPS	1		\$35.00	7
7	REAR LICENSE PLATE WITH HOLDER	1	Me	\$65.00	X
				S/N TOTAL	\$750.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & REPAIR REAR ACCIDENT AREA.	\$1,200.00	7
LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREA.	\$1,400.00	800l
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS.	\$150.00	120l
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM.	\$120.00	60l
LABOUR CHARGES TO REMOVE & REPLACE REVERSE SENSOR.	\$100.00	50l
TO CONDUCT DIAGNOSTIC, RESET FAULT CODE & MEMORY.	\$150.00	7
TO CHECK WIRING & CENTRAL LOCKING SYSTEM.	\$80.00	20l
TO TUFF COAT AND UNDERSEAL MATERIAL.	\$100.00	?
LABOUR TOTAL		\$3,300.00

Vic	<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>	TOTAL \$15,122.18
-----	--	--------------------------

Head office
6 Kung Chong Road Singapore 156143
Tel: 1-651 6472 1313 | Fax: 1-651 6472 2112

Branch
6A Serangoon North Ave 5 Singapore 554500
Tel: 1-651 6484 0010 | Fax: 1-651 6481 1993

Branch (Motor Insurance Claims)
Blk 10 Ang Mo Kio Ind Park EA #01-05 SINGAPORE 68047
Tel: 1-651 6481 1528 | Fax: 1-651 6481 1011

