



Faster



Precision



802.11ac

Faster

Giga

**OPTIMA WERKZ**  
SINGAPORE

OPTIMA WERKZ PTE LTD  
Co. Reg. No. 201212455W  
www.ow.sg

f /OptimaWerkz

*Not At home  
Returning B4 paint*

*6 days  
11 Sep @ 7:30pm*

Date: 31.08.2021  
Vehicle No: SMN3682J  
Model: TOYOTA NOAH HYBRID 1.8X CVT  
Chassis: ZWR800389578  
Reg. Year: 2019

Third Party Insurer: CHN TAIPING  
Third Party Veh No: CB692R  
Date of Accident: 31.08.2021  
Estimator: VICTOR  
Surveyor:

## ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	TAILGATE <i>1712</i>	1	<i>Pr</i>	\$1,988.80
2	TAILGATE CHROME MOULDING <i>773.80</i>	1	<i>CM</i>	\$832.00
3	REAR TAILGATE "HYBRID" EMBLEM	1	<i>Pr</i>	\$85.80
4	REAR TAILGATE INNER TRIM <i>570</i>	1	<i>Bul/Di</i>	\$570.00
5	REAR TAILGATE INNER LOCK <i>368</i>	1	<i>Pr</i>	\$495.20
6	REAR WEATHERSTRIP	1	<i>Dd/Di</i>	\$280.60
7	REAR WINDSCREEN	1	<i>Shatter</i>	\$1,290.00
8	REAR WINDSCREEN MOULDING	1	<i>Pr</i>	\$116.00
9	TAILLAMP LH <i>781</i>	1	<i>mg/CM</i>	\$912.00
10	TAILLAMP RH	1	<i>Pr</i>	\$912.00
11	REAR BUMPER	1	<i>Pr</i>	\$823.00
12	REAR BUMPER SIDE BRACKET LH	1	<i>Pr</i>	\$156.70
13	REAR BUMPER SIDE BRACKET RH	1	<i>Pr</i>	\$156.70
14	REAR BUMPER REFLECTOR LH	1	<i>Pr</i>	\$38.40
15	REAR BUMPER REFLECTOR RH	1	<i>Pr</i>	\$124.80
16	REAR TAIL LAMP LOWER GARNISH PANEL LH	1	<i>Pr</i>	\$197.80
17	REAR TAIL LAMP LOWER GARNISH PANEL RH	1	<i>Pr</i>	\$197.80
18	REAR TAIL LAMP LOWER GARNISH PANEL BRACKET LH	1	<i>Pr</i>	\$115.20
19	REAR TAIL LAMP LOWER GARNISH PANEL BRACKET RH	1	<i>Pr</i>	\$115.20
20	END PANEL <i>683.50</i>	1	<i>Pr</i>	\$914.60
21	END PANEL TOP COVER	1	<i>mg/CM</i>	\$207.30
22	REAR SPARE TYRE PANEL	1	<i>Pr</i>	\$698.00
23	REAR SPARE TYRE PANEL TOP BOARD <i>830</i>	1	<i>Bul</i>	\$830.00
24	REAR SPARE TYRE INNER TRIM	1	<i>Reform</i>	\$630.00
25	REAR QUARTER PANEL INNER TRIM LH	1	<i>Di</i>	\$482.00
26	REAR QUARTER PANEL INNER TRIM RH	1	<i>Pr</i>	\$482.00
27	REAR TOP INNER TRIM LH	1	<i>Pr</i>	\$342.00
28	REAR TOP INNER TRIM RH	1	<i>Pr</i>	\$342.00
29	REAR TOP INNER TRIM CENTER	1	<i>Pr</i>	\$427.00
SUB TOTAL				\$14,762.90
LESS 25%				-\$3,690.73
PARTS TOTAL				\$11,072.18

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE INNER TRIM CLIPS	1	<i>Pr</i>	\$120.00

## Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

## Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9910 | Fax: (+65) 6481 1003

## Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6401 1522 | Fax: (+65) 6401 1011





# OPTIMA WERKZ™

SINGAPORE

OPTIMA WERKZ PTE LTD  
Co. Reg. No. 201212455W

www.ow.sg

f /OptimaWerkz

● /OptimaWerkz

Date: 31.08.2021  
Vehicle No: SMN3682J  
Model: TOYOTA NOAH HYBRID 1.8X CVT  
Chassis: ZWR800389578  
Reg.Year: 2019

Third Party Insurer: CHN TAIPING  
Third Party Veh No: CB692R  
Date of Accident: 31.08.2021  
Estimator: VICTOR  
Surveyor:

2	REAR WINDSCREEN SEALANT	1	<i>nu</i>	\$100.00	<i>405n</i>
3	END PANEL JOINT SEALANT	1	<i>nu</i>	\$80.00	<i>305n</i>
4	REVERSE SENSOR	1	<i>nu</i>	\$300.00	<i>200n</i>
5	REAR BUMPER CLIPS	1	<i>nu</i>	\$50.00	<i>✓</i>
6	END PANEL TOP COVER CLIPS	1	<i>nu</i>	\$35.00	<i>✓</i>
7	REAR LICENSE PLATE WITH HOLDER	1	<i>nu</i>	\$65.00	<i>X</i>
				S/N TOTAL	\$750.00

## LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & REPAIR REAR ACCIDENT AREA.	\$1,200.00	<i>700l</i>
LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREA.	\$1,400.00	<i>800l</i>
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS.	\$150.00	<i>120l</i>
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM.	\$120.00	<i>60l</i>
LABOUR CHARGES TO REMOVE & REPLACE REVERSE SENSOR.	\$100.00	<i>50l</i>
TO CONDUCT DIAGNOSTIC, RESET FAULT CODE & MEMORY.	<i>nu</i> \$150.00	<i>X</i>
TO CHECK WIRING & CENTRAL LOCKING SYSTEM.	\$80.00	<i>20l</i>
TO TUFF COAT AND UNDERSEAL MATERIAL.	\$100.00	<i>60l</i>
LABOUR TOTAL		\$3,300.00

Vic

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL \$15,122.18

### Head office

6 Kung Chong Road Singapore 169143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9910 | Fax: (+65) 6481 1093

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

