

Paper Survey

pho 7 pcs only

11/9/11 vehicle still at Eurokars
haven repair

12 days

EUROKARS SERVICES PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

EUROKARS SERVICES

Allianz Insurance Company of Singapore Pte Ltd		NAME :		WIP :			
79 Robinson Road #09-01		ADDRESS :		EXCESS :			
Singapore 068897		TEL :		DATE: 26-Aug-21			
ATTN. : MOTOR CLAIMS							
FAX :							
VEH NO :	SNB1969Y	DATE IN :		CONTACT PERSON :	STEPHANIE		
CHASSIS NO :	LRW3F7EL5MC263559	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM		
MODEL :	TESLA MODEL 3	DATE REG.:		POLICY NO. :			
NATURE OF WORKS							
Parts Description							
NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1	FRONT BUMPER	1			1519965-S0-A		\$ 495.33
2	FRONT BUMPER RETAINER RH	1			1084182-00-E		\$ 1.87
3	FRONT BUMPER BRACKET RH	1			1104541-00-B		\$ 9.35
4	FRONT BUMPER BRACKET TO FENDER RH	1			1084172-00-F		\$ 12.15
5	FRONT BUMPER BRACKET TO FENDER LH	1			1084171-00-F		\$ 12.15
6	FRONT BUMPER BOLT	12			1031683-00-B		\$ 8.88
7	FRONT BUMPER RIVETS	12			1006521-00-A		\$ 8.04
8	FRONT BUMPER CARRIER	1			1611028-00-A		\$ 738.32
9	FRONT BUMPER CARRIER RH TO BUMPER	1			1084170-00-B		\$ 7.48
10	FRONT BUMPER LOWER REINFORCEMENT	1			1084894-00-B		\$ 102.80
11	LOWER REINFORCEMENT BRACKET RH	1			1109193-00-C		\$ 29.91
12	FRONT DOOR RH	1			1081420-E0-C		\$ 1,009.35
13	REAR DOOR RH	1			1081440-E0-C		\$ 953.27
14	FRONT FENDER RH	1			1081400-E0-D		\$ 448.60
15	FRONT FENDER PLUG	1			1127883-00-C		\$ 1.87
16	FRT DOOR UPPER HINGE RH	1			1101034-00-F		\$ 74.77
17	FRT DOOR LOWER HINGE RH	1			1101036-00-F		\$ 74.77
18	FRT DOOR CHECKER RH	1			1089507-00-D		\$ 65.42
19	FRT DOOR CLOSE OUT PANEL ASSY	1			1092146-00-D		\$ 42.06
20	DOOR CLOSE OUT PANEL RIVET	13			1108921-00-A		\$ 9.62
21	DOOR PLUG	4			1052817-00-C		\$ 22.44
22	FRT DOOR CHECKER SEAL RH	1			1101580-00-E		\$ 4.67
23	ROUND PLUG FOR DOOR	2			1127883-00-C		\$ 3.74
24	ROUND PLUG FLUSH	4			1447449-00-A		\$ 2.96
25	FRONT DOOR LATCH	1			1500673-00-A		\$ 33.64
26	DOOR STRIKER	1			1525919-00-B		\$ 2.80
27	FRT DOOR REGULATOR RH	1			1096621-00-L		\$ 224.00
28	FRT DOOR SEAL RH	1			1090494-00-D		\$ 88.79
29	FRT DOOR OUTER MOULDING RH	1			1080684-01-I		\$ 88.79
30	FRT DOOR INNER SEAL RH	1			1090496-00-E		\$ 65.42

DIS ✓
C/O ✓
Nec ✓
Bent ✓
11 X
Nec ✓
Nec ✓
11 X
11 X
11 X
11 X
DIS ✓
Bent ✓
DIS ✓
Nec ✓
Bent ✓
Bent ✓
twi ✓
? ✓
Nec ✓
Nec ✓
Nec ✓
11 X
11 X
? ✓
Nec ✓
Nec ✓
Nec ✓

check and verify

FENDER UNDERSHIELD RH	torn	1	1081582-00-D	\$ 116.82	Torn
UNDERSHIELD CLIPS	-Ne	18	1110713-99-C	\$ 7.20	Ne
RIVET	-Ne	2	1006521-00-A	\$ 1.34	Ne
34 FRT UNDERCOVER	- cut	1	1084174-00-D	\$ 186.92	Torn
35 RIVETS FOR UNDERCOVER	-Ne	10	1128034-00-B	\$ 7.40	Ne
36 NUT FOR UNDERCOVER		4	1454548-00-A	\$ 2.68	Ne
37 UNDERCOVER CENTER	torn	1	1104312-00-B	\$ 224.30	Torn
38 UNDERCOVER CLIPS	-Ne	9	1484170-00-A	\$ 16.83	Ne
39 TESLA LOGO	-Ne	1	1494949-00-A	\$ 37.38	11X
40 SIDE MIRROR RH	?	1	1617900-00-B	\$ 467.29	11X
41 SIDE MIRROR COVER RH	X	1	1092292-00-D	\$ 44.86	11X
42 SIDE MIRROR GLASS RH	X	1	1130654-00-A	\$ 233.64	11X
43 SIDE MIRROR BOLT	X	3	1002784-00-A	\$ 2.22	11X
44 EXT MIRROR A-PILLAR RH	X	1	1130656-00-E	\$ 116.82	11X
45 B-PILLAR GARNISH RH	X	1	1109256-00-D	\$ 205.61	11X
46 B-PILLAR BOLT	X	2	1008884-00-C	\$ 1.48	11X
47 RIVET	-Ne	2	1112572-00-A	\$ 1.48	11X
48 B PILLAR COVER LOWER RH	?	1	1100088-00-D	\$ 37.38	?
49 ROCKER PANEL COVER RH	-graze	1	1089829-00-D	\$ 364.49	2e
50 BONNET HINGE LH	X	1	1098792-00-D	\$ 74.77	11X
51 BONNET HINGE RH	X	1	1098793-00-D	\$ 74.77	11X
52 FRONT LUGGAGE GARNISH	?	1	1526738-00-B	\$ 64.49	?
53 LUGGAGE GARNISH CLIPS	?	10	1472872-00-C	\$ 18.70	?
54 DOOR TRIM PAD FRONT	-Ne	1	1085108-00-D	\$ 9.35	Ne
55 FRT DOOR TRIM RH	X	1	1135308-91-C	\$ 560.75	11X
56 FRT DOOR TRIM CLIPS	-Ne	18	1135147-00-A	\$ 67.32	11X
57 FRONT SUBFRAME	-del	1	1044531-01-B	\$ 1,177.57	twi
58 SUBFRAME BOLT	-Ne	2	1461643-00-A	\$ 1.48	Ne
59 BOLT	-Ne	2	1111151-00-A	\$ 1.48	Ne
60 BOLT	-Ne	2	1456640-00-A	\$ 3.74	Ne
61 BOLT	-Ne	2	1461654-00-A	\$ 1.48	Ne
62 BOLT	-Ne	2	1063257-00-B	\$ 3.74	Ne
63 STEERING GEAR ASSY	-f	1	1044836-00-J	\$ 2,672.90	Buf
64 STEERING NUT	-Ne	2	1109263-00-B	\$ 9.34	Ne
65 BOLT	-Ne	2	1104656-00-C	\$ 1.48	Ne
66 BOLT	-Ne	2	1530018-00-A	\$ 0.84	Ne
67 BOLT	-Ne	2	1063257-00-B	\$ 3.74	Ne
68 BALL JOINT	-broken	2	1044841-00-E	\$ 243.00	twi
69 FRONT SPORT RIM	-fnt	1	1234227-02-D	\$ 1,009.35	?
70 LUG NUT COVER	-dnt	1	1188236-00-A	\$ 5.61	Ne
71 FR KNUCKLE, RH	-dnt	1	1044316-00-E	\$ 420.56	Buf
72 HUB ASSY, DRIVEN	?	1	1044121-00-E	\$ 149.53	?
73 BOLT	-Ne	6	2007111	\$ 11.22	Ne
74 BOLT	-Ne	2	1114797-00-A	\$ 3.74	Ne
75 BOLT	-Ne	1	1064834-00-B	\$ 0.74	Ne
76 NUT	-Ne	1	1111145-00-A	\$ 0.74	Ne
77 FR LWR COMP LINK ASSY, RH	-f	1	1044359-00-A	\$ 224.30	Buf

NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES	
1								
2								
3								
					TOTAL PARTS		\$ 17,665.52	
					TOTAL PARTS COST		\$ 17,665.52	
SUPPLEMENTARY								
					TOTAL PARTS		\$	
					TOTAL PARTS COST		\$	
Labour Description							REVISED	PRICES
1	TO REMOVE & REPLACE FRT BUMPER, FRT FENDER RH, FRT DOOR RH, REAR DOOR RH, SIDE KSIRT RH, SIDE MIRROR RH & ALL ACCIDENT DAMAGE AREAS, TO REPAIR REAR FENDER RH, A PILLAR RH & REALIGN BONNET & ALL AREAS AFFECTED BY THE ACCIDENT						X 5 3800-01	\$ 4,641.00

660X5?

	TO RESPRAY/ PUTTY & POLISH THE ACCIDENT AREAS. BONNET, FRT BUMPER, FRT FENDER RH, SIDE MIRROR COVER RH, A- PILLAR RH, FRT DOOR RH, REAR DOOR RH, REAR FENDER RH, SIDE SKIRT RH, FRT FENDER LH	7K 4410.07	\$ 6,500.00	4410
	TO CARRY OUT BODY CAVITY PRESERVATION	NETT 450.07	\$ 540.00	250
4	TO TRANSFER THE FRONT & REAR DOOR MECHANISM	NETT 560.07	\$ 560.00	✓
8	TO TRANSFER THE FRONT BUMPER SENSORS	150.07	\$ 300.00	✓
9	TO REMOVE & REPLACE FRONT UNDERCARRIAGE RH	NETT 660.07	\$ 660.00	✓
10	MZ-BR-CROSS1 TO REPLACE CROSSMEMBER ASSY.	NETT 660.07	\$ 660.00	✓
11	MZ-BR-WHEEL TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT 560.07	\$ 560.00	300
12	TO MOUNT 1 SPORT RIM AND CONDUCT WHEEL BALANCING (FRT RIM RH)	NETT 120.07	\$ 120.00	✓
13	TO SUPPLY / REPLACE 1 PC TIRE	NETT X	\$ 980.00	X
14	MZ-BR-TOW-IN TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. sub DV		\$ 350.00	350?
15	MZ-BR-ELECTR TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150.07	\$ 350.00	150
16	MZ-BR-REPROG TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	350.07	\$ 450.00	350
17	TO REPLACE PPF FOR THE ACCIDENT AREA		TBA	?
18	MZ-BR-SUNDRI SUNDRIES	50	\$ 120.00	50

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TOTAL LABOUR	\$ -	\$ 16,791.00
TOTAL PARTS	\$ -	\$ 17,665.52
TOTAL	\$ -	\$ 34,456.52
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ 34,456.52
GST 7%	\$ -	\$ 2,411.96
GRAND TOTAL	\$ -	\$ 36,868.48

SUPPLEMENTARY LABOUR DESCRIPTION

		REVISED	PRICES
1	#N/A		
2	#N/A		
		TOTAL LABOUR	\$ - \$ -
		TOTAL PARTS	\$ - \$ -
		TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS

REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE
 BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT
 TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400**
 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN
 SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

EUROKARS SERVICES PTE LTD

20/8/21 1407 12 day.

Tf Survey Without Prejudice
 Authorise Subject to Policy Condition
 Part by Part / Lump Sum day
 Resurvey before / After Paint / Check Items
 Liew Kong Ho HP 97606062 (O) 62550808
 Email: khouho@jxinspection.com

 Authorised Signature