

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5944H**AAD2108-***Not Authorised*
11 Sep @ 4650h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

03 SEP 2021**SHC5944H**

VF1ABL15AUC281463

RENAULT

LATITUDE

02/09/2021

AUTO & GENERAL

23/03/2015

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Sm</i> 747.20 X
1	FENDER PANEL FRT RH	\$	<i>Ry</i> 437.10 ✓
1	HEADLAMP RH	\$	<i>Sm</i> 743.60 X
1	DOOR PANEL FRT RH	\$	<i>Ry</i> 2,844.66 ✓
1	DOOR WEATHERSTRIP FRT RH	\$	<i>Sm</i> 410.27 X
1	DOOR HANDLE OUTER FRT RH	\$	<i>Sm</i> 477.76 X
1	DOOR HANDLE MODULE FRT RH	\$	<i>Sm</i> 133.60 X
1	DOOR REGULATOR FRT RH	\$	<i>R</i> 505.19 X
1	DOOR REGULATOR MOTOR FRT RH	\$	<i>R</i> 796.46 X
1	DOOR HINGE UPPER FRT RH	\$	<i>R</i> 261.28 X
1	DOOR HINGE LOWER FRT RH	\$	<i>R</i> 300.55 X
1	DOOR PANEL REAR RH <i>1458</i>	\$	<i>Ry</i> 2,844.66 ✓
1	DOOR WEATHERSTRIP REAR RH	\$	<i>Sm</i> 311.60 X
1	DOOR HANDLE MODULE REAR RH	\$	<i>Sm</i> 133.40 X
1	DOOR HANDLE OUTER REAR RH	\$	<i>Sm</i> 42.10 X
1	DOOR REGULATOR REAR RH	\$	<i>R</i> 450.60 X
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>R</i> 758.10 X
1	DOOR HINGE UPPER REAR RH	\$	<i>R</i> 241.60 X
1	DOOR HINGE LOWER REAR RH	\$	<i>R</i> 169.90 X
1	FENDER PANEL REAR RH	\$	<i>R</i> 1,933.20 X
1	WHEELARCH REAR RH	\$	<i>Sm</i> 275.40 X
1	ROCKER PANEL OUTER RH	\$	<i>R</i> 1,184.99 X
TOTAL		\$	16,003.22
10%		\$	1,600.32
		\$	14,402.90

Special Nett



Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2108-

SHC5944H

2 FENDER CLIP	\$	na	120.00	X
1 DOOR TRIM CLIP	\$	na	70.00	X
1 DOOR SEAL CLIP	\$	na	65.00	X
1 DOOR MOULDING CLIP	\$	na	70.00	X
1 FR BUMPER CLIP	\$	na	70.00	X
1 RIM	\$	na	350.00	X
1 DOOR STICKER TRANSCAB	\$	na	100.00	60sa
1 DOOR STICKER 65553333	\$	na	100.00	60sa
1 DOOR STICKER CLASSIC	\$	na	100.00	15sa
TOTAL	\$		1,045.00	

TOTAL PARTS \$ 15,447.90

LABOUR

To rust-proofing and apply undercoat of the affected areas.	\$	230.00	90a
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	12a
Putty and spray painting of the affected portion.	\$	1,400.00	66a
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	50a
To transfer of tire, rim and on wheel balancing.	\$	na	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00	20a
To check steering geometry and computer wheel alignment	\$	na	220.00 X
TOTAL	\$	4,360.00	

Over All Total \$ 19,807.90

(LUMPSUM) Repair Days

20 Days

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: