



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2200532

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 26/01/2022
Reference CC4/LPC21009253/Epa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLF 9968A
Insured Veh. SGS 2574P
Claim No. 21/21/21/VP05/024818
Policy No. Z21VP05028562
Accident Date 02/08/2021
Inspection Date 08/09/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21009253/Epa3q2 Date: 26/01/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGS 2574P	Veh. Inspected	SLF 9968A	
Policy No.	Z21VP05028562	Coverage (\$)	0.00	
Claim No.	21/21/21/VP05/024818	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	02/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	SJNFBAJ11U1738850	Colour	GREY	
Odometer	132807 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R19	CONTINENTAL	5 mm	
L/H Front Tyre	225/45 R19	CONTINENTAL	5 mm	
R/H Rear Tyre	225/45 R19	CONTINENTAL	5 mm	
L/H Rear Tyre	225/45 R19	CONTINENTAL	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/08/2021	Inspection Date	08/09/2021	
Survey held at	ETHOZ PROTECT PTE LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 9968A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE (NPA)	TO REPAIR SEE LABOUR	-	-
1	TAILGATE EMBLEM 'QASHQAI'	BROKEN	75.50	75.50
1	TAILGATE EMBLEM 'X-TRONIC'	BROKEN	68.90	68.90
1	REAR BUMPER	DENTED	755.90	755.90
10	REAR BUMPER CLIPS	NECESSARY	55.00	30.00
1	REAR BUMPER SIDE RETAINER LH	BROKEN	75.20	75.20
1	REAR BUMPER SIDE RETAINER RH	BROKEN	75.20	75.20
1	REAR BUMPER INNER BRACKET LH	NOT NECESSARY	45.50	-
1	REAR BUMPER INNER BRACKET RH	NOT NECESSARY	45.50	-
1	REAR BUMPER TOWING COVER	NOT NECESSARY	34.30	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	85.60	-
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	85.60	-
1	REAR BUMPER FOAM	BROKEN	184.30	127.00
1	REAR END PANEL	NOT NECESSARY	643.40	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	253.60	-
1	SPARE TYRE PANEL (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER REINFORCEMENT (ADDITIONAL)	BENT	454.30	454.30
	LESS 10% DISCOUNT		-293.78	-166.20
			2,644.02	1,495.80
	<u>SPECIAL NETT ITEMS</u>			
4	REVERSE SENSOR (1SET) (SN)	SHORTED	350.00	200.00
1	END PANEL SEALANT (SN)	NOT NECESSARY	40.00	-
			390.00	200.00
	<u>LABOUR</u>			
	LABOUR TO CARRY OUT REAR REPAIR .INCLUSIVE OF THE REPAIR OF TAILGATE .		900.00	500.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS .		35.00	30.00
	TO SPRAY PAINTING ON REAR AFFECTED AREA .		900.00	600.00
	SPRAY RUST PROOF ON AFFECTED AREA.		40.00	30.00

Report Ref No. CC4/LPC21009253/Epa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DETACH & RENEW REVERSE SENSOR.		60.00	30.00
			1,935.00	1,190.00
GRAND TOTAL			4,969.02	2,885.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CC4/LPC21009253/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 9968A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 9968A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 9968A

RE-INSPECTION

