


Steve

CC4/LPC 21009253/693

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD/TP/WR/TPRES/OP/RES/EVA/INV/IV  
To Inspect Vehicle Not \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Velt: \_\_\_\_\_



(Policy Condition)  
Remarks: The veh had commenced its  
repair at the time of inspection.

Rel. or Market Value: \_\_\_\_\_  
IDAC Accident Report Consistent? Yes or No  
SIA / PR Seen Consistent? Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Cum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN/OUT

Veh No: SLF 9968A Yr Regn: 11/8/16  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Nissan QASHQAI C.B. 11/97  
Colour: Grey A/O: Insured / Std / NI / N  
Sp. Reading: 132807 T/Radio: Insured / Std / NI / N  
Eng/No: \_\_\_\_\_  
C/No: STAN-BAT 11/2/73 8857  
Gen. Condi: Good / Fair / Poor / Buzd  
Steering: In order / Jammed / Locked / Burnt or  
Brakes: In order / Jammed / Locked / Burnt or  
Mod: NII / SIRIM / STD / A/Rim or  
Tyre Size: P 225/45R19 R 11  
BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/  
TOYO/YOKO or B Continental  
Front R/Bal. S mm R/Bal. S mm  
L/Bal. S mm U/Bal. S mm  
D.O.A. 2/8/21 Borneo Motors O.O.L. 8/9/21  
Survey held at  
Des. of Damages: Fnt / Rear / O/S / N/S / VIC / Roof/Top or  
The U/S / CHASSIS frame / Body Structure affected due to collision

| Date/Time | Action/Instructions |
|-----------|---------------------|
|           | MP-SSK              |
|           |                     |
|           |                     |
|           |                     |
|           |                     |
|           |                     |
|           |                     |
|           |                     |
|           |                     |
|           |                     |

Time/Date, File, Return to: ☐ Prel. Report ☐ Final Report  
Days Of Repair: \_\_\_\_\_ Resurvey No. of Trips: \_\_\_\_\_  
Add Fee: ☐ Site Insp (\$ \_\_\_\_\_) ☐ Interview (\$ \_\_\_\_\_) ☐ Tech. Insp (\$ \_\_\_\_\_) ☐ Wheel and (\$ \_\_\_\_\_)  
Survey Fee: ☐ Transportation \$ \_\_\_\_\_ ☐ Fuel \$ \_\_\_\_\_ ☐ Other \$ \_\_\_\_\_  
TOTAL \$ \_\_\_\_\_

Steve (LKK)  
8/9/21, 12:00 PM

L/K PL  
L/S  
My AL sign  
4 days

PLEASE ARRANGE TO SURVEY  
VEHICLE AT 30 BUKIT BATOK  
CRESCENT (S 658075)

Lee Chen Sin  
CLAIM DEPARTMENT  
DID : 66547520  
FAX :

Date : 01/09/2021  
To : LONPAC INSURANCE BHD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : NG HIN PAK  
: NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Certificate No : 5098326110-03 Accident Date : 02/08/2021  
Vehicle No : SLF-9968-A Make & Model : NISSAN QASHQAI 2.0 CVT ABS D/AIRBAG 2V  
ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

| QTY              | DESCRIPTION                                    | REPAIRER AMT (\$) | SURVEYOR APP. |
|------------------|------------------------------------------------|-------------------|---------------|
| <u>Nett Item</u> |                                                |                   |               |
| 1                | TAILGATE <del>X</del> <del>R</del> R RESTORE   |                   |               |
| 1                | TAILGATE EMBLEM "QASHQAI" ✓ <del>MC</del>      | 75.50             | ✓             |
| 1                | TAILGATE EMBLEM "X-TRONIC" ✓ <del>MC</del>     | 68.90             | ✓             |
| 1                | REAR BUMPER ✓ <del>00</del>                    | 755.90            | ✓             |
| 10               | REAR BUMPER CLIPS ✓ <del>MC</del>              | 30-55.00          | ✓             |
| 1                | REAR BUMPER SIDE RETAINER LH ✓ <del>OR</del>   | 75.20             | ✓             |
| 1                | REAR BUMPER SIDE RETAINER RH ✓ <del>OR</del>   | 75.20             | ✓             |
| 1                | REAR BUMPER INNER BRACKET LH ✓ <del>x mn</del> | 45.50             |               |
| 1                | REAR BUMPER INNER BRACKET RH ✓ <del>x mn</del> | 45.50             |               |

Date : 01/09/2021  
 To : LONPAC INSURANCE BHD.  
 Attn : Motor Claim Department

## ESTIMATION

FAX :

Owner : NG HIN PAK  
 : NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 Certificate No : 5098326110-03 Accident Date : 02/08/2021  
 Vehicle No : SLF-9968-A Make & Model : NISSAN QASHQAI 2.0 CVT ABS D/AIRBAG 2V

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION                       | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|-----------------------------------|-------------------|---------------|
| 1   | REAR BUMPER TOWING COVER X nn     | 34.30             |               |
| 1   | REAR BUMPER REFLECTOR LH X nn     | 85.60             |               |
| 1   | REAR BUMPER REFLECTOR RH X nn     | 85.60             |               |
| 1   | REAR BUMPER FOAM ? - BR           | 184.30            | 127 -         |
| 1   | REAR END PANEL ? + nn             | 643.40            |               |
| 1   | REAR END PANEL TOP GARNISH ? + nn | 253.60            |               |
| 1   | SPARE TYRE PANEL X nn             |                   |               |
|     | RESTORE                           |                   |               |
|     | Sub Total                         | 2483.50           |               |
|     | Discount 10% On Parts             | (248.35)          |               |
|     | <u>Special Nett Item</u>          |                   |               |

1207.70  
 - 10%  
 1086.93

Date : 01/09/2021  
 To : LONPAC INSURANCE BHD.  
 Attn : Motor Claim Department

## ESTIMATION

FAX :

Owner : NG HIN PAK  
 : NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 Certificate No : 5098326110-03 Accident Date : 02/08/2021  
 Vehicle No : SLF-9968-A Make & Model : NISSAN QASHQAI 2.0 CVT ABS D/AIRBAG 2V  
 Excess : 0.00 Add Excess : 0.00

### ESTIMATED REPAIR COST DETAILS

| QTY                      | DESCRIPTION                                  | REPAIRER AMT (\$) | SURVEYOR APP. |
|--------------------------|----------------------------------------------|-------------------|---------------|
| 1                        | REVERSE SENSOR (4PCS)(SET) ✓ <i>Shaded!</i>  | 200 - 350.00      |               |
| 1                        | END PANEL SEALANT X <i>ny</i>                | 40.00             |               |
|                          | Sub Total                                    | 390.00            |               |
| <b>Labour &amp; Misc</b> |                                              |                   |               |
|                          | LABOUR TO CARRY OUT REAR REPAIR              | 900.00            | <i>4500</i>   |
|                          | TO CHECK AND RECONNECT ALL NECESSARY WIRINGS | 35.00             | <i>30</i>     |
|                          | TO SPRAY PAINTING ON REAR AFFECTED AREA      | 900.00            | <i>600</i>    |
|                          | SPRAY RUST PROOF ON AFFECTED AREA            | 40.00             | <i>30</i>     |
|                          | TO DETACH & RENEW REVERSE SENSOR <i>1190</i> | 60.00             | <i>30</i>     |

P- 1086.93  
 n- 200  
 L- 1190  
 SUPP- 408.87  
 2885.80  
 L/S - 2308.64  
 = 2300

Date : 01/09/2021  
To : LONPAC INSURANCE BHD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : NG HIN PAK  
: NTUC INCOME INSURANCE CO-OPERATIVE LTD

Certificate No : 5098326110-03

Accident Date : 02/08/2021

Vehicle No : SLF-9968-A

Make & Model : NISSAN QASHQAI 2.0 CVT ABS D/AIRBAG 2V

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|-------------|-------------------|---------------|
|     | Sub Total   | 1935.00           |               |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Remarks:

Acknowledged by Repairer  
Signature:  
Date:

4,560.15

### SUB TOTAL

GST 7.0 % 319.21

TOTAL 4,879.36

Surveyor's name: \_\_\_\_\_

Principal's name: NG HIN PAK

Survey Date & Time: \_\_\_\_\_

PLEASE ARRANGE TO SURVEY  
VEHICLE AT 30 BUKIT BATOK  
CRESCENT (S 658075)

Lee Chen Sin  
CLAIM DEPARTMENT  
DID : 66547520  
FAX :

Date : 12/10/2021  
To : LONPAC INSURANCE BHD.

**SUPPLEMENTARY**

Attn : Motor Claim Department

FAX :

Owner : NG HIN PAK  
: NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Certificate No : 5098326110-03  
Vehicle No : SLF-9968-A  
Accident Date : 02/08/2021  
Make & Model : NISSAN QASHQAI 2.0 CVT ABS D/AIRBAG 2V

## ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY              | DESCRIPTION               | REPAIRER AMT (\$) | SURVEYOR APP. |
|------------------|---------------------------|-------------------|---------------|
| <u>Nett Item</u> |                           |                   |               |
| 1                | REAR BUMPER REINFORCEMENT | 454.30            |               |
|                  | Sub Total                 | 454.30            |               |
|                  | Discount 10% On Parts     | (45.43)           |               |

408.87

Remarks:

**SUB TOTAL**

**GST 7.0 %** 28.62

**TOTAL** 437.49

Surveyor's name: \_\_\_\_\_

Principal's name: NG HIN PAK

Survey Date & Time: \_\_\_\_\_

PAGE :