



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21009255/Kqf3n2	
			Date: 15/09/2021	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLC 710B	Veh. Inspected	CB 6846R	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2102645/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	02/09/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HIGER (M)	c.c	3800	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	LKLS1CS63BA569825	Colour	GOLD	
Odometer	215896 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/75 R17.5	AEOLUS	7 mm	
L/H Front Tyre	215/75 R17.5	AEOLUS	7 mm	
R/H Rear Tyre	215/75 R17.5 (D)	DOUBLE COIN	9/9 mm	
L/H Rear Tyre	215/75 R17.5 (D)	DOUBLE COIN	9/9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	02/09/2021	Inspection Date	03/09/2021	
Survey held at	566 WOODLANDS ROAD, 728697 WOODLANDS			
Repairer	CONNECT3			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	