



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0709/2021/JT
DATE : 31-Aug-21
WIP : 41953

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/9/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days exclude 1 Sunday

Johnny Boo 8 Oct 21

OWNER'S NAME : MS AW SIN HUI
ADDRESS : BLK 217 BISHAN STREET 23
#13-217
SINGAPORE 570217
TELEPHONE : HP +65 81989018
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800001701-03
VEHICLE NO : **SLV 6417 J**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 8/1/2018
ENGINE NO : CHZ 592063
CHASSIS NO : WAUZZZ8V3J1030068
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Aug-21
PLACE OF ACCIDENT : SLIP ROAD TO CTE FROM
BUKIT TIMAH ROAD

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLV 6417 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00		
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	\$	1,000.00
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET.	\$	3,000.00	\$	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 6,702.00	\$	2,542.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 6417 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT		REMARKS
1	FRONT BUMPER	1	\$	1,987.00	\$ 1,589.60
2	FRONT BUMPER FIXING PARTS	1	\$	187.00	
3	FRONT BUMPER GUIDE SECTION - LH	1	\$	39.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$	160.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$	536.00	
6	FRONT BUMPER CLOSING ELEMENT - LH	1	\$	297.00	
7	FRONT BUMPER COVER TRIM - LH	1	\$	163.00	
8	FRONT WHEEL HOUSING LINER ADAPTER - LH	1	\$	38.00	
9	RADIATOR GRILLE	1	\$	1,406.00	\$ 1,124.80
10	RADIATOR GRILLE CLOSING ELEMENT	1	\$	191.00	\$ 152.40
11	FRONT BUMPER AIR GRILLE - LH	1	\$	188.00	
12	AIR CONDITIONER STICKER	1	\$	8.00	\$ 5.68
13	CAUTION STICKER	1	\$	14.00	\$ 10.88
14	FRONT BUMPER REINFORCEMENT	1	\$	795.00	\$ 636.00
15	FRONT BUMPER REINFORCEMENT FOAM	1	\$	189.00	\$ 151.20
16	FRONT BUMPER REINFORCEMENT COVER	1	\$	122.00	\$ 97.20
17	HORN - LH	1	\$	200.00	
18	FRONT FENDER -LH	1	\$	851.00	
19	POP RIVET	5	\$	17.00	
20	FRONT FENDER ATTACHMENT PART	1	\$	72.00	
SUB TOTAL SPARE PARTS			:	\$ 7,460.00	\$ 3,767.76

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 6417 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
		<i>C/F</i>		\$	3,767.76
21	FRONT FENDER BRACE - LH	1	\$	39.00	
22	FRONT FENDER BRACKET - LH	1	\$	39.00	
23	FRONT WHEEL HOUSING LINER - LH	1	\$	169.00	
24	FRONT FENDER ATTACHMENT PART	1	\$	89.00	
25	FRONT BONNET	1	\$	3,134.00	\$ 2,507.20
26	FRONT BONNET ATTACHMENT PART	1	\$	165.00	
27	FRONT BONNET CATCH - UPPER	1	\$	90.00	
28	FRONT BONNET STRIKER - LH	1	\$	110.00	
29	FRONT BONNET EDGE PROTECTION	1	\$	28.00	\$ 22.00
30	FRONT BONNET CATCH - LOWER	1	\$	63.00	
31	FRONT BONNET LOCK WITH MICRO-SWITCH	1	\$	214.00	
32	FRONT BONNET LOCK COVER	1	\$	4.00	
33	FRONT BONNET BOWDEN CABLE - CENTER	1	\$	58.00	
34	FRONT BONNET BOWDEN CABLE COVER	1	\$	10.00	
35	HEADLIGHT - LH	1	\$	5,455.00	\$ 4,364.00
36	HEADLIGHT LIFT CYLINDER - LH	1	\$	142.00	
37	HEADLIGHT WASHER HOSE	1	\$	68.00	
38	RADIATOR AIR GUIDE - LH	1	\$	25.00	
39	RADIATOR AIR GUIDE - UPPER	1	\$	12.00	
40	FRONT NO. PLATE	S/N	\$	60.00	\$ 60.00
41	SUNDRIES		\$	300.00	
TOTAL SPARE PARTS		:	\$	17,734.00	\$ 10,720.96
TOTAL LABOUR CHARGES		:	\$	6,702.00	\$ 2,542.00
GRAND TOTAL		:	\$	24,436.00	\$ 13,262.96

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-08/10/21



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT