



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0709/2021/JT  
DATE : 31-Aug-21  
WIP : 41953

*Xiao Chan.*

*\$13262.96*

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/9/21

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Dept  
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS AW SIN HUI  
ADDRESS : BLK 217 BISHAN STREET 23  
#13-217  
SINGAPORE 570217  
TELEPHONE : HP +65 81989018  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 1800001701-03  
VEHICLE NO : SLV 6417 J  
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI  
MODEL YEAR : 8/1/2018  
ENGINE NO : CHZ 592063  
CHASSIS NO : WAUZZZ8V3J1030068  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 28-Aug-21  
PLACE OF ACCIDENT : SLIP ROAD TO CTE FROM  
BUKIT TIMAH ROAD



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLV 6417 ]**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ <del>350.00</del>	250 ✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ <del>2,800.00</del>	1000 ✓
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET.	\$ <del>3,000.00</del>	1100 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ <u>6,702.00</u></b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 6417 J**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 1,987.00	✓ 1589.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 187.00	✗
3	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 39.00	✗
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 160.00	✗
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>	1	\$ 536.00	✗
6	FRONT BUMPER CLOSING ELEMENT - LH <i>new</i>	1	\$ 297.00	✗
7	FRONT BUMPER COVER TRIM - LH <i>new</i>	1	\$ 163.00	✗
8	FRONT WHEEL HOUSING LINER ADAPTER - LH <i>new</i>	1	\$ 38.00	✗
9	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,406.00	✓ 1124.80
10	RADIATOR GRILLE CLOSING ELEMENT <i>Cracked</i>	1	\$ 191.00	? 152.40 ✓
11	FRONT BUMPER AIR GRILLE - LH <i>Not New</i>	1	\$ 188.00	? ✗
12	AIR CONDITIONER STICKER <i>new</i>	1	\$ 8.00	✓ 5.68
13	CAUTION STICKER	1	\$ 14.00	✓ 10.88
14	FRONT BUMPER REINFORCEMENT <i>? Dented</i>	1	\$ 795.00	? 636 ✓
15	FRONT BUMPER REINFORCEMENT FOAM <i>? Cracked</i>	1	\$ 189.00	? 151.20 ✓
16	FRONT BUMPER REINFORCEMENT COVER <i>? Cracked</i>	1	\$ 122.00	? 97.20 ✓
17	HORN - LH <i>Not New</i>	1	\$ 200.00	? ✗
18	FRONT FENDER - LH <i>new</i>	1	\$ 851.00	✗
19	POP RIVET <i>new</i>	5	\$ 17.00	✗
20	FRONT FENDER ATTACHMENT PART <i>new</i>	1	\$ 72.00	✗
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 7,460.00</b>	

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 6417 J**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACE - LH	1	\$ 39.00	X
22	FRONT FENDER BRACKET - LH	1	\$ 39.00	X
23	FRONT WHEEL HOUSING LINER - LH	1	\$ 169.00	X
24	FRONT FENDER ATTACHMENT PART	1	\$ 89.00	+
25	FRONT BONNET <i>Dented</i>	1	\$ 3,134.00	✓ 2507.20
26	FRONT BONNET ATTACHMENT PART <i>Not n</i>	1	\$ 165.00	+
27	FRONT BONNET CATCH - UPPER	1	\$ 90.00	+
28	FRONT BONNET STRIKER - LH <i>Not n</i>	1	\$ 110.00	+
29	FRONT BONNET EDGE PROTECTION <i>Not n</i>	1	\$ 28.00	✓ 22
30	FRONT BONNET CATCH - LOWER <i>Not n</i>	1	\$ 63.00	+
31	FRONT BONNET LOCK WITH MICRO-SWITCH <i>Not n</i>	1	\$ 214.00	+
32	FRONT BONNET LOCK COVER	1	\$ 4.00	+
33	FRONT BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	+
34	FRONT BONNET BOWDEN CABLE COVER	1	\$ 10.00	+
35	HEADLIGHT - LH <i>Canted</i>	1	\$ 5,455.00	✓ 4364
36	HEADLIGHT LIFT CYLINDER - LH <i>Not n</i>	1	\$ 142.00	? X
37	HEADLIGHT WASHER HOSE <i>Not n</i>	1	\$ 68.00	+
38	RADIATOR AIR GUIDE - LH <i>Not n</i>	1	\$ 25.00	? X
39	RADIATOR AIR GUIDE - UPPER <i>Not n</i>	1	\$ 12.00	? X
40	FRONT NO. PLATE <i>Not n</i>	S/N	\$ 60.00	✓ ✓
41	SUNDRIES <i>Not n</i>		\$ 300.00	? X
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 17,734.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 6,702.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 24,436.00</b>	

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Lim  
SURVEYED DATE : 02/09/11  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : Not Authorised, 04 Days.  


PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT