

FASTECH AUTO PTE LTD

PAGE 1 OF 2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 22558

Date : 02.09.2021

Vehicle Num : SMK 1286Z

Make/Model : BMW 520I

Chassis/Engine no :

Accident Date : 01.09.2021

Claim No : 0821-22558

Reference :

Policy No :

TP ALG.

Xiao Tong.

WBAXG12080DX53391

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Rear fender air duct LH <i>new</i>	\$ 1,982.60 <i>x</i>
1 pc	Rear boot emblem (520I) <i>new</i>	\$ 95.00 <i>x</i>
1 pc	Rear boot emblem logo	\$ 98.00 <i>x</i>
1 pc	Rear boot reflector lamp R/H <i>new</i>	\$ 1,118.40 <i>x</i>
1 pc	Rear end panel <i>new</i>	\$ 984.10 <i>x</i>
1 pc	Rear tail lamp R/H <i>cut</i>	\$ 1,336.60 <i>640.</i>
1 pc	Rear tail lamp panel R/H <i>new</i>	\$ 704.60 <i>x</i>
1 pc	Rear bumper diffuser <i>new</i>	\$ 1,012.30 <i>x</i>
1 pc	Rear bumper <i>Deland</i>	\$ 1,974.00 <i>1563</i>
1 pc	Rear bumper reflector R/H <i>new</i>	\$ 118.20 <i>x</i>
1 pc	Rear bumper reinforcement <i>new</i>	\$ 967.70 <i>x</i>
1 pc	Rear bumper centre retainer <i>new</i>	\$ 289.50 <i>x</i>
4 pc	Rear bumper reverse sensor R/H @ 265.00	\$ 1,060.00 <i>x</i>
1 pc	Rear bumper side retainer R/H <i>Combined</i>	\$ 265.00 <i>115</i>
List Item Total :		\$ 12,006.00
Discount 10 %		\$ 1,200.60
		\$ 10,805.40

2318

2086.20

FASTECH AUTO PTE LTD

PAGE 2 OF 2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 22558

Date : 02.09.2021

Vehicle Num : SMK 1286Z

Make/Model : BMW 520I

Chassis/Engine no :

Accident Date : 01.09.2021

Claim No : 0821-22558

Reference :

Policy No :

Qty	Particular	Amount S\$
-----	------------	------------

Special Nett Item :

6 pc Rear bumper lower clips @ 12.90

3 pc Rear end panel top garnish clips @ 12.90

Special Nett Total :

\$	77.40
\$	38.70
\$	116.10

Labour Charge :

To check wiring and reset

Tuff kote

Remove and refix rear timing etc

Remove and replace reverse sensor

To remove and replace spare part and panel beating

To spray painting and etc

Labour Charge Total :

\$	200.00
\$	120.00
\$	160.00
\$	150.00
\$	850.00
\$	650.00
\$	2,130.00

E & O . E

Total Amount : \$ 13,051.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Adrian G
4/5 04/09/21
02 days
total: 2696.20
4/5 2150.