

Section A - Accident Details

Registration Number	SHC4644E
Case Reference Number	TAX/08/21/2070
Registration Date	20/10/2014
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	V CHANDRASAGARAN
Type of Accident	Side Swipe
Accident Date and Time	28/8/2021 4:00 PM
Accident Reported Date and Time	30/8/2021 11:32 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24112103
Special Instruction to ARC, if any	FRONT LEFT /TOWED \$40 / CHINA TAIPING - LKK
Prepared Date and Time	31/8/2021 6:32 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$2,412.00	\$680.00
Total Spare Part Cost	\$8,923.11	\$3,202.66
Total Other Cost	\$876.00	\$200.00
TOTAL COST	\$12,887.11	\$4,482.66
Lump Sum Total	\$12,900.00	\$4,500.00 (L/S)
Number of Repair Days	6.0	5.0
Prepared / Adjusted By	Ang Bang Kien	GUO QIANG (LKK) / China Taiping
ARC / Surveyor Sign Off Date	06/09/2021 11:04 AM	06/09/2021 10:54 AM
Signature		
Remarks	Total number of repair days = 5 days. SUP = 0 day.	lump sum repair / after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2109-0225	Invoice Number	
Quotation Date	15.09.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$676.00	\$400.00 ✓
Total Labour	\$676.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 ✓
RESPRAY MIRROR COVER LH	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00 ✓
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$80.00 ✓
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$2,412.00	\$680.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00 ✓
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$56.00	\$40.00 ✓
Total Other Costs	\$876.00	\$200.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		68740-12120	HINGE LOWER LHF, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Check
		68720-15151	HINGE UPPER LHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Check
		68610-47021	CHECK ASSY, FR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Check
		69040-47070	DOOR LOCK FRT/LH	0.00	\$575.80	0.00	\$0.00	Replace	Not Given
		87940-47310	MIRROR ASSY,LH	0.00	\$1,224.90	0.00	\$0.00	Replace	Not Given

X
X
X
X
X
X } NN

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/09/2021

User ID : PohSuan

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
81740-52040			MIRROR LAMP LH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given	X NN
87945-74010			COVER, OUTER MIRROR, LH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given	X NN
53802-47050			FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	√ BUC
75374-47051			NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	√ NEC
53826-47010			FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Not Given	X NN
53828-47060			PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Check	X NN
53867-47030			SEAL, FRONT FENDER TO COWL SIDE LH	1.00	\$15.20	100.00	\$0.00	Replace	Repair	R
53876-47030			FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$128.78	Replace	Replace	√ DE
53852-47020			FENDER LINER PAD, FR WHEEL. LH	1.00	\$49.30	25.00	\$36.98	Replace	Replace	√ NEC
53702-47050			FENDER APRON SUB FRT/LH	0.00	\$637.80	0.00	\$0.00	Replace	Not Given	X NN
42611-47140			WHEEL DISC. FRONT	1.00	\$1,484.20	25.00	\$1,113.15	Replace	Replace	√ CUT
75852-47900			MOULDING BODY, LH	1.00	\$673.60	100.00	\$0.00	Replace	Repair	R
43550-47011			WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Check	X NN
52119-47930			BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace	√ CUT
52161-16010			BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	√ NEC
52116-47040			BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace	√ DE
52611-47080			BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given	X NN
52021-47023			BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given	X NN
57014-47030			ARM SUB-ASSY,FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X NN
57013-47030			ARM SUB-ASSY,FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X NN
53102-47020			BUMPER GRILLE SUB-ASSY,LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given	X NN
81220-12230			FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Not Given	X NN
81521-47050			LENS & BODY,FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given	X NN
53113-47040			GRILLE, RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Not Given	X NN
76851-47020			BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X NN
52618-47050			BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given	X NN
51410-12105			UNDER COVER CENTER	0.00	\$448.30	0.00	\$0.00	Replace	Not Given	X NN
51444-12050			UNDER COVER SIDE/LH	0.00	\$46.10	0.00	\$0.00	Replace	Not Given	X NN
53301-47060			HOOD PANEL	0.00	\$748.10	0.00	\$0.00	Replace	Not Given	X NN
53420-47070			HOOD HINRE LH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given	X NN
53410-47070			HOOD HINGE RH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given	X NN
81170-47500			HEAD LAMP LH	0.00	\$945.20	0.00	\$0.00	Replace	Check	X NN
67002-47070			DOOR FRT/LH	1.00	\$894.40	25.00	\$670.80	Replace	Replace	√ BT
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√ NEC
Total					\$13,168.51		\$3,022.07			

Added Spare Parts / Material Usage After Surveyor Signed off										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	√ SCR
			CAP SUB-ASSY, WHEEL	1.00	\$174.10	25.00	\$130.58	Replace	Replace	√ DIS
Total					1,119.30		981.26			

4,003.33
 -20% L/S \$4,500/-
 3202.66
 + 400.00
 + 880.00
 4,482.66