

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 22736900M

PAGE 1 OF 3

Estimate : 22562

Date : 03.09.2021

Vehicle Num : SKH 1816J

Make/Model : Mitsubishi Lancer

Chassis/Engine no :

Accident Date : 02.09.2021

Claim No : 0921-22562

Reference :

Policy No :

TP III
Asher.

Qty	Particular	Amount S\$
List Item :		
1 pc	Rear boot lid board <i>Distorted.</i>	\$ 347.00 <i>230</i>
1 pc	Rear third brake light <i>crackd</i>	\$ 452.00 <i>125</i>
2 pc	Rear boot lid reflector @ 395.00 <i>crackd.</i>	\$ 790.00 <i>580.</i>
1 pc	Rear boot lid <i>Distorted.</i>	\$ 1,025.00 <i>850.</i>
1 pc	Rear boot rubber <i>lt</i>	\$ 325.00 <i>185.</i>
1 pc	Rear boot lock <i>Tamed</i>	\$ 282.00
1 pc	Rear boot lock catch <i>Best</i>	\$ 75.00
2 pc	Rear boot hinge @ 185.00 <i>Best</i>	\$ 370.00 <i>250.</i>
1 pc	Rear boot emblem (mivec) <i>Free</i>	\$ 85.00
1 pc	Rear boot emblem (lancer)	\$ 85.00
2 pc	Rear boot lid hinges absorber holder @ 225.00 <i>Damaged</i>	\$ 450.00
1 pc	Rear boot centre logo <i>new</i>	\$ 82.00
1 pc	Rear end panel <i>Distorted</i>	\$ 655.00 <i>550.</i>
1 pc	Rear end panel top garnish <i>Dishd</i>	\$ 285.00
2 pc	Rear chassis number @ 755.00 <i>Ry</i>	\$ 1,510.00 <i>x.</i>
2 pc	Rear spare tyre board corner panel @ 275.00 <i>Buckd</i>	\$ 550.00
1 pc	Rear bumper centre beam <i>Distorted</i>	\$ 125.00
1 pc	Rear spare tyre board top cover cloth <i>new</i>	\$ 145.00 <i>x</i>
2 pc	Rear tail lamp @ 749.00 <i>crackd</i>	\$ 1,498.00 <i>700</i>
2 pc	Rear tail lamp panel @ 165.00 <i>Distorted</i>	\$ 330.00
2 pc	Rear fender @ 895.00 <i>RA Buckd</i>	\$ 1,790.00 <i>895</i>
2 pc	Rear fender inner garnish @ 415.00 <i>ton</i>	\$ 830.00 <i>290</i>
2 pc	Rear fender dust cover @ 40.00 <i>new</i>	\$ 80.00 <i>x</i>
1 pc	Rear bumper <i>Distorted</i>	\$ 948.00 <i>830</i>
2 pc	Rear bumper side retainer @ 60.00 <i>new</i>	\$ 120.00
1 pc	Rear bumper reinforcement <i>Best</i>	\$ 655.00 <i>325</i>
2 pc	Rear bumper reflector @ 47.00 <i>crackd</i>	\$ 94.00
1 pc	Rear spare tyre panel <i>Distorted</i>	\$ 1,012.00
1 pc	Rear spare tyre top cover board <i>ton</i>	\$ 350.00
1 pc	Rear spare tyre screw <i>new</i>	\$ 68.00
1 pc	Rear exhaust silencer <i>new</i>	\$ 1,450.00 <i>x</i>
2 pc	Rear lower arm @ 355.00 <i>new</i>	\$ 710.00 <i>x</i>
1 pc	Rear blind spot sensor <i>new</i>	\$ 552.00 <i>x.</i>
		\$ 18,125.00

CHOO MOTOR SPRAY PAINTER

PAGE 2 OF 3

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 22736900M

Estimate : 22562

Date : 03.09.2021

Vehicle Num : SKH 1816J

Make/Model : Mitsubishi Lancer

Chassis/Engine no :

Accident Date : 02.09.2021

Claim No : 0921-22562

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Rear exhaust chrome pipe <i>3 are nec</i>	\$ 125.00 <i>+</i>
1 pc	Rear boot lock antennae	\$ 255.00 <i>+</i>
2 pc	Rear shock absorber @ 415.00	\$ 830.00 <i>+</i>
2 pc	Rear knuckle arm @ 652.30	\$ 1,304.60 <i>+</i>
2 pc	Rear exhaust rubber @ 41.00	\$ 82.00 <i>+</i>
2 pc	Rear wheel bearing hub @ 395.00	\$ 790.00 <i>+</i>
2 pc	Rear number plate lamp @ 60.00	\$ 120.00 <i>-</i>
1 pc	Rear windscreen mldg <i>dur</i>	\$ 145.00 <i>-</i>
List Item Total :		\$ 21,776.60
Discount 10 %		\$ 2,177.66
		\$ 19,598.94

9768

8791.20

Special Nett Item :

3 pc	Rear end panel top garnish clips @ 6.50 <i>nu</i>	\$ 19.50 <i>✓</i>
1 pc	Rear spare tyre panel top insulator <i>nu</i>	\$ 250.00 <i>2w</i>
1 pc	Rear windscreen sealant <i>nu</i>	\$ 100.00 <i>60</i>
1 pc	Rear number plate <i>Best</i>	\$ 45.00 <i>✓</i>
1 pc	Rear bumper sensor <i>Dargd</i>	\$ 450.00 <i>2w</i>
1 pc	Rear reversing camera <i>nu</i>	\$ 650.00 <i>+</i>
1set	Tail lamp mask <i>nu</i>	\$ 150.00 <i>+</i>
1 pc	Rear boot cover top spoiler <i>3 are</i>	\$ 2,200.00 <i>+</i>
1 pc	Rear boot cover top spoiler (small) <i>nu</i>	\$ 1,800.00 <i>+</i>
Special Nett Total :		\$ 5,664.50

524.50

CHOO MOTOR SPRAY PAINTER

PAGE 3 OF 3

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 22736900M

Estimate : 22562

Date : 03.09.2021

Vehicle Num : SKH 1816J

Make/Model : Mitsubishi Lancer

Chassis/Engine no :

Accident Date : 02.09.2021

Claim No : 0921-22562

Reference :

Policy No :

Qty	Particular	Amount S\$
	<u>Labour Charge :</u>	
	To check wiring	\$ 250.00 30
	Tuff kote	\$ 200.00 100
	Remove and refix rear windscreen	\$ 150.00 120
	Remove and refix upholstery	\$ 250.00 180
	Remove and replace exhaust pipe	\$ 160.00 +
	Remove and replace reserve sensor	\$ 150.00 50
	To remove and replace spare part and panel beating	\$ 2,800.00 1600
	To spray painting and etc	\$ 1,800.00 1400
	Remove and refix rear undercarriage suspension etc	\$ 550.00 +
	Check wheel alignment	\$ 120.00 +
	Labour Charge Total :	\$ 6,430.00

E & O . E

Total Amount : \$ 31,693.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 12795.70

2/s: 10.2K.

12 Days.

CHOO MOTOR SPRAY PAINTER

Repair limit: 14K.