

ESTIMATE BILL FOR CB7198X DOA 20/08/2021

PARTS	DESCRIPTION	QUANTITY	ESTIMATE
1	ENGINE ?	1	-
2			-
3			-
4			-
5			-
6			-
7			-
8			-
9			-
10			-
11			-
12			-
13			-
14			-
15			-
16			-
17			-
18			-
19			-
20			-
21			-
22			-
23			-
24			-
25			-
26			-
27			-
28			-
29			-
30			-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modifications are allowed
- Supplier of parts must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SUB TOTAL FOR PARTS

LABOUR

1	LABOUR FOR MECHANICAL ?	2,560.00
2	LABOUR FOR WIRING ?	3,600.00
3		
4		

SUB TOTAL FOR LABOUR

6,160.00

TOTAL ESTIMATE BILL

6,160.00

Guo Qiang
8288 0282
Guo Qiang @ LKK Auto . com
03/9/2021
Not Authorized.
(umpsin repair / After repair photos.
Excess = TBA



SC AUTO

Hamimah Binte Jamaludin
Customer Care Advisor

D 65 6571 9958 M 65 8282 8611
E hamimah.j@scauto.com.sg

SC AUTO INDUSTRIES (S) PTE LTD
51/53 Senoko Road, Singapore 758133
T 65 6758 2222 F 65 6257 6931
scauto.com.sg