

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21009279/R1ES3Q2**Date:** 17/01/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SJZ3314U **Insured Vehicle No :** SLT4716U
 Date of Loss: 31/08/2021 Nature of Claim: TP Claim No: MFL2021D0003818

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ3314U**
 Make & Model: BMW X5 XDRIVE35I, 3.0 AT 4WD 5DR GAS/D NAV SR (A) Engine No: 07027398N55B30A
 Reg. Date: 16/11/2010 (Man. Year: 2010) Chassis No: WBAZV42050LL57425
 Colour: Blue Odometer: 61700 km
 Engine Capacity: 2979 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55 R18 Rear Tyre Size: 255/55 R18
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,259.16	2,436.51	822.65	25.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	760.00	500.00	260.00	34.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,019.16	2,936.51	1,082.65	26.94
Approved Total (Overridden) (S\$)		2,350.00		
(S\$)	4,019.16	2,350.00	1,669.16	41.53
+ GST 7.00/7.00% (S\$)	281.34	164.50	116.84	41.53
Nett Amount (S\$)	4,300.50	2,514.50	1,786.00	41.53
+ Car Rental (5.0 x S\$180.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,421.95		
Global Sum Settlement (S\$)		3,400.00		

INSPECTION

Date of Assignment: 03/09/2021
 Date Inspected: 07/10/2021 Inspected At: Vin's Motor Pte Ltd (Sin Ming)
 160 Sin Ming Drive, #03-03, Sin Ming AutoCity
 Singapore 575722
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE

MARKET VALUE: \$99,000
LTA REBATE: \$34,651
NETT VALUE: \$64,349

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Dec 2021)

Parts: M1-SUV BMW X5 XDRIVE35I 3.0 AT 4WD 5DR GAS/D NAV SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJZ3314U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,624.10 FL	*1,472.00 FL
2	2		*REAR BUMPER LH SENSOR	Not Working (1 PCS ONLY)	513.00 FL	*236.00 FL
3	1		*REAR BUMPER LH SIDE REFLECTOR	Cracked	36.75 FL	*36.75 FL
4	1		*REAR BUMPER LH SIDE RETAINER	Serviceable	135.10 FL	*- FL
5	1		*REAR BUMPER LOWER PAD	Serviceable	267.50 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	737.10 FL	*707.00 FL
7	1		*REAR LH EXHAUST CHROME	Scratched	117.15 FL	*113.00 FL
					Sub Total (\$\$)	3,430.70 2,564.75
					- List Item Discount on L Items 5.00/5.00% (\$\$)	171.54 128.24
					Total Parts (\$\$)	3,259.16 2,436.51

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR DAMAGES	New	380.00	250.00
2	TO SPRAY PAINTING	New	380.00	250.00
Gross Labour Cost (S\$)			760.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >