

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : India International Insurance
Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Claim Details

Case Ref. No. : TP/102021/5019
Date : 06-10-2021
Accident Date : 31-08-2021

Vehicle Details

Make & Model : B.M.W. X5 XDRIVE35i 3.0 AT
4WD 5DR GAS
Chassis No : WBAZV42050LL57425
Registration No : SJZ3314U

Third Party Vehicle Details

Registration No : SLT4716U

| S/N | Description | Qty | Amount (\$) |
|-----|--------------------------------------------------|------|-------------|
| 1 | REAR BUMPER <i>de</i> | 1.00 | \$1,624.10 |
| 2 | REAR BUMPER LH SENSOR @ \$256.50 <i>an / ipc</i> | 2.00 | \$513.00 |
| 3 | REAR BUMPER LH SIDE REFLECTOR <i>cm / ipc</i> | 1.00 | \$36.75 |
| 4 | REAR BUMPER LH SIDE RETAINER <i>x</i> | 1.00 | \$135.10 |
| 5 | REAR BUMPER LOWER PAD <i>x</i> | 1.00 | \$267.50 |
| 6 | REAR BUMPER REINFROCEMENT <i>st?</i> | 1.00 | \$737.10 |
| 7 | REAR LH EXHAUST CHROME <i>slu</i> | 1.00 | \$117.15 |

\$3,430.70

Discount -5%

(\$171.56)

\$3,259.14

8 TO REPAIR DAMAGES

1.00

~~\$380.00~~ *250*

9 TO SPRAY PAINTING

1.00

~~\$380.00~~ *250*

Subtotal w/o GST:

\$4,019.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.

Rasul
Hp 90010068
3 days
4s
07/10/21 @ 1435
Resy after repair