



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0480521

Date of Report : 03/07/2021

To : M/s. jefter engineering pte ltd
C/o. 48 Toh Guan Road East
#01-119 Enterprise Hub
Singapore 608586

Date of Assignment : 31/05/2021
Report requested by : M/s. jefter engineering pte ltd
Date of Accident : 21/05/2021
Date of Inspection : 31/05/2021
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : GBE7772J
Make & Model : Toyota Dyna 150
Date of Registration : 29/03/2016
Colour : Met. Silver

Engine Capacity (cc) : 2982cc
Mileage (km) : 147088km
Chassis / Frame No. : JTFAT35Y80K206111
Engine No. : 1KD2589469

TYRE CONDITION

Front LH : 10 mm
Make : Bridgestone

Front RH : 10 mm
Make : Bridgestone

Rear LH : 4 mm / 4 mm
Make : Bridgestone

Rear RH : 4 mm / 4 mm
Make : Bridgestone

Road wheels Type : Standard

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Gold Autoworks Pte Ltd
48, Toh Guan Road East, #01-119, Enterprise Hub, Singapore 608586

ASSESSMENT

Repairer's Estimate : \$ 6,772.80
Revised Amount : \$ 4,341.23
Less Excess : \$ -
Recommended Reserve : \$ 3,470.00 (Lump Sum)

Estimated Normal Period of Repairs : 5 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addressees (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may be protected by legal privilege. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : GBE7772J

Report No. : PAS/TP/0480521

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Gold Autoworks Pte Ltd, 48, Toh Guan Road East, #01-119, Enterprise Hub, Singapore 608586.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the front portion.

DAMAGES

The front windscreen, front wiper panel, front panel top inner member, front panel (outer), dashboard, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$4,341.23.

CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$3,470.00.

This inspection was conducted entirely on a '**Without Prejudice**' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,
Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No : GBE7772J

Report No. : PAS/TP/0480521

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (\$)	Our Assessment (\$)
1	1 pc	Frt windscreen	Cracked	\$ 1,582.40 <i>1288</i>	\$ 1,582.40 ✓
2	1 pc	Frt windscreen moulding	Necessary	\$ 372.90 <i>250</i>	\$ 372.90 ✓
3	1 pc	Wiper blade RH	Dented/Bent	\$ 81.20 <i>40</i>	\$ 81.20 ✓
4	1 pc	Wiper arm RH	Dented/Bent	\$ 114.50	\$ 114.50 ✓
5	1 pc	Wiper blade LH	Refit	\$ 86.30 <i>nn</i>	\$ - ✗
6	1 pc	Wiper arm LH	Dented/Bent	\$ 110.40 <i>nn</i>	\$ 110.40 ✗
7	1 pc	Wiper arm cap LH	Dented/Cracked	\$ 9.70	\$ 9.70 ✓
8	2 pcs	Wiper nozzle R/L	Broken	\$ 117.20	\$ 117.20 ✓
9	1 pc	Wiper arm cap link rod assy	Dented/Damaged	\$ 298.70 <i>nn</i>	\$ 298.70 +
10	1 pc	Wiper motor	Refit	\$ 760.70 <i>nn</i>	\$ - ✗
11	1 pc	Frt wiper garnish	Dented/Distorted	\$ 301.60	\$ 301.60 ✓
12	1 pc	Frt panel top inner member	Dented/Distorted	\$ 482.30 <i>R</i>	\$ 482.30 ✗
13	1 pc	Frt panel top garnish (Black)	Dented/Loop Broken	\$ 325.50	\$ 325.50 ✓
14	1 pc	Frt panel outer	Dented/Repair	\$ 834.60 <i>R</i>	\$ - ✗
15	1 pc	Frt emblem (Dyna)	Necessary	\$ 63.90	\$ 63.90 ✓
16	1 pc	Frt grille assy	Refit	\$ 600.50 <i>nn</i>	\$ - ✗
17	1 pc	Frt panel outer	Dented/Repair	(Refer labour no. 4 & 5)	
				\$ 6,142.40	\$ 3,860.30
Less Discount : 25%				\$ 1,535.60	\$ 965.08
List Parts Sub-Total :				\$ 4,606.80	\$ 2,895.23
1	1 pc	ERP bracket	Necessary	\$ 26.00	\$ 26.00 ✓
Special Nett Sub-Total :				\$ 26.00	\$ 26.00
Parts Total :				\$ 4,632.80	\$ 2,921.23



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : GBE7772J

Report No. : PAS/TP/0480521

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To remove and reinstall electrical wiring system for necessary repairs. To check electrical system, repair wire harness and focus headlamp.	\$ 70.00 30	\$ 50.00
2	To remove, replace and reinstall front windscreen.	\$ 120.00	\$ 120.00
3	To remove, replace and reinstall dashboard assy.	\$ 350.00 200	\$ 300.00
4	To straighten, repair, realign on affected area and replace damaged parts.	\$ 800.00 400	\$ 550.00
5	To spray painting, blending on affected and adjacent area.	\$ 800.00	\$ 400.00
Labour Total :		<u>\$ 2,140.00</u>	<u>\$ 1,420.00</u>
Total (Parts & Labour) :		<u>\$ 6,772.80</u>	<u>\$ 4,341.23</u>

4 repair days

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 3,470.00

Under normal circumstances, the repairs should be completed within a reasonable period

of **5 Working Days.** (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)

52 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.