



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC21006224/Etf3e2-1	
			Date: 21/09/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XB 8263K		Veh. Inspected	GBE 7772J
Policy No.			Coverage (\$)	0.00
Claim No.	20/21/21/VC00/024599		Excess (\$)	0.00
Assign From	KENNY LIM		Assign Date	03/09/2021
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA		c.c	2982
Engine No.	HIDDEN		Year of Reg.	2016
Chassis No.	JTFAT35Y80K206111		Colour	SILVER
Odometer	147088 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	STANDARD ALLOY RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		106/104R	BRIDGESTONE	5 mm
L/H Front Tyre		106/104R	BRIDGESTONE	5 mm
R/H Rear Tyre		106/104R	BRIDGESTONE	5 mm
L/H Rear Tyre		106/104R	BRIDGESTONE	5 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/05/2021		Inspection Date	31/05/2021
Survey held at	GOLD AUTOWORKS PTE LTD 48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	