



**ESTEEM**

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485H

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575716  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
178 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7828

**Repair Estimates**

SDB 8899 M

Parts	(a) Cost / List Price Items	\$	79,943.60
	Plus/Less 10%	\$	7,994.36
	<b>Total of Cost / List</b>	<b>\$</b>	<b>71,949.24</b>
	(b) Nett Price Items		
	Less		
	<b>Total of Nett Item</b>		
	(c) Special Nett Items	\$	45.00
<b>Total Parts Cost</b>		<b>\$</b>	<b>71,994.24</b>
<b>Labour</b>		<b>\$</b>	<b>3,650.00</b>
<b>Total</b>		<b>\$</b>	<b>75,644.24</b>

The above total will be subjected to 7% G.S.T.

83,330.24

*Not known  
Primary B4pains  
Ex \$10,000  
\$ 74,507.80*

Name of Surveyor

*Kenneth*

Company

*LKIC*

Survey conducted on

at

*3/9/21*

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : *06* day(s)

(c) Resurvey : Required / Not Required *Not Required*

(d) Excess : \$

(e) Signature of surveyor

Date: \_\_\_\_\_

**ESTEEM**

ESTEEM PERFORMANCE PTE LTD  
UEN 200805488N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6758 2112 (F) 6451 0394

WORKSHOP  
178 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7620

**Spare Parts**

Vehicle No. :  
Make & Model :  
Chassis No. :

**SDB 8899 M**

BENTLEY / CONTINENTAL GTC  
SCBGE23W9DC081180

Submit By :  
Year Manufacture :  
Engine No. :

**JENNY**

07-Feb-13

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	S.N	✓ 29/12
2	Headlamp LH	1	\$9,900.00		✓
3	Headlamp RH	1	\$9,900.00		✓
4	Headlamp Chrome LH	1	\$324.00		✓
5	Headlamp Chrome RH	1	\$324.00		✓
6	Signal Lamp chrome LH	1	\$306.00		X
7	Signal Lamp chrome RH	1	\$306.00		X
8	Front support panel	1	\$2,340.00		X
9	Front support panel lower	1	\$666.00		X
10	Condenser	1	\$1,800.00		✓
11	Radiator	1	\$2,628.00		✓
12	Radiator fan blade	1			
13	Radiator air guide RH	1	\$108.00		✓
14	Radiator air guide LH	1	\$108.00		✓
15	Front bumper	1	\$8,244.00		✓
16	Front bumper clip	10	\$200.00		✓
17	Front bumper reinforcement	1	\$2,250.00		X
18	Front bumper side retainer LH	1	\$117.00		X
19	Front bumper side retainer RH	1	\$117.00		X
20	Front bumper sponge	1	TBA		X
21	Front grille	1	\$3,960.00		✓
22	Front grille mesh	1	\$1,242.00		✓
23	Front grille chrome	1	\$1,728.00		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ASS. REQ. BY:

REF: *LPC1**KENNETH*

NT

*OmN 48516*

Bus / Van / Lorry / T

*Piente*

AC

TF

**Spare Parts**Vehicle No. :  
Make & Model :  
Chassis No. :**SDB 8899 M**BENTLEY / CONTINENTAL GTC  
SCBGE23W9DC081180Submit By :  
Year Manufacture :  
Engine No. :**JENNY**  
41312**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Fronty grille rubber <i>See</i>	1	\$234.00		<i>X</i>
25	Front grille emblem <i>nn</i>	1	TBA		<i>X</i>
26	Front bumper lower grille mesh LH <i>See</i>	1	\$1,224.00	<i>mtjcm</i>	<i>X</i>
27	Front bumper lower grille mesh RH <i>See</i>	1	\$1,224.00	<i>u</i>	<i>X</i>
28	Fog lamp mesh LH <i>cra</i>	1	\$756.00	<i>u</i>	<i>X</i>
29	Fog lamp mesh RH <i>cra</i>	1	\$756.00	<i>u</i>	<i>X</i>
30	Front bumper sensor <i>See</i>	6	\$1,080.00		<i>X</i>
31	Front bumper sensor cover <i>See</i>	6	\$21.60		<i>X</i>
32	LH front fender <i>By</i>	1	\$14,040.00		<i>✓</i>
33	RH front fender <i>By</i>	1	\$14,040.00		<i>✓</i>
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

LKK Auto Consultants hence notify the Repeirer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repeirer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

\* before Panel Kenneth Surveys on 17/10/11

@ 10.13



**ESTEEM**

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

## Supplementary

### Spare Parts

Vehicle No. : **SDB 8899 M**  
Make & Model : **BENTLEY / CONTINENTAL GTC**  
Chassis No : **SCBGE23W9DC081180**

Submit By : **JENNY**  
Year Manufacture : **07/02/2013**  
Engine No. :  
**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front support top panel <i>No 27 Bu</i>	1	\$864.00		✓
2	Front grille top panel <i>No 7 CM</i>	1	\$324.00		✓
3	Front grille top panel cover <i>No 6 CM</i>	1	\$360.00		✓
4	Front grille mesh side bracket LH <i>No 23 D/I</i>	1	\$153.00		✓
5	Front grille mesh side bracket RH <i>No 23 D/I</i>	1	\$153.00		✓
6	Front bumper reinforcement lower cover <i>No 15 CM</i>	1	\$270.00		✓
7	Engine oil cooler <i>No 19 Pu</i>	1	\$4,320.00		✓
8					
9					
10					
11	Front Grille mesh RH <i>CM 1</i>	1	\$1242.00		✓
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

7626





**WORKSHOP**  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

Vehicle No. : SDB 8899 M Submit By : JENNY  
Make & Model : NTLEY / CONTINENTAL GTC Year of Manufacture : 41312

[illegible]

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any*

2310