



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

are Parts

Vehicle No. :

Make & Model :

Chassis No. :

SDB 8899 M

BENTLEY / CONTINENTAL GTC

SCBGE23W9DC081180

Submit By :

JENNY

Year Manufacture :

07-Feb-13

Engine No. :

Cost / List

No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	S.N	✓ 25/12
2	Headlamp LH	1	\$9,900.00		✓
3	Headlamp RH	1	\$9,900.00		✓
4	Headlamp Chrome LH	1	\$324.00		✓
5	Headlamp Chrome RH	1	\$324.00		✓
6	Signal Lamp chrome LH	1	\$306.00		X
7	Signal Lamp chrome RH	1	\$306.00		X
8	Front support panel	1	\$2,340.00		✓
9	Front support panel lower	1	\$666.00		X
10	Condenser	1	\$1,800.00		✓
11	Radiator	1	\$2,628.00		✓
12	Radiator fan blade	1			
13	Radiator air guide RH	1	\$108.00		✓
14	Radiator air guide LH	1	\$108.00		✓
15	Front bumper	1	\$8,244.00		✓
16	Front bumper clip	10	\$200.00		✓
17	Front bumper reinforcement	1	\$2,250.00		X
18	Front bumper side retainer LH	1	\$117.00		X
19	Front bumper side retainer RH	1	\$117.00		X
20	Front bumper sponge	1	TBA		X
21	Front grille	1	\$3,960.00		✓
22	Front grille mesh	1	\$1,242.00		✓
23	Front grille chrome	1	\$1,728.00		✓

any of the quoted parts are recommended to be repaired, then an additional labour charge charged accordingly under supplementary.

Spare Parts

Vehicle No. :
Make & Model :
Chassis No :

SDB 8899 M

BENTLEY / CONTINENTAL GTC
SCBGE23W9DC081180

Submit By :
Year Manufacture :
Engine No. :

JENNY
41312

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Front grille rubber	1	\$234.00		X
25	Front grille emblem	1	TBA		X
26	Front bumper lower grille mesh LH	1	\$1,224.00	mtjcm	X
27	Front bumper lower grille mesh RH	1	\$1,224.00	5	X
28	Fog lamp mesh LH	1	\$756.00	5	X
29	Fog lamp mesh RH	1	\$756.00	5	X
30	Front bumper sensor	6	\$1,080.00		X
31	Front bumper sensor cover	6	\$21.60		X
32	LH front fender	1	\$14,040.00		✓
33	RH front fender	1	\$14,040.00		✓
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Vehicle No. : SDB 8899 M Submit By : JENNY
Make & Model : NITLEY / CONTINENTAL GTC Year of Manufacture : 41312

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any