



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Repair Estimates

SDB 8899 M

Parts	(a) Cost / List Price Items	\$ <u>80192.00</u>	44,502.00
	Plus/Less 10%	\$ <u>8019.20</u>	4,450.20
	Total of Cost / List	\$ <u>72172.80</u>	48,952.20
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$ <u>45.00</u>	45.00
	Total Parts Cost	\$ <u>72217.80</u>	48,997.20
	Labour	\$ <u>2310.00</u>	3,650.00
	Total	\$ <u>74527.80</u>	52,647.20

The above total will be subjected to 7% G.S.T.

Not Authorized
Permy Bepcin
Ex 810,000h

Name of Surveyor : Kenneth
Company : CLIC
Survey conducted on : 3/9/21 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 06 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: 3/9/21

ASS. REC. BY:

Kenneth

From:

Estim:

QP



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200006485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. :

Make & Model :

Chassis No. :

SDB 8899 M

BENTLEY / CONTINENTAL GTC

SCBGE23W9DC081180

Submit By :

JENNY

Year Manufacture :

07-Feb-13

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	S.N	✓ 25/2
2	Headlamp LH	1	\$9,900.00		✓
3	Headlamp RH	1	\$9,900.00		✓
4	Headlamp Chrome LH	1	\$324.00		✓
5	Headlamp Chrome RH	1	\$324.00		✓
6	Signal Lamp chrome LH	1	\$306.00		X
7	Signal Lamp chrome RH	1	\$306.00		X
8	Front support panel	1	\$2,340.00		X
9	Front support panel lower	1	\$666.00		X
10	Condenser	1	\$1,800.00		✓
11	Radiator	1	\$2,628.00		✓
12	Radiator fan blade	1			
13	Radiator air guide RH	1	\$108.00		✓
14	Radiator air guide LH	1	\$108.00		✓
15	Front bumper	1	\$8,244.00		✓
16	Front bumper clip	10	\$200.00		✓
17	Front bumper reinforcement	1	\$2,250.00		X
18	Front bumper side retainer LH	1	\$117.00		X
19	Front bumper side retainer RH	1	\$117.00		X
20	Front bumper sponge	1	TBA		X
21	Front grille	1	\$3,960.00		✓
22	Front grille mesh LH	1	\$1,242.00		✓
23	Front grille chrome	1	\$1,728.00		✓

te: If any of the quoted parts are recommended to be repaired, then an additional labour charge be charged accordingly under supplementary.

40466
455N

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SDB 8899 M

BENTLEY / CONTINENTAL GTC
SCBGE23W9DC081180

Submit By :
Year Manufacture :
Engine No. :
Cost / List

JENNY

41312

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Fronty grille rubber	1	\$234.00		X
25	Front grille emblem	1	TBA		X
26	Front bumper lower grille mesh LH	1	\$1,224.00	mtjcm	X
27	Front bumper lower grille mesh RH	1	\$1,224.00	5	X
28	Fog lamp mesh LH	1	\$756.00	5	X
29	Fog lamp mesh RH	1	\$756.00	5	X
30	Front bumper sensor	6	\$1,080.00		X
31	Front bumper sensor cover	6	\$21.60		X
32	LH front fender	1	\$14,040.00		✓
33	RH front fender	1	\$14,040.00		✓
34					
35					
36					
37					
38					
39	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
40					
41					
42					
43					
44					
45					
46					

If any of the quoted parts are recommended to be repaired, then an additional labour charge be charged accordingly under supplementary.

32040



176 Sin Ming Drive
Sin Ming Auto Care #01-14 , #01-15 , #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

2310

* before Panel Kenneth survey on 14/10/11

@ 10:18



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP

385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP

176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Supplementary

Spare Parts

Vehicle No. : **SDB 8899 M**
Make & Model : **BENTLEY / CONTINENTAL GTC**
Chassis No : **SCBGE23W9DC081180**

Submit By : **JENNY**
Year Manufacture : **07/02/2013**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front support top panel <i>NO-27 Bn</i>	1	\$864.00		✓
2	Front grille top panel <i>NO-7 CM</i>	1	\$324.00		✓
3	Front grille top panel cover <i>NO-6 CM</i>	1	\$360.00		✓
4	Front grille mesh side bracket LH <i>NO-23 D/I</i>	1	\$153.00		✓
5	Front grille mesh side bracket RH <i>NO-23 D/I</i>	1	\$153.00		✓
6	Front bumper reinforcement lower cover <i>CM NO-15</i>	1	\$270.00		✓
7	Engine oil cooler <i>NO-19 Pn</i>	1	\$4,320.00		✓
8					
9					
10					
11	Front Grille mesh RH <i>CM-1</i>	1	\$1242.00		✓
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

7626