

ASS. REC. BY:

REF:

C72 / CS/CTI21009284/Kvc

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. SNM21D204888/C01

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

03/09/21 @ 4.31pm revert to Chee So Chow via Merimen.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

: Prell. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
178 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Repair Estimates

SDB 8899 M

Parts	(a) Cost / List Price Items	\$	79,943.60
	Plus/Less 10%	\$	7,994.36
	Total of Cost / List	\$	71,949.24
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	45.00
Total Parts Cost		\$	71,994.24
Labour		\$	3,650.00
Total		\$	75,644.24

Not Authorised
Permy B4pain
Ex \$10,000

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKLC
Survey conducted on : _____ at 31/9/21

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 06 day(s)

(c) Resurvey : Required / Not Required Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. : **SDB 8899 M**
Make & Model : **BENTLEY / CONTINENTAL GTC**
Chassis No. : **SCBGE23W9DC081180**

Submit By : **JENNY**
Year Manufacture : **07-Feb-13**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	S.N	✓ 25/12
2	Headlamp LH	1	\$9,900.00		?
3	Headlamp RH	1	\$9,900.00		?
4	Headlamp Chrome LH	1	\$324.00		✓
5	Headlamp Chrome RH	1	\$324.00		?
6	Signal Lamp chrome LH	1	\$306.00		X
7	Signal Lamp chrome RH	1	\$306.00		Λ
8	Front support panel	1	\$2,340.00		?
9	Front support panel lower	1	\$666.00		?
10	Condenser	1	\$1,800.00		?
11	Radiator	1	\$2,628.00		?
12	Radiator fan blade	1			
13	Radiator air guide RH	1	\$108.00		?
14	Radiator air guide LH	1	\$108.00		?
15	Front bumper	1	\$8,244.00		?
16	Front bumper clip	10	\$200.00		?
17	Front bumper reinforcement	1	\$2,250.00		?
18	Front bumper side retainer LH	1	\$117.00		X
19	Front bumper side retainer RH	1	\$117.00		X
20	Front bumper sponge	1	TBA		?
21	Front grille	1	\$3,960.00		✓
22	Front grille mesh	1	\$1,242.00		✓
23	Front grille chrome	1	\$1,728.00		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SDB 8899 M

BENTLEY / CONTINENTAL GTC
SCBGE23W9DC081180

Submit By :
Year Manufacture :
Engine No. :

JENNY

41312

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Front grille rubber	1	\$234.00		?
25	Front grille emblem	1	TBA		?
26	Front bumper lower grille mesh LH <i>Ln</i>	1	\$1,224.00		X
27	Front bumper lower grille mesh RH <i>Ln</i>	1	\$1,224.00		X
28	Fog lamp mesh LH <i>Ln</i>	1	\$756.00		X
29	Fog lamp mesh RH <i>Ln</i>	1	\$756.00		X
30	Front bumper sensor	6	\$1,080.00		?
31	Front bumper sensor cover	6	\$21.60		?
32	LH front fender <i>By</i>	1	\$14,040.00		✓
33	RH front fender <i>By</i>	1	\$14,040.00		✓
34					
35					
36					
37					
38					
39	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer: Signature: Date:				
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



(M) 6494 1221 (F) 6494 7829

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to assist in the claims process.
2. This form must be completed by the Policymaker, and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy claims.
4. The sole and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the CUA Recovery Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and the copies of this report will, on a fee, be made available upon application by interested parties.
7. By the completion of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 31/08/2021 17:37 (SGT)
Date of Accident 31/08/2021 12:30 (SGT)
Exact Location of Accident Holland Rd, Singapore
Additional Location Information To Napier Road
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SDBS899M

INSURED POLICYHOLDER

Is company? No
Name Of Registered Owner Phua Raymond
NRIC No SXXXX819A
Email Address hr@davinciasia.com
Mobile Phone No (Phone) +65-96309223
Alternative Phone No +65-96309223

VEHICLE PARTICULARS

Manufacturer Bentley
Model Continental
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 5998


INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMPCSNW00148232101
Cover Note Number -

DRIVER

Name of Driver Phua Raymond
NRIC No SXXXX819A

Accident report SL03218V0008



A- SDB 2899M
B: SKV5405

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 31 August 2021 at 12:30 approximately, I was driving from Holland Road to Napier road. There was a construction on right side of road with a quick but very short notice. I noticed 2 cars ahead of me which had jammed their brakes and as the road was wet, I had to also jam my brakes, however was unable to stop the vehicle in time, hitting the car in front of me. The first car had driven off and left the scene. The driver stepped out of the second car and told me the driver in the first car had jammed his brakes, which made him do the same.

DECLARATION

I/we declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: **Angie Soh**
NRIC/FIN No.:

31 AUG 2021