



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5501C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER,REAR BUMPER	TO REPAIR SEE LABOUR	485.60	-
1	REINFORCEMENT SUB-ASSY,REAR BUMPER	TO REPAIR SEE LABOUR	332.70	-
1	GUARD,REAR BUMPER,CENTER	SERVICEABLE	374.50	-
1	COVER,REAR BUMPER,LOWER	SERVICEABLE	22.00	-
1	RETAINER,REAR BUMPER SIDE,LH	SERVICEABLE	132.60	-
1	RETAINER,REAR BUMPER SIDE,RH	SERVICEABLE	132.60	-
1	PANEL SUB-ASSY,BODY LOWER BACK	SERVICEABLE	651.00	-
1	COVER,DECK TRIM,REAR	SERVICEABLE	126.70	-
	LESS 25% DISCOUNT		-564.43	-
			1,693.27	-
<u>SPECIAL NETT ITEMS</u>				
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	85.00	-
1	BUMPER CENTRE GUARD CLIP (SN)	NOT NECESSARY	80.00	-
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	180.00	-
1	REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	75.00	-
			1,120.00	-
<u>LABOUR</u>				
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	240.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.	NOT NECESSARY	3,000.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,600.00	220.00

Report Ref No. CS/AGI21009287/Kuf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT REAR BIG & SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	300.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
			6,240.00	220.00
GRAND TOTAL			9,053.27	220.00
RECOMMENDED COST OF REPAIRS				220.00

Report Ref No. CS/AGI21009287/Kuf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.