



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD			Ref:	CS3/SMR21007329/T1uf3e2-1
60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Date:	13/09/2021
			Code:	SMR
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMB 5077G	Veh. Inspected	PC 8111E
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/07/21/5001	Excess (\$)	0.00
	Assign From	KAREN CHAN	Assign Date	03/09/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ VIANO	c.c	2143
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	WDF63981523696308	Colour	BLACK
	Odometer	336141 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/65 R16	WEST LAKE	6 mm
	L/H Front Tyre	205/65 R16	WEST LAKE	6 mm
	R/H Rear Tyre	205/65 R16	WEST LAKE	6 mm
	L/H Rear Tyre	205/65 R16	WEST LAKE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/07/2021	Inspection Date	06/07/2021
	Survey held at	BEST AUTO K PTE LTD 10 KAKI BUKIT RD 2 #03-01 SINGAPORE 417868		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	