

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

6-Sep-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8344 A

1 pc	Tailgate lower garnish	\$	362.61/Cut
1 pc	Tailgate	\$	2,292.30Xr
2 pcs	Tailgate hinge @\$28.50	\$	57.00XSUC
1 pc	Tailgate weatherstrip	\$	276.98XSUC
1 pc	Tailgate Striker	\$	36.50XSUC
1 pc	Tailgate Emblem "i30"	\$	27.80/nec
1 pc	Emblem CRDI	\$	29.40/nec
1 pc	Emblem Hyundai logo	\$	29.40/nec
1 pc	Rear bumper	\$	811.11/Def
1 pc	Rear bumper sponge	\$	79.20XSUC
1 pc	Rear bumper reinforcement	\$	815.64XSUC
1 pc	Rear bumper reinforcement centre	\$	79.20XSUC
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40XSUC
2 pcs	Rear bumper n/s & o/s reflector	\$	107.50X Side only left
		\$	5,109.04
Less 20%		\$	1,021.81
		\$	4,087.23

S/NETT

1 set	Rear bumper clips	\$	48.00/nec
1 set	Reverse sensor	\$	280.00 200 Cut
1 set	Tailgate stickers	\$	100.00/nec
1 set	Tailgate lower garnish clips	\$	38.00/nec
1 pc	Sealant	\$	50.00/nec

6-Sep-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8344 A

Sundry	\$ 50.00	<i>360 X SVC</i>
To dismantle and replace reverse sensor and test system	\$ 80.00	<i>40</i>
To dismantle and refit the inner components of the tailgate into new tailgate, test wiper motor and water etc	\$ 120.00	<i>50</i>
To dismantle and refit the rear windscreen	\$ 120.00	<i>✓</i>
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel etc	\$ 850.00	<i>360</i>
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel,	\$ 800.00	<i>360</i>
To apply rustproofing on the repaired and replaced panels	\$ 120.00	<i>40</i>
Total	\$ 6,743.23	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Thuan Lkh *[Signature]*
82235769
thuan@lkh auto-bm
6/9/21 1400
3 days up
after repair photos

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>
--