

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009300/BGA3Q2**Date:** 18/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900257928
Claimant Vehicle No :	SJT7679Y	Insured Vehicle No :	SMR551C
Date of Loss:	01/09/2021	Nature of Claim:	TP
		Claim No:	0451791380SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT7679Y	Engine No:	M16A1483534
Make & Model:	SUZUKI SWIFT, 1.6 MT (M)	Chassis No:	JSAEZC31S00204811
Reg. Date:	29/10/2009 (Man. Year: 2009)	Odometer:	225962 km
Colour:	White		
Engine Capacity:	1586 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R16	Rear Tyre Size:	205/45 R16
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,296.09	3,498.23	6,797.86	66.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,450.00	2,290.00	2,160.00	48.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,746.09	5,788.23	8,957.86	60.75
Approved Total (Overridden) (\$\$)		4,600.00		
(\$\$)	14,746.09	4,600.00	10,146.09	68.81
+ GST 7.00/7.00% (\$\$)	1,032.23	322.00	710.23	68.81
Nett Amount (\$\$)	15,778.32	4,922.00	10,856.32	68.81
+ Car Rental (10.0 x \$S\$100.00/day + 7.00% GST) (\$\$)		1,070.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		5,999.45		
Global Sum Settlement (\$\$)		5,950.00		

INSPECTION

Date of Assignment:	03/09/2021	Team Autopro Pte Ltd (sin Ming) (HQ)
Date Inspected:	06/09/2021 Inspected At:	160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
Estimated Period of Repair:	7.0 days	Singapore 575722

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	746.80 FL	*687.20 FL
2	1		*TAILGATE INNER LOCK	Jammed	221.50 FL	*105.05 FL
3	1		*TAILGATE INNER LOCK STICKER	Not Damaged	48.00 FL	*- FL
4	1		*TAILGATE INNER TRIM BOARD	Broken	284.10 FL	*195.15 FL
5	1		*TAILGATE SOLENOID SWITCH	Broken	164.00 FL	*164.00 FL
6	1		*TAILGATE WEATHERSTRIP	Torn	194.80 FL	*108.40 FL
7	1		*TAILGATE OUTER HANDLE	Not Damaged	168.00 FL	*- FL
8	1		*TAILGATE WINDSCREEN MOULDING	No such part	142.00 FL	*- FL
9	2		*TAILGATE HINGE	Not Damaged	205.00 FL	*- FL
10	1		*REAR BUMPER	Broken	680.00 FL	*546.00 FL
11	1		*REAR BUMPER LOWER SPOILER	Broken	482.60 FL	*482.60 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	224.00 FL	*70.00 FL
13	2		*REAR BUMPER REVERSE LAMP	Broken	179.20 FL	*110.00 FL
14	2		*REAR BUMPER BRACKET	Dented	136.00 FL	*92.00 FL
15	1		*REAR BUMPER TOW CAP	Missing	78.00 FL	*45.00 FL
16	2		*REAR NUMBER PLATE LAMP	Not Damaged	91.60 FL	*- FL
17	1		*REAR END PANEL	Dented	589.20 FL	*316.70 FL
18	1		*REAR END PANEL AIR VENT	Broken	84.80 FL	*29.60 FL
19	1		*SPARE TYRE PANEL	Not Damaged	683.00 FL	*- FL
20	1		*SPARE TYRE PANEL TOP BOARD	Not Damaged	206.30 FL	*- FL
21	1		*SPARE TYRE PANEL TOOLS TRAY	Not Damaged	119.80 FL	*- FL
22	1		*REAR FENDER LH	Repair	486.40 FL	*- FL
23	2		*REAR FENDER INNER TRIM BOARD	Not Damaged	397.10 FL	*- FL
24	2		*REAR FENDER INNER COWLING	Not Damaged	353.30 FL	*- FL
25	2		*TAIL LAMP	Broken	908.00 FL	*587.40 FL
26	2		*TAIL LAMP LOWER BRACKET	Not Damaged	176.00 FL	*- FL
27	2		*TAIL LAMP BASE PANEL	Not Damaged	368.00 FL	*- FL
28	2		*REAR EXHAUST PIPE MOUNTING	Not Damaged	93.60 FL	*- FL
29	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Damaged	84.30 FL	*- FL
30	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
31	1		*TAILGATE SEALANT	Necessary	100.00 FS	*40.00 FS
32	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
33	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
34	1		*TAILGATE WINDSCREEN INNER SEAL	No such part	60.00 FS	*- FS
35	1		*TAILGATE WINDSCREEN PRIMER & CLEANER	Not Necessary	80.00 FS	*- FS
36	1		*TAILGATE STICKER BOOBA	Necessary	40.00 FS	*20.00 FS
37	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
38	1		*REAR BUMPER LOWER SPOILER CLIPS	Necessary	50.00 FS	*20.00 FS
39	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
40	1		*REAR FENDER SEALANT	Not Necessary	100.00 FS	*- FS
41	2		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	100.00 FS	*- FS
42	2		*REAR FENDER INNER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
43	2		*TAIL LAMP CLIPS	Necessary	100.00 FS	*30.00 FS
44	2		*TAIL LAMP SEAL	No such part	120.00 FS	*- FS
45	2		*TAIL LAMP BASE PANEL SEALANT	Not Necessary	200.00 FS	*- FS
46	2		*REAR BUMPER REVERSE SENSOR	Scratched	500.00 FS	*200.00 FS
47	1		*REAR NUMBER PLATE W/CASING	Broken	80.00 FS	*50.00 FS
48	1		*REAR EXHAUST PIPE	Not Damaged	980.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,585.40	4,029.10
- List Item Discount on L Items 15.00/15.00% (\$\$)	1,289.31	530.87
Total Parts (\$\$)	10,296.09	3,498.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
4	R&R REAR EXHAUST PIPE	New	150.00	0.00
5	UPHOLSTERY	New	300.00	0.00
6	CHECK WIRING	New	100.00	30.00
7	PANEL BEATING	New	1,600.00	1,000.00
8	RUST PROOFING	New	200.00	0.00
9	SPRAY PAINTING	New	1,600.00	1,000.00
Gross Labour Cost (S\$)			4,450.00	2,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >