



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
NEW HOCK TECK MOTOR PTE LTD			Ref:	CS/TP21009308/Atce2
BLK 1 KAKI BUKIT AVE 6 #01-43 SINGAPORE 417883			Date:	12/10/2021
ON BEHALF OF AH SENG STAINLESS STEEL PTE LTD			Code:	TP199
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SMA 4194M	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	03/09/2021	
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA WISH	c.c	1794
	Engine No.	HIDDEN	Year of Reg.	2006
	Chassis No.	ZNE100319776	Colour	BLACK
	Odometer	291774 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/45 R17	TOURADOR	6 mm
	L/H Front Tyre	215/45 R17	TOURADOR	6 mm
	R/H Rear Tyre	215/45 R17	TOURADOR	6 mm
	L/H Rear Tyre	215/45 R17	TOURADOR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
	DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/08/2021	Inspection Date	03/09/2021
	Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	