



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 30/08/2021

Estimated repair cost for vehicle no: SMA4194M TOYOTA WISH 1.8XA

CHASSIS: ZNE100319776 (2006)

TP Tokio Marine
Independent
Deviser.

01/09/2021

S/N	Qty	Items	U/price	Amount
1	1	RH FRONT DOOR <i>Distorted</i>	\$1,277.90	\$1,277.90 ✓
2	1	RH FRONT DOOR LOCK <i>Repd</i>	\$350.60	\$350.60 ✓
3	1	RH FRONT DOOR WEATHER STRIPE <i>Repl</i>	\$215.60	\$215.60 +
4	1	RH FRONT DOOR INNER TRIM BOARD <i>Repl</i>	\$412.30	\$412.30 +
5	1	RH FRONT DOOR POWER WINDOW MOTOR <i>Repl</i>	\$589.60	\$589.60 +
6	1	RH FRONT DOOR POWER WINDOW GEAR <i>Repl</i>	\$458.60	\$458.60 +
7	1	RH REAR DOOR <i>Distorted</i>	\$1,277.90	\$1,277.90 ✓
8	1	RH REAR DOOR LOCK <i>Repl</i>	\$350.60	\$350.60 +
9	1	RH REAR DOOR WEATHER STRIPE <i>Repl</i>	\$215.60	\$215.60 +
10	1	RH REAR DOOR INNER TRIM BOARD <i>Repl</i>	\$412.30	\$412.30 +
11	1	RH REAR DOOR POWER WINDOW MOTOR <i>Repl</i>	\$589.60	\$589.60 +
12	1	RH REAR DOOR POWER WINDOW GEAR <i>Repl</i>	\$458.60	\$458.60 +
13	1	RH ROCKER PANEL <i>Repl</i>	\$789.20	\$789.20 +
14	1	RH DOOR CENTER PILLAR <i>Repl</i>	\$468.60	\$468.60 +
15	1	RH REAR FENDER <i>Repl</i>	\$1,265.60	\$1,265.60 +
16	1	REAR BUMPER <i>Repl</i>	\$654.10	\$654.10 +
17	1	RH REAR BUMPER SIDE RETAINER <i>Repl</i>	\$45.80	\$45.80 +

2906.40

2179.80

TOTAL :	\$9,832.50
LESS 25 %	\$2,458.13
SUB-TOTAL :	\$7,374.38

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	RH REAR SPORT RIM <i>cut</i>	\$350.00	\$350.00 ✓

350

TOTAL:	\$350.00
TOTAL PARTS	\$7,724.38

Labour charges

1	LABOUR FOR PANEL BEATING	\$1,000.00	900
2	LABOUR FOR SPRAYPAINTING	\$1,000.00	900
3	LABOUR FOR REMOVE / RENWE & TRANSFER RH BOTH DOORS FITTING	\$300.00	160
4	TO CONDUCT WHEEL ALIGNMENT	\$150.00	80
5	WIRING CHECK	\$80.00	30
6	TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS	\$300.00	100
7	LABOUR FOR REMOVE & REFIX REAR UPHOLSTERY / ROOF LINING CARPET	\$250.00	60
Subtotal :-		\$3,080.00	
Total:-		\$10,804.38	

Adrian Lj
 1/s 03/09/21
 07 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Total: 4755.80
 1/s: 3.8k
 (3.8k)