

FASTECH AUTO PTE LTD

PAGE 1 OF 4

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Reg No: 200006262D

Estimate : 22561

TP A16

Ashes

Date : 02.09.2021

Vehicle Num : SKS 6848B

Make/Model : VOLKSWAGEN JETTA 1.4

Chassis/Engine no :

Accident Date : 02.09.2021

Claim No : 0921-22561

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Front bonnet <i>Buckled</i>	\$ 1,120.00 ✓
1 pc	Front bonnet lock <i>Dented</i>	\$ 209.30 ✓
1 pc	Front bonnet lock catch <i>New</i>	\$ 91.80 +
1 pc	Front bonnet lock cable <i>New</i>	\$ 42.80 +
2 pc	Front bonnet hinge @ 86.50 <i>Best</i>	\$ 173.00 ✓
1 pc	Front bonnet absorber <i>New</i>	\$ 126.50 +
1 pc	Front bonnet insulator <i>crumpled.</i>	\$ 392.10 ✓
1 pc	Front bonnet seal <i>New</i>	\$ 32.50 +
2 pc	Front bonnet stopper @ 18.70 <i>New</i>	\$ 37.40 +
2 pc	Front fender @ 579.60 <i>Buckled</i>	\$ 1,159.20 ✓
2 pc	Front fender cowling @ 292.10 <i>Not New</i>	\$ 584.20 +
2 pc	Head lamp @ 1690.60 <i>cracked.</i>	\$ 3,381.20 ✓
1 pc	Radiator grille <i>cracked</i>	\$ 551.50 ✓
1 pc	Radiator grille emblem <i>New</i>	\$ 148.75 ✓
1 pc	Front bumper <i>Distorted</i>	\$ 1,348.40 ✓
2 pc	Front bumper retainer @ 157.10 <i>Not New</i>	\$ 314.20 +
1 pc	Front bumper reinforcement <i>Dented</i>	\$ 762.50 ✓
1 pc	Front bumper absorber <i>cracked.</i>	\$ 278.75 ✓
1 pc	Front bumper lower grille <i>New</i>	\$ 862.50 +
1 pc	Front number plate garnish <i>cracked</i>	\$ 143.10 ✓
2 pc	Front fog lamp cover @ 75.10 <i>New</i>	\$ 150.20 +
1 pc	Front support panel <i>cracked.</i>	\$ 1,151.50 ✓
2 pc	Front head lamp panel @ 56.20 <i>Buckled</i>	\$ 112.40 ✓
1 pc	Aircon condenser assy <i>Dented</i>	\$ 756.25 ✓
1 pc	Radiator assy <i>Dented</i>	\$ 712.50 ✓
1 pc	Radiator fan cowling <i>New</i>	\$ 240.90 +
2 pc	Radiator fan motor assy @ 826.50 <i>New</i>	\$ 1,653.00 +
1 pc	Water cooler <i>Dented</i>	\$ 846.50 ✓
1 pc	Radiator tank <i>New</i>	\$ 160.00 +
1 pc	Radiator top hose <i>New</i>	\$ 162.80 +
		\$ 17,705.75

FASTECH AUTO PTE LTD

PAGE 2 OF 4

1 Kaki Bukit Ave 6 #01-48 Autobay**Singapore 417883****Tel No: 67452063 / 67467158 Fax No: 67458520****Reg No: 200006262D**

Estimate : 22561

Date : 02.09.2021

Vehicle Num : SKS 6848B

Make/Model : VOLKSWAGEN JETTA 1.4

Chassis/Engine no :

Accident Date : 02.09.2021

Claim No : 0921-22561

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Air cleaner box assy <i>cracked.</i>	\$ 435.00 ✓
1 pc	Driver air bag	\$ 3,553.85 ✓
1 pc	Driver air bag spiral wire	\$ 1,031.25 ✓
1 pc	Front passanger air bag	\$ 3,260.00 ✓
1 pc	Air bag module (ECU)	\$ 2,670.40 ✓
1 pc	Front dashboard <i>to r</i>	\$ 3,344.00 ✓
2 pc	Front safety belt @ 1470.00 <i>Activated</i>	\$ 2,940.00 ✓
2 pc	Front safety belt buckle @ 650.00 <i>Activated</i>	\$ 1,300.00 ✓
1 pc	Front windscreen glass <i>cracked.</i>	\$ 1,460.00 ✓
1 pc	Rear boot lid <i>Distorted.</i>	\$ 1,459.70 ✓
2 pc	Rear boot lid hinge @ 226.30 <i>new</i>	\$ 452.60 +
1 pc	Rear boot lid inner lock <i>Damaged</i>	\$ 180.90 ✓
1 pc	Rear boot lid inner board <i>new</i>	\$ 294.40 +
1 pc	Rear boot lid logo <i>new</i>	\$ 189.30 ✓
1 pc	Rear boot lid emblem (jetta) <i>new</i>	\$ 68.10 ✓
1 pc	Rear boot lid emblem (isi)	\$ 52.30 ✓
2 pc	Rear boot lid lamp @ 258.10 <i>cracked.</i>	\$ 516.20 ✓
2 pc	Tail lamp @ 418.80 <i>cracked.</i>	\$ 837.60 ✓
2 pc	Rear fender @ 1710.90 <i>Reps</i>	\$ 3,421.80 +
2 pc	Rear fender inner garnish @ 301.90 <i>new</i>	\$ 603.80 +
2 pc	Rear tail lamp panel @ 304.00 <i>Reps</i>	\$ 608.00 +
1 pc	Rear bumper diffuse <i>Del'd</i>	\$ 455.70 ✓
1 pc	Rear bumper <i>Dist'd.</i>	\$ 1,806.20 ✓
1 pc	Rear bumper towing cover <i>del'd</i>	\$ 34.70 ✓
1 pc	Rear bumper reinforcement <i>Del'd</i>	\$ 354.70 ✓
1 pc	Rear bumper centre retainer <i>Del'd</i>	\$ 89.10 ✓
2 pc	Rear bumper retain @ 49.70 <i>new</i>	\$ 99.40 ✓
2 pc	Rear bumper reflector @ 42.10 <i>new</i>	\$ 84.20 +
2 pc	Rear number lamp @ 35.60	\$ 71.20 +
1 pc	End panel outter <i>Distorted</i>	\$ 765.60 ✓
1 pc	End panel inner <i>Reps</i>	\$ 517.20 ✓
		\$ 32,957.20

FASTECH AUTO PTE LTD

PAGE 3 OF 4

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Reg No: 200006262D

Estimate : 22561

Date : 02.09.2021

Vehicle Num : SKS 6848B

Make/Model : VOLKSWAGEN JETTA 1.4

Chassis/Engine no :

Accident Date : 02.09.2021

Claim No : 0921-22561

Reference :

Policy No :

Qty	Particular	Amount S\$
-----	------------	------------

List Item :

1 pc End panel garnish	Defend	\$	506.20 ✓
1 pc Spare tyre panel	Ryis	\$	1,095.30 +
1 pc Spare tyre panel cover board	Defend	\$	581.30 ✓
1 pc Rear exhaust pipe	Free new	\$	1,106.30 +
1 pc Rear exhaust pipe heat shield		\$	143.40 +
2 pc Rear exhaust pipe mounting @ 57.20		\$	114.40 +
List Item Total		\$	54,209.85
Discount 10%		\$	5,420.99
		\$	48,788.87

39938.45
35544.60

Special Nett Item:

1 pc Front number plate	3and	\$	45.00 ✓
1 pc Rear number plate		\$	45.00 ✓
1 pc Front IU bracket	new	\$	35.00 ✓
1 set Front windscreen glass sealant	new	\$	100.00 60
Total Special Nett Item		\$	225.00

185

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Reg No: 200006262D

PAGE 4 OF 4

Estimate : 22561

Date : 02.09.2021

Vehicle Num : SKS 6848B

Make/Model : VOLKSWAGEN JETTA 1.4

Chassis/Engine no :

Accident Date : 02.09.2021

Claim No : 0921-22561

Reference :

Policy No :

Qty	Particular	Amount S\$
-----	------------	------------

Labour Charge:

To check wiring and reset	\$	650.00	200
Tuff kote	\$	350.00	80
Remove and replace aircon condenser & reill gas	\$	250.00	60
Remove and replace radiator	\$	100.00	60
Remove and replace front windscreen	\$	160.00	120
Remove and replace dashboard	\$	450.00	220
Remove and refix upholstery	\$	160.00	80
Remove and replace air bag	\$	550.00	380
To remove and replace spare part and panel beating	\$	4,800.00	2000
To spray paint effected portion	\$	3,000.00	1800
Total Labour Charge	\$	10,470.00	

E & O . E

Total Amount : \$ 59,483.87

FASTECH AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

total: 41129.60

L/S: 13.51K.
(Nett Value)

Repair time 18 Days