

Accident Assist SG

24 Sin Ming Lane #01-94 Midview City Singapore 573970

Tel: 6334 1182 Email: management@assist.com

Registration no. : FBS3360G / Yamaha NMAX 155 ABS CVT

Date : 02-Sep-21

Estimate No. : AAS005_FBS3360S NMAX

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

- | | | |
|----|------|---|
| 1 | 1 | Handle bar |
| 2 | 1set | Handle bar bracket |
| 3 | 1set | Handle grip |
| 4 | 1set | Handle balancer |
| 5 | 1set | Rear view mirror |
| 6 | 1 | Rear brake lever |
| 7 | 1 | Steering stem |
| 8 | 2 | Front fork @ \$914.25 |
| 9 | 1 | Front fork bracket |
| 10 | 1 | Front disc rotor |
| 11 | 1 | Front brake caliper |
| 12 | 1 | Front rim |
| 13 | 1 | Front rim shaft |
| 14 | 1 | Front fender |
| 15 | 1 | Front signal light LH |
| 16 | 1 | Front side fairing LH |
| 17 | 1 | Front side leg shield cowling LH |
| 18 | 1 | Front side leg shield cowling emblem LH |
| 19 | 1 | Side fairing lower LH |
| 20 | 1 | Side fairing centre LH |
| 21 | 1 | Front footrest board LH |
| 22 | 1 | Rear footrest LH |
| 23 | 1 | Rear side fairing LH |
| 24 | 1 | Rear side fairing emblem LH |
| 25 | 1 | Rear side cowling LH |
| 26 | 1 | Side stand |
| 27 | 1 | Main stand |
| 28 | 1 | Headlight |
| 29 | 1 | Headlight stay |
| 30 | 1 | Taillight |
| 31 | 1 | Air filter outer cover |
| 32 | 1 | Crank pulley cover |
| 33 | 1 | Exhaust muffler protector |

2021

194.20	✓ 194.20	} BT ✓
92.50	✓ 92.50	} NE ✓
	76.00	NNX
	84.00	cut ✓
60.00	✓ 95.00	cut ✓
95.00	✓ 92.70	cut ✓
41.00	582.00	
	1828.50	} NDX
	559.20	
	169.30	} NDX
	253.70	
	820.00	NDX
	78.00	NNX
	✓ 183.50	cut ✓
	89.00	NDX
	✓ 193.80	cut ✓
	✓ 145.00	cut ✓
	✓ 45.00	NEC ✓
	✓ 132.50	} cut ✓
	✓ 155.00	
	142.40	NDX
	70.00	96.50 cut ✓
	✓ 178.00	cut ✓
	60.00	90.00 NEC ✓
	✓ 75.00	cut ✓
	69.30	✓ 69.30 cut ✓
	147.80	177.00 cut ✓
	520.00	752.70 cut ✓
		84.00 NDX
	285.00	569.00 BR ✓
	✓ 82.00	cut ✓
	✓ 132.00	cut ✓
	✓ 72.00	cut ✓
	<u>8388.80</u>	

3030.60

Less 10%

303.06

838.88

2727.54

7549.92

Accident Assist SG

24 Sin Ming Lane #01-94 Midview City Singapore 573970
Tel: 6334 1182 Email: management@assist.com

Registration no. : FBS3360S / Yamaha NMAX 155 ABS CVT
Date : 02-Sep-21 Estimate No. : AAS005_FBS3360S_NMAX

S/N	Qty	Item	Amount
-----	-----	------	--------

SPECIAL NETT ITEMS

1	1	Sundries	50.00 NNX
2	1	Rear number plate	20.00 40.00 BT✓
3	1	Steering cone bearing	60.00 NNX
4	1	Front fork oil	68.00 NNX
5	1	Front tyre	110.00 NDX
6	1set	Front footrest floor mats (Accessories)	187.60 NNX
* 7 1 rear tyre			20.00
PART TOTAL			8904.40

LABOUR & MISC CHARGES

1	To remove/replace damaged parts & components.	300.00	400.00
2	To carry out body frame alignment		350.00 NNX
3	To respray replaced & affected parts.	400.00	500.00 ✓
LABOUR TOTAL		700.00	1250.00

Total Parts and Labour Cost of Repair

10154.40

Survey 1/9/2021
1335 hrs
Touin Min
Resurveys 16/9/2021
1245 hrs
Touin Min
Lump sum repair
Repair days 4

Parts 2727.54
SN 20.00
Labour 700.00
3747.54
@20% 689.51
2758.03

LS 2750/2

Touin Min

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: