

Date : 17 June 2019

To

: NTUC Income Insurance Co-operative Limited

73 Bras Basah Road #05-01 NTUC Trade Union House

Singapore 189556

Attn : Ms Corinne Hoo

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08, Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 6849 9155

info@ajaxinspection.com

Invoice No - AV19831 Company Reg No -201318067R GST Reg No - 201318067R

#### TAX INVOICE

YOUR REF / CLAIM NUMBER : MT/1043109-001

OUR REF : AVS2019-18867/SA

TP VEHICLE NO : FBN8491R

CLAIM TYPE : PRE-REPAIR SURVEY

DATE OF SURVEY : 07 May 2019

No. Description

1 Professional fee

Amount (S\$)

50.00

1 8 JUN 2019

MOTOR CLAIM

 Subtotal
 50.00

 GST 7.00%
 3.50

 Total
 53.50

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows: Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd Account No: 450-309-276-4

Email remittance advice to: accounts@ajaxadjusters.com



#### PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Ms Corinne Hoo

Assign Date:

06/05/2019

Survey Date:

07/05/2019

Accident Date:

30/04/2019

TP Policy No:

NA

Our Ref: Your Ref: AVS2019-18867/SA

Place of Survey:

Yong Seng Heng Motor Services

5 Soon Lee Street, #01-12 Pioneer Point

MT/1043109-001

Singapore

627607

Claim Type:

Third Party

Description of Vehicle:

Veh. No:

FBN8491R

Make/Model:

Yamaha 135

Colour: **Engine Capacity:** 

Black NA

**Engine No:** Chassis No: NA NA

Odometer:

NA

Reg. Date:

NA

Condition of Vehicle:

General:

Good

Modification:

No

Steering:

Paint work:

Affected Good

Handbrake: Tyre Make:

Front Tyre Size:

Rear Tyre Size:

Affected Dunlop

80/90/16 80/90/16

Front Side: Rear Side:

Footbrake:

6mm

6mm

Affected

#### Description of Damage:

The vehicle sustained damage on the left and right portions.

The box comportment, footrest, footrest bracket, clutch lever, centre console, mudguard, fork assy and sport rim were among the items affected.

#### Remarks:

Based on visual survey of the vehicle without any repair estimate provided, we viewed that the repair cost should not be more than \$\$2,200.00 and could take approximately four (4) working days to complete.

Adjuster:

Motor Appraiser

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

AVS2019-18867/SA

Your Ref: MT/1043109-001

Pre-repair survey













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref: Your Ref: AVS2019-18867/SA MT/1043109-001

Pre-repair survey













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

# AJAX Inspection Services Pte Ltd

Our Ref:

AVS2019-18867/SA

Your Ref: MT/1043109-001

Pre-repair survey













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



Our Ref: Your Ref: AVS2019-18867/SA MT/1043109-001

Re-survey items













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

### **AJAX Inspection Services Pte Ltd**

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155 Email: info@ajaxinspection.com Website:www.ajaxadjusters.com Co. Reg. No.: 201318067R

## AJAX Inspection Services Pte Ltd

Our Ref:

AVS2019-18867/SA

Your Ref: MT/1043109-001

Re-survey items













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

## AJAX Inspection Services Pte Ltd


Our Ref: Your Ref: AVS2019-18867/SA MT/1043109-001

Re-survey items













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



Our Ref: Your Ref: AVS2019-18867/SA MT/1043109-001

Post repair survey









Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.