

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121009318/UVF3N2**Date:** 24/09/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SJC4150P **Insured Vehicle No :** YQ9889H

Date of Loss: 03/09/2021 Nature of Claim: TP Claim No: CDMCG21001716

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJC4150P**

Make & Model: MITSUBISHI LANCER, 1.6 (A) Engine No: 4G18JP0604

Reg. Date: 18/02/2008 (Man. Year: 2007) Chassis No: JMYSTCS3A8U006091

Colour: Black Odometer: 123378 km

Engine Capacity: 1584 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R15 Rear Tyre Size: 195/60R15

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,115.00	954.90	2,160.10	69.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	820.00	630.00	43.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,565.00	1,774.90	2,790.10	61.12
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	4,565.00	1,400.00	3,165.00	69.33
+ GST 7.00/7.00% (S\$)	319.55	98.00	221.55	69.33
Nett Amount (S\$)	4,884.55	1,498.00	3,386.55	69.33

INSPECTION

Date of Assignment: 06/09/2021

Date Inspected: 06/09/2021 Inspected At: Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2021)
Parts:	143	MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJC4150P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER N/S	Repair	516.00 F	*- FL
2	1		*FRONT FENDER OUTER CHROME MOULDING N/S	Necessary	68.00 F	*58.00 FL
3	1		*FRONT DOOR N/S	Repair	808.00 F	*- FL
4	1		*FRONT DOOR OUTER CHROME MOULDING N/S	Necessary	166.00 F	*138.00 FL
5	1		*FRONT DOOR MIRROR ASSY N/S	Cracked	850.00 F	*450.00 FL
6	1		*FRONT DOOR GLASS OUTER MOULDING N/S	Serviceable	162.00 F	*- FL
7	1		*FRONT DOOR GLASS N/S	Cut	545.00 F	*415.00 FL
					Sub Total (\$\$)	3,115.00 1,061.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 106.10
					Total Parts (\$\$)	3,115.00 954.90

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	60.00	0.00
3	TO TRANSFER FRONT DOOR MECHANISM	New	60.00	0.00
4	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	480.00	280.00
5	TO PUTTY & SPRAY PAINTING	New	800.00	520.00
Gross Labour Cost (\$)			1,450.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >