

ADD. NEW, BY:

Steve

CS/AIG 2100 9331 /ETF3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TPRES/OD-RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

at

Insured:

Policy No.

7210030818

Claims No.

3874305146SG

Sum Insured:

Excess:


\$S\$300.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

SIA / PR Seen

Consistent? : Yes or No

Est. Repair:

days

Res.:

Yes or No

Sum Sum

%

3 Val.:

Yes or No

GA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

MV 115K

part by part \$13521.97, 15days

red: 7593.03: 35%

via/Time, File, Ross 107

☐ : Prel. Report
☐ : Final Report

Days Of Repair:

15

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐ : Site Insp (\$
☐ : Interview (\$
☐ : Tech. Inve (\$
☐ : Weekend (\$

\$ + RS \$

Private

Others

TOTAL

via/Time, File, Ross 107

via/Time, File, Ross 107

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
MAZLAN BIN RAKIMAN 640 JURONG WEST STREET 61 #07-16 SINGAPORE 640640 Contact No	<table border="1"> <tr> <td>Cust No/Name</td><td>KCV18967/MAZLAN BIN RAKIMAN</td></tr> <tr> <td>Reg No/Reg Date</td><td>SGS4242J / 26/03/202</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>GF7W0701101</td></tr> <tr> <td>Engine No</td><td>4J11DA5541</td></tr> <tr> <td>Make/Model</td><td>MIT/2OMY OUTLANDER 2.0 CVT MODERN (</td></tr> <tr> <td>Colour/Trim</td><td>U02 STERLING SILVER/ BK BLACK</td></tr> </table>	Cust No/Name	KCV18967/MAZLAN BIN RAKIMAN	Reg No/Reg Date	SGS4242J / 26/03/202	Date In/Mileage	/ 0	Chassis No	GF7W0701101	Engine No	4J11DA5541	Make/Model	MIT/2OMY OUTLANDER 2.0 CVT MODERN (Colour/Trim	U02 STERLING SILVER/ BK BLACK
Cust No/Name	KCV18967/MAZLAN BIN RAKIMAN														
Reg No/Reg Date	SGS4242J / 26/03/202														
Date In/Mileage	/ 0														
Chassis No	GF7W0701101														
Engine No	4J11DA5541														
Make/Model	MIT/2OMY OUTLANDER 2.0 CVT MODERN (
Colour/Trim	U02 STERLING SILVER/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
KCV18967	CRDVCH	06/09/2021/ 11:07	BLC	442 / CocoLu	14980				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000					3	X	450	1350	2700.00
RENEW FRT BUMPER, BONNET, FRT SUPPORT PANEL, FRT FENDER LH									
WHEELHOUSING LH, REPAIR FRT DOOR LH, A-PILLAR LH									
E PNT98000					7	X	350	2450.00	
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT SUPPORT PANEL, FRT FENDER LH									
FRT DOOR LH, A-PILLAR LH, WHEELHOUSING LH									
E PNT88000								100.00	
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR (photo)									
M SUNDRY								50.00	
FRT NUMBER PLATE WITH FRAME BR									
M SUNDRY								40 80.00	
APPLY SEALANT FOR ACCIDENT PORTION									
A 54900099								80.00	
TOP UP AIRCON GAS									
A 54900099								30.00	
CHECK WIRING & ELECTRICAL SYSTEM									
A 10028901								120.00	
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM									
B WHEELALIGNMENT								120.00	
To Conduct Computerize Full Wheel Alignment									
M SUNDRY								20.00	
Sundry									
A 54900099								450.00	
TRANSFER MAIN WIRE & RELAYS (photo)									
M FACE,FR BUMPER BR					1.00	863.00	00.00	863.00	
M EXTENSION,FR BUMPER BR					1.00	517.00	00.00	517.00	
M BRACKET,FR BUMPER SIDE,RH BR					1.00	18.00	00.00	18.00	
M BRACKET,FR BUMPER SIDE,LH BR					1.00	18.00	00.00	18.00	
M GARNISH,FR BUMPER,LH CUT (chrome)					1.00	48.00	00.00	48.00	
M BRKT,FR BUMPER SIDE,LWR LH MIS					1.00	6.00	00.00	6.00	
M MOULDING,FR BUMPER,LH MIS					1.00	97.00	00.00	97.00	
M MOULDING,FR WHEEL ARCH,LH MIS					1.00	168.00	00.00	168.00	
M REINFORCEMENT,FR BUMPER BT					1.00	510.00	00.00	510.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address		Owner Name & Vehicle Info	
MAZLAN BIN RAKIMAN		Cust No/Name	KCV18967/MAZLAN BIN RAKIMAN
640 JURONG WEST STREET 61		Reg No/Reg Date	SGS4242J / 26/03/202
#07-16		Date In/Mileage	/ 0
SINGAPORE 640640		Chassis No	GF7W0701101
Contact No		Engine No	4J11DA5541
		Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (
		Colour/Trim	U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
KCV18967	CRDVCH	06/09/2021/ 11:07	BLC	442 / CocoLu	14980	
Description of Goods / Services						Amount
	Qty	Unit Price	Disc%			
M REINF,F/BMPR SIDE,LWRLH	1.00	25.00	00.00			25.00
M REINFORCEMENT,FR BUMPER	1.00	135.00	00.00			135.00
M REINFORCEMENT,FR BMPR SIDE	1.00	22.00	00.00			22.00
M REINF,FR BUMPER SIDE,LH	1.00	60.00	00.00			60.00
M GRILLE ASSY,RADIATOR	1.00	550.00	00.00			550.00
M COVER,FR BUMPER	1.00	25.00	00.00			25.00
M COVER,HEADLAMP SUPT PANEL	1.00	50.00	00.00			50.00
M BRACKET,RADIATOR GRILLE,LH	1.00	13.00	00.00			13.00
M REINFORCEMENT,FR BUMPER	1.00	510.00	00.00			510.00
M REINF,F/BMPR SIDE,LWRLH	1.00	25.00	00.00			25.00
M REINFORCEMENT,FR BUMPER	1.00	135.00	00.00			135.00
M REINFORCEMENT,FR BMPR SIDE	1.00	22.00	00.00			22.00
M REINF,FR BUMPER SIDE,LH	1.00	60.00	00.00			60.00
M GRILLE ASSY,RADIATOR	1.00	550.00	00.00			550.00
M COVER,FR BUMPER	1.00	25.00	00.00			25.00
M COVER,HEADLAMP SUPT PANEL	1.00	50.00	00.00			50.00
M BRACKET,RADIATOR GRILLE,LH	1.00	13.00	00.00			13.00
M HOOD	1.00	980.00	00.00			980.00
M HINGE,HOOD,RH	1.00	68.00	00.00			68.00
M HINGE,HOOD,LH	1.00	68.00	00.00			68.00
M INSULATOR,HOOD	1.00	133.00	00.00			133.00
M WEATHERSTRIP,HOOD,RR	1.00	36.00	00.00			36.00
M ROD,HOOD SUPPORT	1.00	24.00	00.00			24.00
M LATCH,HOOD	1.00	76.00	00.00			76.00
M WEATHERSTRIP,HOOD	1.00	40.00	00.00			40.00
M WEATHERSTRIP,HOOD	1.00	41.00	00.00			41.00
M FENDER,FR LH	1.00	622.00	00.00			622.00
M INSULATOR,FR FENDER,LH	1.00	60.00	00.00			60.00
M SHIELD,FR WHEELHOUSE,LH	1.00	164.00	00.00			164.00
M CLIP,ENG ROOM COVER	15.00	2.00	00.00			30.00
M CLIP,RR BUMPER	10.00	3.00	00.00			30.00
M PANEL,HEADLAMP SUPPORT,UPR	1.00	183.00	00.00			183.00
M PNL,HEADLAMP SUPT,UPR LH	1.00	58.00	00.00			58.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
MAZLAN BIN RAKIMAN		Cust No/Name	KCV18967/MAZLAN BIN RAKIMAN
640 JURONG WEST STREET 61		Reg No/Reg Date	SGS4242J / 26/03/202
#07-16		Date In/Mileage	/ 0
SINGAPORE 640640		Chassis No	GF7W0701101
Contact No		Engine No	4J11DA5541
		Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (
		Colour/Trim	U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV18967	CRDVCH	06/09/2021/ 11:07	BLC	442 / CocoLu	14980

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M PANEL, HEADLAMP SUPPORT, LWR	1.00	147.00	00.00	147.00
M EXTENSION, FR SIDEMEMBER, LH	1.00	58.00	00.00	58.00
M GARNISH, FR DECK	1.00	173.00	00.00	173.00
M COVER, FR DECK, LH	1.00	19.00	00.00	19.00
M HEADLAMP ASSY, LH	1.00	1948.00	00.00	1948.00
M LAMP ASSY, FOG, FR LH	1.00	350.00	00.00	350.00
M COVER, RELAY BOX	1.00	52.00	00.00	52.00
M BOX ASSY, RELAY	1.00	409.00	00.00	409.00
M CONDENSER ASSY, A/C REFRIGE	1.00	861.00	00.00	861.00
M RADIATOR ASSY	1.00	1020.00	00.00	1020.00
M INSULATOR, RDTR SUPPORT, UPR	2.00	9.00	00.00	18.00
M INSULATOR, RDTR SUPPORT, LWR	2.00	10.00	00.00	20.00

Estimate

Steve CLKK)
6/9/21, 2.12pm

OD - 11/1 AL
Excess - ?
P/P

My Bel Spj
12 dgs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices subject to change without prior notice

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Nett	18,403.00
7% GST on	18403.00
Total Payable	19,691.21

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 06/09/2021 11:44 (SGT)
Date of Accident 04/09/2021 14:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information AYE TOWARDS BUONA VISTA
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGS4242J

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner MAZLAN BIN RAKIMAN
NRIC No SXXXX086G
Email Address MAZLAN0716@YAHOO.COM.SG
Mobile Phone No (Phone) +65-96608475
Alternative Phone No (Home) +65-96608475

VEHICLE PARTICULARS

Manufacturer Mitsubishi
Model Outlander
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 2000

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 7210030818
Cover Note Number -

DRIVER

Name of Driver MAZLAN BIN RAKIMAN
NRIC No SXXXX086G

Date Of Birth	01/06/1962
Occupation	Indoor
Date Of Driving Pass	28/04/1999
Driving experience	22 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96608475
Alt. Phone Number	(Home) +65-96608475
Email Address	MAZLAN0716@YAHOO.COM.SG
Address	BLK 640 JURONG WEST ST 61
Address complement	#07-16
Postcode	640640
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	Yes

PASSENGER 1

Name	NORSEMAH BINTE JAMAAH
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHMENTS.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMY417X
Vehicle Manufacturer	Honda
Vehicle Model	Shuttle
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

HELMI

(Phone) +65-87175650

NTUC Income Insurance Co-operative Ltd

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

On Saturday, 4 Sep 21, at about 2.30 pm, while I was driving with my wife, on the way to city, via A7B, we got the accident. It happened so fast.


I drove 80 km/h on 1st lane. The road is clear on ^{my} the lane. Suddenly, I saw four cars down in front of us. I did my best to brake but failed to stop immediately. I hit the car of Harder Shuttle, vehicle no. SMY 417X.


No injuries for 2 parties.


Before that near Clement Ave, there was also an accident which was parked at the shoulder.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



CERTIFICATE OF INSURANCE

CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : MAZLAN BIN RAKIMAN
 Period of Insurance : 26 Mar 2021 To 25 Mar 2022
 Engine No. : 4J11DA5541
 Chassis No. : GF7W0701101

Vehicle No. : SGS4242J
 Policy No. : 7210030818
 Endorsement No. :
 Issued Date : 08 Apr 2021

ABOUT THE COVER

Make/Model : MITSUBISHI OUTLANDER 2.0 MODERN / STYLE
 Engine Capacity/Tonnage : 1,998.00 CC
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive* :
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2021
 Insuring with COE/PAFF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Mileage Condition : Unlimited Mileage

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 150000 - 160000

* Limitations rendered imperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Section 55 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2

Property Damage - \$0

Windscreen - \$100

Named Driver and Excess (where applicable)

MAZLAN BIN RAKIMAN - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

- 1 Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 676338 66684501
- 2 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 335 Ubi Rd 3 Singapore 409650 87481900
- 3 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 150054 64705686
- 4 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 820 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0660720811

CYCLE & CARRIAGE - BRUCE

239 ALEXANDRA ROAD
 SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

SUCKA