

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MAZLAN BIN RAKIMAN 640 JURONG WEST STREET 61 #07-16 SINGAPORE 640640 Contact No	Cust No/Name KCV18967/MAZLAN BIN RAKIMAN Reg No/Reg Date SGS4242J / 26/03/202 Date In/Mileage / 0 Chassis No GF7W0701101 Engine No 4J11DA5541 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN (Colour/Trim U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
KCV18967	CRDVCH	06/09/2021/ 11:07	BLC	442 / CocoLu	14980				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000					3	X	450	1350	2700.00
RENEW FRT BUMPER, BONNET, FRT SUPPORT PANEL, FRT FENDER LH									
WHEELHOUSING LH, REPAIR FRT DOOR LH, A-PILLAR LH									
E PNT98000					7	X	350	2450.00	
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT SUPPORT PANEL, FRT FENDER LH									
FRT DOOR LH, A-PILLAR LH, WHEELHOUSING LH									
E PNT88000								100.00	
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR (photo)									
M SUNDRY								50.00	
FRT NUMBER PLATE WITH FRAME BR									
M SUNDRY								40 80.00	
APPLY SEALANT FOR ACCIDENT PORTION									
A 54900099								80.00	
TOP UP AIRCON GAS									
A 54900099								30.00	
CHECK WIRING & ELECTRICAL SYSTEM									
A 10028901								120.00	
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM									
B WHEELALIGNMENT								120.00	
To Conduct Computerize Full Wheel Alignment									
M SUNDRY								20.00	
Sundry									
A 54900099								450.00	
TRANSFER MAIN WIRE & RELAYS (photo)									
M FACE,FR BUMPER BR					1.00	863.00	00.00	863.00	
M EXTENSION,FR BUMPER BR					1.00	517.00	00.00	517.00	
M BRACKET,FR BUMPER SIDE,RH BR					1.00	18.00	00.00	18.00	
M BRACKET,FR BUMPER SIDE,LH BR					1.00	18.00	00.00	18.00	
M GARNISH,FR BUMPER,LH cut (chrome)					1.00	48.00	00.00	48.00	
M BRKT,FR BUMPER SIDE,LWR LH MIS					1.00	6.00	00.00	6.00	
M MOULDING,FR BUMPER,LH MIS					1.00	97.00	00.00	97.00	
M MOULDING,FR WHEEL ARCH,LH MIS					1.00	168.00	00.00	168.00	
M REINFORCEMENT,FR BUMPER BT					1.00	510.00	00.00	510.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
MAZLAN BIN RAKIMAN	Cust No/Name KCV18967/MAZLAN BIN RAKIMAN
640 JURONG WEST STREET 61	Reg No/Reg Date SGS4242J / 26/03/202
#07-16	Date In/Mileage / 0
SINGAPORE 640640	Chassis No GF7W0701101
Contact No	Engine No 4J11DA5541
	Make/Model MIT/2OMY OUTLANDER 2.0 CVT MODERN (
	Colour/Trim U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV18967	CRDVCH	06/09/2021/ 11:07	BLC	442 / CocoLu	14980			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	REINF,F/BMPR SIDE,LWRLH	BT	1.00	25.00	00.00	—	25.00	
M	REINFORCEMENT,FR BUMPER	BT	1.00	135.00	00.00	—	135.00	
M	REINFORCEMENT,FR BMPR SIDE	+nn	1.00	22.00	00.00	—	22.00	
M	REINF,FR BUMPER SIDE,LH	+nn	1.00	60.00	00.00	—	60.00	
M	GRILLE ASSY,RADIATOR	BR	1.00	550.00	00.00	—	550.00	
M	COVER,FR BUMPER	X nn	1.00	25.00	00.00	—	25.00	
M	COVER,HEADLAMP SUPT PANEL	CUT	1.00	50.00	00.00	—	50.00	
M	BRACKET,RADIATOR GRILLE,LH	+nn	1.00	13.00	00.00	—	13.00	
M	REINFORCEMENT,FR BUMPER	+nn	1.00	510.00	00.00	—	510.00	
M	REINF,F/BMPR SIDE,LWRLH	+nn	1.00	25.00	00.00	—	25.00	
M	REINFORCEMENT,FR BUMPER	+nn	1.00	135.00	00.00	—	135.00	
M	REINFORCEMENT,FR BMPR SIDE	+nn	1.00	22.00	00.00	—	22.00	
M	REINF,FR BUMPER SIDE,LH	+nn	1.00	60.00	00.00	— BT	60.00	
M	GRILLE ASSY,RADIATOR	X BR Repeated	1.00	550.00	00.00	—	550.00	
M	COVER,FR BUMPER	X Repeated	1.00	25.00	00.00	—	25.00	
M	COVER,HEADLAMP SUPT PANEL	X Repeated	1.00	50.00	00.00	—	50.00	
M	BRACKET,RADIATOR GRILLE,LH	+nn	1.00	13.00	00.00	—	13.00	
M	HOOD	nn	1.00	980.00	00.00	—	980.00	
M	HINGE,HOOD,RH	BT	1.00	68.00	00.00	—	68.00	
M	HINGE,HOOD,LH	BT	1.00	68.00	00.00	—	68.00	
M	INSULATOR,HOOD	CRU	1.00	133.00	00.00	—	133.00	
M	WEATHERSTRIP,HOOD,RR	+nn	1.00	36.00	00.00	—	36.00	
M	ROD,HOOD SUPPORT	+nn	1.00	24.00	00.00	—	24.00	
M	LATCH,HOOD	+nn	1.00	76.00	00.00	—	76.00	
M	WEATHERSTRIP,HOOD	+nn	1.00	40.00	00.00	—	40.00	
M	WEATHERSTRIP,HOOD	Tn	1.00	41.00	00.00	—	41.00	
M	FENDER,FR LH	nn	1.00	622.00	00.00	—	622.00	
M	INSULATOR,FR FENDER,LH	X BR - TN	1.00	60.00	00.00	—	60.00	
M	SHIELD,FR WHEELHOUSE,LH	BR	1.00	164.00	00.00	—	164.00	
M	CLIP,ENG ROOM COVER	RC	15.00	2.00	00.00	—	30.00	
M	CLIP,RR BUMPER	RC	10.00	3.00	00.00	—	30.00	
M	PANEL,HEADLAMP SUPPORT,UPR	+nn	1.00	183.00	00.00	—	183.00	
M	PNL,HEADLAMP SUPT,UPR LH	BT	1.00	58.00	00.00	—	58.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MAZLAN BIN RAKIMAN	Cust No/Name	KCV18967/MAZLAN BIN RAKIMAN
640 JURONG WEST STREET 61	Reg No/Reg Date	SGS4242J / 26/03/202
#07-16	Date In/Mileage	/ 0
SINGAPORE 640640	Chassis No	GF7W0701101
Contact No	Engine No	4J11DA5541
	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (
	Colour/Trim	U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV18967	CRDVCH	06/09/2021/ 11:07	BLC	442 / CocoLu	14980			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	PANEL, HEADLAMP SUPPORT, LWR				1.00	147.00	00.00	147.00
M	EXTENSION, FR SIDEMEMBER, LH				1.00	58.00	00.00	58.00
M	GARNISH, FR DECK				1.00	173.00	00.00	173.00
M	COVER, FR DECK, LH				1.00	19.00	00.00	19.00
M	HEADLAMP ASSY, LH				1.00	1948.00	00.00	1948.00
M	LAMP ASSY, FOG, FR LH				1.00	350.00	00.00	350.00
M	COVER, RELAY BOX				1.00	52.00	00.00	52.00
M	BOX ASSY, RELAY				1.00	409.00	00.00	409.00
M	CONDENSER ASSY, A/C REFRIGE				1.00	861.00	00.00	861.00
M	RADIATOR ASSY				1.00	1020.00	00.00	1020.00
M	INSULATOR, RDTR SUPPORT, UPR				2.00	9.00	00.00	18.00
M	INSULATOR, RDTR SUPPORT, LWR				2.00	10.00	00.00	20.00

Estimate

Steve CLKK)
6/9/21, 2.10pm

OD - 11/1 AL
Excess - ?
P/P

My Bel Spj
15 ~~12~~ days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to change without prior notice

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Nett	18,403.00
7% GST on	18403.00
Total Payable	19,691.21

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.