



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2200150

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 07/01/2022
Reference CC4/FCI21009333/Gpa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMH 3775G
Insured Veh. SG 5097B
Claim No. D21002454MFBP/1
Policy No. D-20096309MFBP
Accident Date 27/08/2021
Inspection Date 08/09/2021

Description	Total
Survey Inspection	215.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	215.00
GST (7%)	15.05
Grand Total	230.05

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21009333/Gpa3q2	
			Date: 07/01/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SG 5097B	Veh. Inspected	SMH 3775G	
Policy No.	D-20096309MFBP	Coverage (\$)	0.00	
Claim No.	D21002454MFBP/1	Excess (\$)	0.00	
Assign From	RACHEL WU	Assign Date	06/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA NOAH HYBRID 7-SEATER 1.8X	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	ZWR800345375	Colour	BLACK	
Odometer	248996 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	TRIANGLE	6 mm	
L/H Front Tyre	195/65 R15	TRIANGLE	6 mm	
R/H Rear Tyre	195/65 R15	TRIANGLE	6 mm	
L/H Rear Tyre	195/65 R15	TRIANGLE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/08/2021	Inspection Date	08/09/2021	
Survey held at	TRIDENT AUTO SERVICE CENTRE PTE LTD 8 KAKI BUKIT AVENUE 4, #02-42, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			1 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 3775G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	W/MIRROR RH	CRACKED	1,239.40	1,055.30
1	W/MIRROR COVER	NOT NECESSARY	107.00	-
1	W/MIRROR SIGNAL LIGHT	NOT NECESSARY	119.00	-
	LESS 25% DISCOUNT		-366.35	-263.82
			1,099.05	791.48
	<u>LABOUR</u>			
	TO REPLACE W/MIRROR RH TO REPAIR AND RE-ALIGN ON ALL ACCIDENT AFFECTED AREAS .		200.00	100.00
	TO PUTTY AND RESPRAY ON ACCIDENT PORTION .		200.00	100.00
	TO CHECK WIRING .		60.00	20.00
			460.00	220.00
	GRAND TOTAL		1,559.05	1,011.48
RECOMMENDED COST OF REPAIRS				1,011.48

Report Ref No. CC4/FCI21009333/Gpa3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 3775G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 3775G

RE-INSPECTION

