

AH CHANG MOTOR SERVICE CENTRE

Co Reg No: 53188714 J GST Reg No. M90368983C
 Blk 10 Ang Mo Kio Industrial Park 2A, Ang Mo Kio Auto Point #03-16, Singapore 568047
 Tel: (65) 6483 5434 Fax: (65) 6484 2124 HP: 9111 7978
 Email: acm.chang@outlook.com FB: www.facebook.com/AcmServiceCentre

page 1/4


Not Authorised
 11/12/21

Resurvey After Paving
 5-6 days

Car Plate No. **SLH 4303 R**
 Model **Honda Vezel**

Date of Accident : **04-09-2021**Time of Accident : **19.35**Venue : **CTE to City**

No.	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	\$ Bu 1,098.00 ✓
2	1	Rear bumper left retainer	\$ PL 83.00 X
3	1	Rear bumper right retainer	\$ PL 83.00 X
4	1	Rear bumper left side lower panel	\$ NLP 787.00 X
5	1	Rear bumper right side lower panel	\$ NLP 787.00 X
6	1	Rear bumper left reflector	\$ PL 90.00 X
7	1	Rear bumper right reflector	\$ PL 90.00 X
8	1	Rear left side bumper	\$ 355.00 ?
9	1	Rear right side bumper	\$ 355.00 ?
10	1	Rear tailgate assy	\$ PL 1,887.00 ✓
11	1	Rear tailgate outer handle	\$ PL 68.00 X
12	1	Rear tailgate lock	\$ PL 175.00 ✓
13	1	Rear tailgate inner trim board	\$ 476.00 ?
14	1	Rear tailgate weatherstrip	\$ PL 188.00 50% PL
15	2	Rear tailgate damper	\$ PL 276.00 X
16	1	Rear tailgate centre logo	\$ PL 105.00 X
17	1	Rear tailgate vezel emblem	\$ PL 105.00 ✓
18	1	Rear left tailgate taillamp	\$ CM PL 342.00 X
19	1	Rear right tailgate taillamp	\$ CM PL 342.00 ✓
20	1	Rear tailgate outer garnish	\$ 678.00 ?
21	2	Rear no plate lamp	\$ PL 120.00 X
22	1	Rear left taillamp	\$ PL 866.00 X
23	1	Rear right taillamp	\$ PL 866.00 ✓
24	1	Rear left fender inner garnish	\$ PL 475.00 X
25	1	Rear right fender inner garnish	\$ PL 475.00 X
26	1	Rear left fender protector	\$ 197.00 ?
27	1	Rear right fender protector	\$ PL 197.00 X ?



AH CHANG MOTOR SERVICE CENTRE

Co Reg No: 53188714 J

GST Reg No. M90368983C

Blk 10 Ang Mo Kio Industrial Park 2A, Ang Mo Kio Auto Point #03-16, Singapore 568047

Tel: (65) 6483 5434 Fax: (65) 6484 2124 HP: 9111 7978


Email: acm.chang@outlook.com

FB: www.facebook.com/AcmServiceCentre

Car Plate No. **SLH 4303 R**
Model **Honda Vezel**

Date of Accident : **04-09-2021**Time of Accident : **19.35**Venue : **CTE to City**

<u>No.</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Estimated Parts Price</u>	
28	1	Rear sponge tray	\$	198.00 7
29	1	Rear floor panel	\$	<i>12</i> 1,670.00 X
30	1	Rear wiper motor	\$	<i>12</i> 298.00 X
31	1	Rear wiper blade assy	\$	<i>12</i> 166.00 X
32	1	Rear spare tyre top cover	\$	<i>12</i> 218.00 X
33	1	Rear reverse sensor switch	\$	286.00 7
34	1	Rear lower dust cover	\$	280.00 7
35	1	Rear end lower panel	\$	976.00 7
36	1	Rear end lower panel top garnish	\$	<i>cm</i> 185.00 ✓
			\$	15,843.00
		Less 20%	\$	3,168.60
			\$	<u><u>12,674.40</u></u>



AH CHANG MOTOR SERVICE CENTRE

Co Reg No: 53188714 J

GST Reg No. M90368983C

Blk 10 Ang Mo Kio Industrial Park 2A, Ang Mo Kio Auto Point #03-16, Singapore 568047

Tel: (65) 6483 5434 Fax: (65) 6484 2124 HP: 9111 7978

Email: acm.chang@outlook.com


FB: www.facebook.com/AcmServiceCentre

Car Plate No. **SLH 4303 R**
Model **Honda Vezel**

Date of Accident : **04-09-2021**Time of Accident : **19.35**Venue : **CTE to City**

<u>No.</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Estimated Parts Price</u>
<u>Special Nett Items</u>			
1	10	Rear bumper clips	\$ <i>na</i> 50.00 ✓
2	16	Rear tailgate inner trim board clips	\$ <i>na</i> 30.00 ✓
3	6	Rear end lower panel top garnish clips	\$ <i>na</i> 20.00 X
4	1	Rear windscreen glass sealant	\$ <i>na</i> 80.00 <i>Posh</i>
5	6	Rear lower dust cover clips	\$ <i>na</i> 20.00 X
6	8	Rear left fender inner garnish clips	\$ <i>na</i> 30.00 X
7	8	Rear right fender inner garnish clips	\$ <i>na</i> 30.00 X
8	6	Rear left fender protector clips	\$ <i>.</i> 30.00 7
9	6	Rear right fender protector clips	\$ <i>na</i> 30.00 1
10	6	Rear tailgate outer garnish clips	\$ <i>na</i> 30.00 X
11	1	Rear view camera	\$ <i>pu</i> 300.00 X
12	2	Rear bumper reverse sensor	\$ 250.00 7
13	1	Rear no plate with garnish	\$ <i>su</i> 80.00 X
			<u>\$ 980.00</u>

Total Parts \$ **13,654.40**



AH CHANG MOTOR SERVICE CENTRE

Co Reg No: 53188714 J

GST Reg No. M90368983C

Blk 10 Ang Mo Kio Industrial Park 2A, Ang Mo Kio Auto Point #03-16, Singapore 568047

Tel: (65) 6483 5434 Fax: (65) 6484 2124 HP: 9111 7978

Email: acm.chang@outlook.com FB: www.facebook.com/AcmServiceCentre

Car Plate No. **SLH 4303 R**
 Model **Honda Vezel**

Date of Accident : **04-09-2021**Time of Accident : **19.35**Venue : **CTE to City**

<u>No.</u>	<u>Parts Description</u>	<u>Labour Charges</u>
1	Labour for panel beating, cut, weld , straighten rear affected area and replace damage parts	\$ 1,600.00 <i>700</i>
2	To putty & spray painting rear portion	\$ 1,600.00 <i>800</i>
3	To check rear lighting and wiring	\$ 50.00 <i>20</i>
4	To remove and install rear tailgate lock mechanism	\$ 80.00 <i>60</i>
5	To remove and install rear inner trim and garnish to facilitate the repair	\$ 140.00 <i>60</i>
6	To apply anti rust proofing to rear affected area	\$ 140.00 <i>60</i>
7	To remove and install rear bumper reverse sensor	\$ 80.00 <i>50</i>
8	To remove and install rear windscreen glass to facilitate the repair	\$ 140.00 <i>120</i>
9	To remove and install rear view camera	\$ 80.00 <i>40</i>
Total Labour		\$ 3,910.00
Total Parts		\$ 13,654.40
Total Labour		\$ 3,910.00
Total Repair Cost		\$ 17,564.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 06/09/2021 10:54 (SGT)
Date of Accident 04/09/2021 19:35 (SGT)
Exact Location of Accident Singapore
Additional Location Information CTE TO CITY
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLH4303R

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner HAIRANI BINTE SIDEK
NRIC No SXXXX441C
Email Address NANIESIDEK74@GMAIL.COM
Mobile Phone No (Phone) +65-81689852
Alternative Phone No +65-81689852

VEHICLE PARTICULARS

Manufacturer Honda
Model HRV 1.5 LX CVT
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1496


INSURANCE COMPANY

Name of Insurance Company AXA Insurance Pte Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number GA570273/1
Cover Note Number 02/05/2021 - 01/05/2022

DRIVER

Name of Driver HAIRANI BINTE SIDEK
NRIC No SXXXX441C

Date of accident: 4/9/2021 Time: 1935 Location: CTE to City
My Vehicle A: SLH4303R Vehicle B: QBB3902T Vehicle C: QJC1683M
SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

It was raining heavily. I was driving at a speed of 70km/h so I was going to exit at Bt. Timah. As I slow down to stop, suddenly I heard a bang behind my car. I was a little shocked when I realised my car got hit by a lorry from the behind.

VER B: Ramasamy Vasudhasan
G 722 2216 X

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :
Email address :
& myself :
Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

6/9/2021
0605

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

